



Steve Linden

Specialized Vintage Vehicle Services

Consulting • Appraisals • Inspections • Expert Witness • Export

516-524-4102

9 Mobrey Lane • Smithtown, NY 11787

www.stevelinden.com • steve@stevelinden.com

INSPECTION REPORT

© Steven Linden 2000

Owners Name: Aventura Motors
Address: 625 County Road 39A
South Hampton, NY 11968

Prepared for: [REDACTED]
Address: [REDACTED]

Telephone: [REDACTED]

E-mail: [REDACTED]
Telephone: [REDACTED]

Date of Inspection: February 2nd, 2015

Lift Available : Yes X No

Vehicle Test Driven : Yes No X

Photos Taken : Yes X No

Vehicle Manufacturer: BMW

Model: M6

Year: 1987 **VIN:** WBAEE1406H2560190

Plate: N/A

Mileage Per Odometer: 89,733

Engine: 6-Cyl.

Transmission: 5-Speed

Color Ext: Red

Top: N/A

Int: Cream /Gray Leather

Exterior Condition

Front Bumper: Very good. No noted defects.

Grille: Very good. No noted defects.

Hood: Very good. No noted defects.

Right Fender: Very good. No noted defects.

Right Door(s): Very good. No noted defects.

Right ¼ Panel: Very good. No noted defects.

Right Rocker: Very good. No noted defects.

Rear Bumper: Very good. No noted defects.

Trunk Lid: Very good. No noted defects.

Left ¼ Panel: Very good. No noted defects.

Left Door(s): Very good. No noted defects.

Left Rocker: Very good. No noted defects.

Left Fender: Very good. No noted defects.

Roof: Including sunroof. Very good. No noted defects.

Decals / Emblems: Very good. No noted defects.

Glass: Very good. No noted defects. All glass is etched for anti-theft purposes.

Lenses: Very good. No noted defects.

Mirrors: Very good. No noted defects.

Stainless / Chrome Trim: Very good. No noted defects.

Wheels: BBS. Very good. No noted defects. The original wheels are located in the trunk.

Tires: Cooper Zeon 2XS. 90+% tread remaining.

Miscellaneous: None.

Under Hood Condition

Engine: Very good. No noted defects. Aftermarket high-performance ignition wires are present as is a Power-Flo intake kit. The original air-box is in a box on the front passenger floor.

Engine Bay: Very good. No noted defects. No visible major modifications.

Miscellaneous: None.

Interior Condition

Seats: Very good. No noted defects. However, the seating surfaces show the slightest amount of wear and tear that is more a function of age than use.

Dash: Very good. No noted defects.

Gauges: Very good. No noted defects. All function properly and all indicate within proper parameters.

Door Panels: Very good. No noted defects.

Convertible Top (Frame-Pads-Bows-Etc.): N/A.

Interior Of Trunk: Very good. No noted defects. Tool box with tool present (missing spare bulbs), fire extinguisher present. Spare tire (Michelin 220/55/VR15, appears unused), jack and hardware present.

Carpet: Very good. No noted defects.

Console: Very good. No noted defects.

Headliner: Very good. No noted defects.

Miscellaneous: All lights, levers, controls, switches, and accessories function properly. There is an under-dash nit that appears to be a radar detector. I could not verify the proper function of this unit.

Under Vehicle Condition

Chassis: Very good. No noted defects.

Suspension: Very good. No noted defects.

Exhaust: Very good. No noted defects.

Provenance: Connecticut title with no recorded liens. Original Bill of Sale, original Retail Order, original Window Sticker,

Comments: Overall the vehicle presents very well. The fit and finish of body panels is virtually as-new. In fact, it is good enough that my impression was that the vehicle must have been painted at some point, but I can find no signs of this.

This interior presents almost as-new, with the exception of the most minor of wear and tear. Most of this is nothing more than very slight fading of materials which is a function of age rather than use.

The engine bay, trunk, and undercarriage are all in very good condition.

The engine starts easily with no smoke or unusual sounds, and quickly settles into a smooth idle. The shifter shifts smoothly through all of the gears and there are no sounds from the clutch.

The vehicle could not be test-driven due to inclement weather including snow and ice.