CARFAX Report

1997 Mercedes-Benz SL-Class SL 320

92,390 mi | **VIN:** WDBFA63FXVF149786

Convertible | 3.2L I6 F | Gasoline | Rear wheel drive

NO ACCIDENTS REPORTED

No Accidents or Damage Reported to CARFAX

20 Service History Records

5 Previous Owners

Types of Owners: Personal Lease, Personal

Last Owned in California

44 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/27/26 at 3:28:37 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	Oil and filter changed	05/22/2026

This car has been recently serviced. That's a good thing!

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

	Owners 1-3	Owner 4	Owner 5
Total Loss No total loss reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
Structural Damage No structural damage reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated	No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	No Recalls Reported	No Recalls Reported	No Recalls Reported

Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

CARFAX Title History	Owners 1-3	Owner 4	Owner 5
Damage Brands Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon	No Problem	No Problem	No Problem
Odometer Brands Not Actual Mileage | Exceeds Mechanical Limits	No Problem	No Problem	No Problem

CARFAX Ownership History The number of owners is estimated	Owners 1-3	Owner 4	Owner 5
Year purchased	1997	2006	2023
Type of owner	See Details	Personal	Personal
Estimated length of ownership	9 yrs. 6 mo.	10 yrs. 6 mo.	3 yrs. 3 mo.
Owned in the following states/provinces	See Details	California	California
Estimated miles driven per year	See Details	2,335/yr	807/yr
Last reported odometer reading	54,656	88,823	92,390

CARFAX Detailed History

Owner 1
Purchased: 1997

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Lease Vehicle
8,343 mi/yr

Date	Mileage	Source	Comments
03/17/1997	13	California Motor Vehicle Dept.	**Odometer reading reported** -
04/03/1997		California Motor Vehicle Dept.	**Title issued or updated** First owner reported Titled or registered as personal lease vehicle -
08/24/2000	28,322	Auto Auction	**Listed as a fleet vehicle** Vehicle sold Millions of used vehicles are bought and sold at auction every year.
08/25/2000		Service Facility Alameda, CA	**Vehicle serviced**
08/25/2000		California Inspection Station Alameda, CA	**Passed emissions inspection**

Owner 2
Purchased: 2000

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
5,090 mi/yr

Date	Mileage	Source	Comments
08/25/2000	28,325	California Motor Vehicle Dept. Danville, CA	**Odometer reading reported** - - - - -

09/15/2000	28,816	Service Facility	**Vehicle serviced** 7,500 mile service performed Cylinder head replaced Electrical system checked Engine checked Evaporative emission system checked Oil and filter changed Trunk latch replaced
10/17/2000	28,990	Service Facility	**Vehicle serviced** Dash light bulb(s) replaced Electrical system checked Engine/powertrain computer/module checked Fuel system checked Instrument cluster checked Instrument cluster replaced/repaired Oil and filter changed
11/20/2000		California Motor Vehicle Dept. Danville, CA	**Title issued or updated** New owner reported
04/12/2001	31,087	Service Facility	**Vehicle serviced** Front seat cover replaced Oil and filter changed
01/09/2002	34,841	California Inspection Station Palm Desert, CA	**Passed emissions inspection**
02/12/2002	35,038	Mercedes-Benz of Palm Springs Palm Springs, CA 760-328-6525 **4.6 / 5.0** 221 Verified Reviews	**Vehicle serviced** Brakes checked Oil and filter changed
05/24/2002	36,953	Service Facility	**Vehicle serviced** Drivability/performance checked Engine checked Engine/powertrain computer/module checked Fuel injector(s) replaced Fuel pressure checked Oxygen sensor replaced
09/10/2002	38,929	Service Facility	**Vehicle serviced** Brake fluid flushed/changed Cooling system checked Cylinder head gasket(s) replaced Drive belt(s) replaced Four wheel alignment performed Idler arm replaced Oil and filter changed Rear brake pads replaced Rear brake rotor(s) replaced Tire(s) balanced Tires rotated
10/17/2002	39,245	Service Facility	**Vehicle serviced** Battery/charging system checked

Owner 3
Purchased: 2003

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
4,859 mi/yr

Date	Mileage	Source	Comments
02/12/2003	40,329	California Motor Vehicle Dept. Indian Wells, CA	**Title issued or updated** New owner reported
02/02/2004	46,159	California Inspection Station	**Passed emissions inspection**
02/19/2004	46,455	Service Facility	**Vehicle serviced**

02/19/2004		Mercedes-Benz of Palm Springs Palm Springs, CA 760-328-6525 4.6 / 5.0 221 Verified Reviews	**Vehicle serviced** Outside mirror replaced/repaired
06/17/2004	48,882	Service Facility	**Vehicle serviced**
06/17/2004		Mercedes-Benz of Palm Springs Palm Springs, CA 760-328-6525 4.6 / 5.0 221 Verified Reviews	**Vehicle serviced** Engine/powertrain computer/module reprogrammed Shift linkage repaired Transmission checked Valve body replaced
01/23/2006	54,656	California Inspection Station Palm Desert, CA	**Passed emissions inspection**

Owner 4
Purchased: 2006

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
2,335 mi/yr

Date	Mileage	Source	Comments
10/11/2006	57,039	California Motor Vehicle Dept. Sonoma, CA	**Title issued or updated** New owner reported
07/18/2007		Smothers European Santa Rosa, CA 888-438-6505 4.6 / 5.0 170 Verified Reviews 88 Customer Favorites	**Vehicle serviced** Door latch repaired/replaced Oil and filter changed
01/18/2008	62,857	California Inspection Station	**Passed emissions inspection**
04/15/2008		Smothers European Santa Rosa, CA 888-438-6505 4.6 / 5.0 170 Verified Reviews 88 Customer Favorites	**Vehicle serviced**
02/02/2010	69,026	California Inspection Station Sonoma, CA	**Passed emissions inspection**
01/05/2012	74,220	California Inspection Station Palm Desert, CA	**Passed emissions inspection**
01/23/2013	75,351	Mercedes-Benz of Palm Springs Palm Springs, CA 760-328-6525 4.6 / 5.0 221 Verified Reviews	**Vehicle serviced** Recommended maintenance performed 30,000 mile service performed Antifreeze/coolant flushed/changed Battery replaced Brake fluid flushed/changed Brakes serviced Computer(s) checked Oil and filter changed Thermostat replaced Tire condition and pressure checked Vehicle washed/detailed
02/05/2013	75,421	Mercedes-Benz of Palm Springs Palm Springs, CA 760-328-6525 4.6 / 5.0 221 Verified Reviews	**Vehicle serviced** Camshaft position sensor replaced Hood insulator replaced Tire condition and pressure checked Vehicle washed/detailed

02/25/2013	75,695	Mercedes-Benz of Palm Springs Palm Springs, CA 760-328-6525 4.6 / 5.0 221 Verified Reviews	**Vehicle serviced** Tire condition and pressure checked Vehicle washed/detailed -
01/09/2014	76,717	California Inspection Station Indio, CA	**Passed emissions inspection** -
01/21/2016	79,800	California Inspection Station Cathedral City, CA	**Passed emissions inspection** -
04/05/2017	81,492	Mercedes-Benz of Palm Springs Palm Springs, CA 760-328-6525 4.6 / 5.0 221 Verified Reviews	**Vehicle serviced** Oil and filter changed Rear brake pads replaced Tire condition and pressure checked
04/25/2017	81,619	Mercedes-Benz of Palm Springs Palm Springs, CA 760-328-6525 4.6 / 5.0 221 Verified Reviews	**Vehicle serviced** Computer(s) checked Tire condition and pressure checked
04/27/2017	81,685	California Inspection Station Palm Springs, CA	**Passed emissions inspection**
05/05/2017		Dealer Inventory	**Vehicle offered for sale**
07/13/2017		Exotic Motor Cars, Inc. Palm Springs, CA 760-778-5444 4.4 / 5.0 8 Verified Reviews	**Vehicle offered for sale**
02/20/2019	85,987	California Inspection Station Sonoma, CA	**Passed emissions inspection**
02/11/2021	87,206	California Inspection Station Sonoma, CA	**Passed emissions inspection**
03/14/2023	88,823	California Inspection Station Napa, CA	**Passed emissions inspection** -

Owner 5
Purchased: 2023

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
807 mi/yr

Date	Mileage	Source	Comments
03/15/2023		California Motor Vehicle Dept. Sonoma, CA	**Title issued or updated** New owner reported
03/17/2025	91,437	California Inspection Station Costa Mesa, CA	**Passed emissions inspection**
05/22/2026	92,390	Pacific Coast Benz Costa Mesa, CA 714-850-1206	**Vehicle serviced** Oil and filter changed

Have Questions? Please visit our Help Center at www.carfax.com.

CARFAX Glossary

First Owner
When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History
CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued
A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: facebook.com/CARFAX @CARFAXinc About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
6/27/26 3:28:37 PM (CDT)

Invoice

DATE: 5/28/2026

Classic Trim Parts LLC

1083 Delaware Avenue
Buffalo NY 14209

Invoice #: 00011410

Bill To:

839 Oakwood Drive
Sonoma, CA 95476

PAID

Ship To:

83[illegible]
Sonoma, CA 95476

SALESPERSON	PO#	SHIP VIA	DUE DATE	TERMS	PG.
WEBSITE	WEBSITE	USPS	5/28/2026	Prepaid	1

QTY.	ITEM NO.	DESCRIPTION	PRICE	UNIT	DISC %	EXTENDED	TX.
1	CTP-361	Tan 129 CTP Dome Light Cover INCLUDES REBUILDING SERVICE	$195.00	each		$195.00	
1	CTP-310	Dome Light Inner Bracket no	$130.00	each		$130.00	
1	CTP-758L	Dome Light Int Switch Left REBUILT PRICE DISCOUNTED	$25.00	each		$25.00	
1	CTP-758R	Dome Light Int Switch Right REBUILT PRICE DISCOUNTED	$25.00	each		$25.00	

Thank you!

SALE AMT.	$375.00
FREIGHT	$8.00
SALES TAX	$0.00
TOTAL AMT.	$383.00
PAID TODAY	$383.00
BALANCE DUE	$0.00

PACIFIC COAST BENZ
1346 Logan Ave
Ste B
Costa Mesa, CA 92626
(714) 850-1206
service@pacificcoastbenz.com
www.pacificcoastbenz.com
BAR LIC # ARD-259179

PD
✓ 10/29

Invoice #1139

Created: 05/22/2026
Invoiced: 05/22/2026
Payment Term: On Receipt
Payment Due: 05/22/2026

DONN DABNEY
LEFT COAST CLASSICS
Mobile: (707) 332-8331
donn@leftcoastclassics.com

1997 Mercedes-Benz SL320 Base
VIN: WDBFA63FXVF149786
Mileage In: 92,390 mi
Mileage Out: 92,390 mi

Customer Comments

OIL CHANGE SERVICE

REPLACE CLUSTER LIGHT BULBS AS NEEDED

PAID

Recommendations

- Brake pads have 40% remaining front and rear
- tires are in good shape and measure 6.5mm
- replaced two ICD 1.5w bulbs
- strut bushings show some cracks
- sub oil pan "sweating"

OIL CHANGE SERVICE

Description	Price	QTY	HRS	Subtotal
Labor: OIL CHANGE SERVICE			0.3	$75.00
Part: MERCEDES-BENZ ENGINE OIL FULL SYNTHETIC SPEC 229.5 5W-40 000-989-79-02-11-BIFFU *Part #: MOTOR OIL*	$13.00	7.5		$97.50
Part: OEM ENGINE OIL FILTER KIT *Part #: 1041800109*	$15.00	1		$15.00
Part: ICD BULB *Part #: 2452MFX6*	$2.50	2		$5.00

EPA: $7.50 Tax (7.75%): $9.11 **Total: $209.11**

Estimates provided are an approximation of timing and charges to you for the services requested. They are based on the anticipated work to be done. It is possible for unexpected complications to cause some deviation from the original quote. Labor charges are not always based on actual time bur are sometimes established by multiplying our retail labor rate by industry flat rate allowances or by average time based on our experience. You hereby authorize the repair work described in this estimate to be done along with the procurement of the necessary material(s), including permission to operate the vehicle for on-road testing or inspection. If any additional repairs are required, we will prepare a revised work order providing the cost of additional parts and labor and total revised cost. All parts are new unless specified otherwise. Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts.

Labor	$75.00
Parts	$117.50
Subtotal	$192.50
Shop Supplies	$0.00
EPA	$7.50
Tax	$9.11
Grand Total	**$209.11**
Paid to Date	($0.00)
REMAINING BALANCE	**$209.11**

There is no warranty for used parts or customer supplied parts. You agree that we are not responsible for loss or damage to your vehicle, including loss of articles left in the vehicle, including, without limitation, in case of fire, theft, act of God or any other cause(s) beyond our control. We are not responsible for any delays caused by unavailability of parts or delays in delivery of parts by the supplier or transporter. You have the right to know before authorizing any additional repairs what those repairs will be and what they will cost. If required repairs exceed the authorized estimated amount, we must obtain your approval to perform the repairs. We will keep you informed and perform only repairs authorized by you.

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

PACIFIC COAST BENZ
1346 Logan Ave
Ste B
Costa Mesa, CA 92626
(714) 850-1206
service@pacificcoastbenz.com
www.pacificcoastbenz.com
BAR LIC # ARD-259179

Invoice #1139

Created: 05/22/2026
Invoiced: 05/22/2026
Payment Term: On Receipt
Payment Due: 05/22/2026

Signature _____

Authorizations

In Person by DONN DABNEY 5/22/2026 at 10:21 AM PDT	+ OIL CHANGE SERVICE	**$209.11**

Repair Order / Invoice

PACIFIC COAST BENZ
1346 Logan Ave Ste. B
Costa Mesa, Ca 92626
714-850-1206

BAR LIC # ARD-259179

Date	Invoice #
3/21/2025	110738

PAID 03/21/2025

Bill To	Summary
DON DABNEY LEFT COAST CLASSICS 707-332-8331 donn@leftcoastclassics.com	

Make	Model	Year	Miles-In	Miles-Out
MBZ	SL320	1997	91491	91491

Qt	Description	Rate	Item	Amount
	1) BELT IS NOISY, REPLACE BELT			
	2) TURN SIGNALS WONT CANCEL, COMBO SWITCH LOOSE			
1	OEM DRIVE BELT 011-997-21-92	71.00	NON-INVENTORY	71.00T
0.3	REMOVE/REPLACE MAIN DRIVE BELT	225.00	LABOR	67.50
	-			
1.5	REMOVE STEERING WHEEL AND CLOCK SPRING, REPAIR, TIGHTEN STEERING COLUMN PINCH CLAMP SHAFT AND TABS AT COMBO SWITCH, RE-INSTALL IN REVERSE ORDER	225.00	LABOR	337.50
	-			
	CHECK/CORRECT TIRE PRESSURE 33 PSI X 4	0.00	CHECK TIRE PRESS...	0.00
	TECH 1			

Thank you for your business.

Subtotal	$476.00
Sales Tax (7.75%)	$5.50
Total	$481.50
Payments/Credits	-$481.50
Balance Due	$0.00

Additional parts & labor required during repairs are extra. Parts utilized are always new OEM unless noted. Shop not responsible for vehicle damage caused by theft, fire, acts of nature or God. We may operate your vehicle for purpose of testing, inspection & delivery at your risk. We will not be responsible for loss or damage to vehicle or items left in vehicle. Payments for services rendered are due at time of completion. 24 mo/unlimited mile warranty, on all new parts & labor. Labor charges are not always based on actual time but are established by multiplying our retail labor rate by industry flat rate allowances or by average time based on our experience.I agree to all repairs performed and understand the content and terms set forth in this agreement.

SIG._____

Repair Order / Invoice

PACIFIC COAST BENZ
1346 Logan Ave Ste. B
Costa Mesa, Ca 92626
714-850-1206

BAR LIC # ARD-259179

Date	Invoice #
4/4/2023	107974

PAID 04/04/2023

Bill To	Summary
DON DABNEY LEFT COAST CLASSICS 707-332-8331 donn@leftcoastclassics.com	

Make	Model	Year	Miles-In	Miles-Out
MBZ	SL320	1997	88874	88874

Qt	Description	Rate	Item	Amount
	1) LEFT/REAR HYDRAULIC CYLINDER RAM LEAKING..REPLACE ALL W/ TOP HYDRAULICS KIT EST $3000 ** VIN # WDBFA63FXVF149786 **			
1	TOP HYDRAULICS FULL SET + FRONT DISTRIBUTOR HYDRAULIC CYLINDER KIT FOR CONVERTIBLE TOP	1,100.00	NON-INVENTORY	1,100.00T
10	REMOVE/REPLACE ALL HYDRAULIC CYLINDER AND DISTRIBUTOR FOR TOP, REPLENISH HYDRAULIC FLUID, RE-LEARN POSITION OF SOFT TOP, TEST	185.00	LABOR	1,850.00
1	HYDRAULIC FLUID FOR CONVERTIBLE TOP 000 989 91 03 10	15.50	NON-INVENTORY	15.50T
1	CHECK/CORRECT TIRE PRESSURE 36 PSI X 4 - TECH 2	0.00	CHECK TIRE PRESS...	0.00

Thank you for your business.

Subtotal	$2,965.50
Sales Tax (7.75%)	$86.45
Total	$3,051.95
Payments/Credits	-$3,051.95
Balance Due	$0.00

Additional parts & labor required during repairs are extra. Parts utilized are always new OEM unless noted. Shop not responsible for vehicle damage caused by theft, fire, acts of nature or God. We may operate your vehicle for purpose of testing, inspection & delivery at your risk. We will not be responsible for loss or damage to vehicle or items left in vehicle. Payments for services rendered are due at time of completion. 24 mo/unlimited mile warranty, on all new parts & labor. Labor charges are not always based on actual time but are established by multiplying our retail labor rate by industry flat rate allowances or by average time based on our experience.I agree to all repairs performed and understand the content and terms set forth in this agreement.

SIG._____

Napa Smog Test Only
1509 Main Street
Napa, CA. 94559
Phone: 707-224-5566 Fax: 707-224-8216
www.napasmogtestonly.com

INVOICE
58766

ARD 277441
Smog Test Only TC 277441

INVOICE

Date: 03/14/2023

W

1997 Mercedes-Benz - SL320 - 3.2L, In-Line6 (195CI) VIN(Not A
Lic # : KIDLESS
Odometer In : 0

VIN # : WDBFA63FX **VF149786**

Part Description / *Number*	Qty	Sale	Ext	Labor Description	Ext
Certificate *Sc-*	1.00	8.25	8.25	Smog test High Prefomance, Saab, BMW, MINI, Porsche, Mercedes-Benz, Jaguar, Lexus, Landrover, Audi, French, Italian, Mini. Smog test High Prefomance, Corvette, Saab, BMW, Porsche, Mercedes-Benz, Jaguar, Lexus,Landrover, Audi, French, Italian,Mini.	90.00
				Reinspection fee - 31.75+ Cert. (8.25) Good for 30 days	n/c
				[Discount] $15.00 off labor	

Org. Estimate 83.25 Revisions 0.00 Current Estimate 83.25

Labor:	**90.00**
Parts:	**8.25**
Discount:	**-15.00**
SubTotal:	**83.25**
Tax:	**0.00**
Total:	**83.25**
Bal Due:	**$83.25**

[Payments -]

Thank you for letting us provide your smog service

Vehicle Received: 3/14/2023

Customer Number : 27426

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. You will be held responsible for loss or damage to vehicle due to fire, theft, accident, dyno testing or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am soley responsible fo all costs including attorney's fees an court costs. I have read and understand the above and acknowedge receipt of an estimate.

Signature _____ Date _____

Copyright (c) 2023 Mitchell Repair Information Company, LLC invhrs 9.15.17d

www.esp-global.com

Smog Check Vehicle Inspection Report (VIR)

www.autorepair.ca.gov

Vehicle Information

Test Date/Time: 03/14/2023@16:27:22

Model Year:	1997	Make:	MERCEDES-BENZ	Model:	SL320
License:	KIDLESS	State:	CA	VIN:	WDBFA63FXVF149786
Engine Size:	3.20 L	Type:	Passenger Car	Transmission:	Automatic
GVWR:	N/A	Test Weight:	N/A	Cylinders:	6
Odometer:	88,823	Certification:	California	VLT Record #:	27847
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: IR809310

DMV ID Number: 8090R370I456

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Not applicable	Ignition Timing:	Pass	Other Emission Related Components
Not applicable	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Not applicable	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Bypass	Fuel Evaporative Controls Functional		

Idle Emission Test Results

		%CO2	%O2	HC (PPM)			CO (%)			
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
Idle	699	16.0	0.0	100	17	17	1.00	0.00	0.02	Pass
2500 RPM	2430	16.0	0.0	130	12	18	1.00	0.10	0.02	Pass

MAX = Maximum Allowable Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Inspection Station Information

NAPA SMOG
1509 MAIN STREET, NAPA CA, 94559
707-224-5566
Station Number: TC277441

Technician Name/Number: VASQUEZ, CHRISTOPHER/EO636865
Repair Tech Name/Number:
Software Version/EIS Number: 2201 / EP728395

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

MAR 14 2023
Date

Technician's Signature

Repair Order / Invoice

PACIFIC COAST BENZ
1346 Logan Ave Ste. B
Costa Mesa, Ca 92626
(714) 850-1206

8129

BAR LIC # ARD-259179

Date	Invoice #
10/20/2023	108759

Bill To

DON DABNEY
LEFT COAST CLASSICS
707-332-8331
donn@leftcoastclassics.com

Summary

Make	Model	Year	Miles-In	Miles-Out
MBZ	SL500	1997	90623	90624

Qt	Description	Rate	Item	Amount
	1) CHECK ENGINE LIGHT IS ON AND ENGINE RUNS ROUGH ...found ignition coil # 3 to be faulty, spark plugs are worn and have an excessive gap, recommend new plugs and all coils est $650			
3	OEM BOSCH IGNITION COIL 000-158-75-03	80.00	NON-INVENTORY	240.00T
6	NGK IRIDIUM SPARK PLUG 6341	14.00	NON-INVENTORY	84.00T
1.5	TEST + REMOVE/REPLACE ALL SIX SPARK PLUGS AND THREE IGNITION COILS, CLEAR CODES, ROAD TEST	200.00	LABOR	300.00
1	CHECK/CORRECT TIRE PRESSURE 36 PSI X 4 - TECH 2	0.00	CHECK TIRE PRESS...	0.00

Thank you for your business.

Subtotal	$624.00
Sales Tax (7.75%)	$25.11
Total	$649.11
Payments/Credits	$0.00
Balance Due	$649.11

Additional parts & labor required during repairs are extra. Parts utilized are always new OEM unless noted. Shop not responsible for vehicle damage caused by theft, fire, acts of nature or God. We may operate your vehicle for purpose of testing, inspection & delivery at your risk. We will not be responsible for loss or damage to vehicle or items left in vehicle. Payments for services rendered are due at time of completion. 24 mo/unlimited mile warranty, on all new parts & labor. Labor charges are not always based on actual time but are established by multiplying our retail labor rate by industry flat rate allowances or by average time based on our experience.I agree to all repairs performed and understand the content and terms set forth in this agreement.

SIG._____

O'Reilly FIRST CALL

DEDICATED TO THE PROFESSIONAL

Store 2691, 1175 BAKER ST UNIT E26,
COSTA MESA, CA 92626 (714) 662-2005

Invoice	2691-411057
Sale Type	CHARGE SALE
Date	10/13/2023 11:47 AM
Ship Via	
PO Number	

Bill To:

LEFT COAST CLASSICS LLC
.
255 W NAPA ST STE E
SONOMA, CA 95476
(707) 332-8331

97828129

Counter #	Customer Account	Ordered By	Special Instructions
629329	1874281	donn	

Qty	Line	Item Number	Description	Warr	Unit	Tax	List	Net	Extended
1	SSB	49EXTJ	BATTERY	3Y	EA	N	355.92	174.32	174.32
		1997 Mercedes-Benz SL320 L6 3.2L 3199cc GAS MFI 104.991 DOHC							
		49EXTJ	Core Charge		EA	Y		22.00	22.00
		49EXTJ	Core Exchange		EA	Y		-22.00	-22.00
		BATTERY FEE	BATTERY FEE		EA	N	3.39	2.00	2.00

1 Item

Call 866-830-4351 for Super Start National Warranty Information.
This dealer is required by law to charge a nonrefundable $2 California battery fee and a refundable deposit for each lead-acid battery purchased. A credit of the same amount as the refundable deposit will be issued if a used lead-acid battery is returned at the time of purchase or up to 45 days later along with this dealer's receipt.
Ask about our Battery Tester Earnback for alternators, starters & batteries!

Sub-Total	176.32
Sales Tax	15.21
Total	**191.53**

X
Customer Signature

WWW.FIRSTCALLONLINE.COM

Warranty/Garantía: www.firstcallonline.com/warranty

WE APPRECIATE YOUR BUSINESS!

2691WS166 Remit To: PO BOX 9464, SPRINGFIELD, MO 65801-9464

Best Buy Co....
Order Placed

- $198.50

Your payment method .. completes your order.

Seller info

Best Buy Co., Inc.

Transaction ID

O-1WH44535YW5

Speakers

PACIFI

est Buy #854
c FOREST DR
INE, CA 92618

Val:100000-552 99-267645-885497-393018-90849
0854 0 0 2157 04/15/23 12 56
6283672 GX626
JBL GX628 6.5" COAXIAL SPEAKE 84.99
109.99 Was Price
25.00- Sale Discount
Serial # ES3344-JM0097185
Sales Tax 6.60
8801932 STANDARD SP
STANDARD SPEAKER INSTALL 79.99
Sales Tax 0.00
643628 VW-9000
VW AUDI PORSCHE MERCEDES HARN 16.99
Sales Tax 1.31
347333 40-VW10
EUROPEAN FWD ANTENNA ADPT 84- 13.99
Sales Tax 1.08

Subtotal 195.96
Sales Tax 8.99
Total 204.95
USD$ 204.95

**********2977 ChipRead
US DEBIT - DEBIT
DABNEY/DONN W
Approval 001639
Verified By PIN
CARD ENTRY: Chip MODE: Issuer
AID: A0000000980840
Reference Number: 60012562569 79

Other Savings: 25.00
Total Savings: 25.00

Return/Exchange Policy: 15 days on most purchases. Activatable devices have a 14-day return policy (30 days for Verizon activatable devices). For details, go to BestBuy.com/Returns. To learn about privacy practices, go to BestBuy.com/Privacy.

Your Customer Service PIN is:
0854 060 2157 041523

204.95

381.95

ANTON'S EUROPEAN CAR SERVICE

Order Date 08/11/22 05:06 pm
Paid: 08/11/22 05:06 pm

BAR #: AM197428
EPA # CAL000231507
19562 8TH ST EAST
SONOMA, CA 95476
Phone: 707-996-9914 FAX: 707-996-8365

Invoice No.
000020728

Specializing In Fine European Cars

A
8)R.
SONOMA CA 95476

Mobile: 9

97 MercedesBenz SL320 GRAY
88469 Mi.Last in 7/16/2021
Lic: KIDLESS/CA L6Cyl 3.2 Eng
Vin: WDBFA63FXVF149786 01/97
Eq: AT AC PS FI

Quotes
1 08/11/22 12:47pm 200.90
in person.

5-K SERVICE.

5K MB SL 320 104

Labor: $105.00

5,000 MILE SERVICE.
ROAD TEST CAR.

1041800109	OIL FILTER KIT-N	1.0 @	13.00 =$	13.00	
20/50	MOBIL 20/50 OIL-N	7.0 @	7.00 =$	49.00	
HAZ-OIL	HAZARDOUS WASTE OIL-N	1.0 @	0.00 =$	0.00	
SOLVENT	WINDSHIELD SOLVENT-N	1.0 @	6.95 =$	6.95	
SWEPCO-503	FUEL ADDITIVE-N	1.0 @	12.99 =$	12.99	81.94

Job Subtotal: $186.94

Recommendations: BELT TENSIONER NOISY.

Payments to ANTON'S EUROPEAN CAR SERVICE

Status: Paid Work Order

Payments: $200.91
1 08/11/22 200.91 MCard 58843Z

Cost Summary

Labor	105.00
Parts	81.94
Haz Waste	7.00
Subtotal	193.94
Tax	6.97
Total	$200.91
Payments	200.91
Bal Due	0.00

Thank you for choosing ANTON'S EUROPEAN CAR SERVICE

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

ANTON'S EUROPEAN CAR SERVICE

Order Date 07/16/21 01:43 pm
Paid: 07/16/21 01:43 pm

BAR #: AM197428
EPA # CAL000231507
19562 8TH ST EAST
SONOMA, CA 95476
Phone: 707-996-9914 FAX: 707-996-8365

Invoice No.
000019730

8/27/21 2:45 pm
mon 9:30

Specializing In Fine European Cars

SONOMA CA 95476

Mobile:

97 MercedesBenz SL320 GRAY
87614 Mi.Last in 7/9/2021
Lic: KIDLESS/CA L6Cyl 3.2 Eng
Vin: WDBFA63FXVF149786 01/97
Eq: AT AC PS FI

Quotes
1 07/16/21 01:44pm 310.47
in person.

REPLACE TRUNK STRUTS - BAD.
CHECK ALL RUNNING LIGHTS.

TRUNK STRUTS — Labor: $150.00

R&R TRUNK STRUTS - BAD.

1299800664	TRUNK STRUT-N	2.0 @	66.00 =$	132.00	132.00

Job Subtotal: $282.00

CK. ALL RUNNING LIGHTS — Labor: $0.00

REPLACE BOTH LIC. PLATE LIGHT BULBS.

12V1.5W	BULB-N	2.0 @	7.95 =$	15.90	15.90

Job Subtotal: $15.90

Recommendations: BELT TENSIONER NOISY

Payments to ANTON'S EUROPEAN CAR SERVICE

Status: Paid Work Order

Payments: $310.47
1 07/16/21 310.47 MCard 66388Z

Cost Summary

Labor	150.00
Parts	147.90
Subtotal	297.90
Tax	12.57
Total	$310.47
Payments	310.47
Bal Due	0.00

Thank you for choosing ANTON'S EUROPEAN CAR SERVICE

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

TON'S EUROPEAN CAR SERVICE

Order Date 07/09/21 03:50 pm
Paid: 07/09/21 03:50 pm

BAR #: AM197428
EPA # CAL000231507
19562 8TH ST EAST
SONOMA, CA 95476
Phone: 707-996-9914 FAX: 707-996-8365

Invoice No.
000019707

Specializing In Fine European Cars

SONOMA CA 95476

Mobile:

97 MercedesBenz SL320 GRAY
87541 Mi.
Lic: KIDLESS/CA L6Cyl 3.2 Eng
Vin: WDBFA63FXVF149786 01/97
Eq: AT AC PS FI

Quotes
1 07/09/21 10:25am 193.36
I in person.

5,000 MILE SERVICE.
REPLACE SPARE KEY BATTERIES.
ORDER TRUNK SHOCKS.

5K MB E320 104

Labor: $105.00

5,000 MILE SERVICE.
REPLACE SPARE KEY BATTERYS. (USE OWNERS PART)
ROAD TEST CAR.

1041800109	OIL FILTER KIT-N	1.0 @	12.00 =$	12.00	
20/50	MOBIL 20/50 OIL-N	7.0 @	7.00 =$	49.00	
HAZ-OIL	HAZARDOUS WASTE OIL-N	1.0 @	0.00 =$	0.00	
SOLVENT	WINDSHIELD SOLVENT-N	1.0 @	6.00 =$	6.00	
SWEPCO-503	FUEL ADDITIVE-N	1.0 @	7.99 =$	7.99	74.99

Job Subtotal: $179.99

Recommendations: BELT TENSIONER NOISY

Payments to ANTON'S EUROPEAN CAR SERVICE

Status: Paid Work Order

Payments: $193.37
1 07/09/21 193.37 MCard 41146Z

Cost Summary

Labor	105.00
Parts	74.99
Haz Waste	7.00
Subtotal	186.99
Tax	6.38
Total	$193.37
Payments	193.37
Bal Due	0.00

Thank you for choosing ANTON'S EUROPEAN CAR SERVICE

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

ANTON'S EUROPEAN CAR SERVICE

Est Date: 08/27/20 10:15 am

BAR #: AM197428
EPA # CAL000231507
19562 8TH ST EAST
SONOMA, CA 95476
Phone: 707-996-9914 FAX: 707-996-8365

ESTIMATE

Specializing In Fine European Cars

SONOMA CA 95476 Mobile: Work Phone:	97 MercedesBenz SL320 GRAY 86977 Mi. Lic: KIDLESS/CA L6Cyl 3.2 Eng Vin: WDBFA63FXVF149786 01/97 Eq: AT AC PS FI

Quotes
1 08/27/20 01:58pm 186.18
in person.

5,000 MILE SERVICE

5K MB E320 104 — Labor: $98.00

5,000 MILE SERVICE

1041800109	OIL FILTER KIT-N	1.0 @	12.00 =$	12.00	
20/50	MOBIL 20/50 OIL-N	7.0 @	7.00 =$	49.00	
HAZ-OIL	HAZARDOUS WASTE OIL-N	1.0 @	0.00 =$	0.00	
SOLVENT	WINDSHIELD SOLVENT-N	1.0 @	6.00 =$	6.00	
SWEPCO-503	FUEL ADDITIVE-N	1.0 @	7.99 =$	7.99	74.99

Job Subtotal: $172.99

Payments to ANTON'S EUROPEAN CAR SERVICE

Status: Estimate

Payments:

Cost Summary

Labor	98.00
Parts	74.99
Haz Waste	7.00
Subtotal	179.99
Tax	6.19
Total	$186.18
Payments	0.00
Bal Due	186.18

Thank you for choosing ANTON'S EUROPEAN CAR SERVICE

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

ANTON'S EUROPEAN CAR SERVICE

Est Date: 05/07/19 01:19 pm

BAR #: AM197428
EPA # CAL000231507
19562 8TH ST EAST
SONOMA, CA 95476
Phone: 707-996-9914 FAX: 707-996-8365

ESTIMATE

SL 320
1997

Specializing In Fine European Cars

[redacted] SONOMA CA 95476 Mobile: [redacted] Work Phone:	97 MercedesBenz SL320 GRAY 86100 Mi. Lic: KIDLESS/CA L6Cyl 3.2 Eng Vin: WDBFA63FXVF149786 01/97 Eq: AT AC PS FI

Quotes
1 05/07/19 01:23pm 214.71
in person.

5-K SERVICE.

5K MB SL320 - V6 — Labor: $98.00

5,000 MILE SERVICE.

1121800009	OIL FILTER 0001802609-N	1.0 @	25.00 =$	25.00	
20/50	MOBIL 20/50 OIL-N	7.0 @	7.00 =$	49.00	
HAZ-OIL	HAZARDOUS WASTE OIL-N	1.0 @	7.00 =$	7.00	
SOLVENT	WINDSHIELD SOLVENT-N (List 6.00)	1.0 @	6.00 =$	6.00	
SWEPCO-503	FUEL ADDITIVE-N	1.0 @	7.99 =$	7.99	94.99

Job Subtotal: $192.99

Payments to ANTON'S EUROPEAN CAR SERVICE

Status: Estimate

Payments:

Cost Summary

Labor	98.00
Parts	87.99
Non Taxable	7.00
Haz Waste	7.00
Subtotal	199.99
Tax	7.15
Total	$207.14
Payments	0.00
Bal Due	207.14

Thank you for choosing ANTON'S EUROPEAN CAR SERVICE

Th 8:00
8/27/20

Cash!

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

Customer Number: **21033** Invoice No: **303116**

[redacted]

[redacted]

[redacted]2253

Home: Bus: Cell:

Email:

INVOICE

PAGE 1

Mercedes-Benz of Palm Springs

Mercedes-Benz MAYBACH

4095 E. Palm Canyon Drive Palm Springs, CA 92264-5233

(760) 328-6525

BAR REG. # ARD36339 EPA # CAD 981659337

SERVICE ADVISOR: 650 MICHAEL MROFCHAK

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	97	MERCEDES-BENZ SL320	WDBFA63FXVF149786	KIDLESS	81614 81619	T3294

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
17MAR97	28JAN97	16MAR2001	16:00 20APR17		150.00	CASH	19APR17

R.O. OPENED	READY
07:16 17APR17	14:27 19APR17

OPTIONS: DLR:05766 ENG:10499112026386 1)RADIO 61561 2)129063-1F-149786 3)WESTERN GENERAL (800)242-9442 #1100-125653 9-11-04/100K

```
LINE OPCODE TECH TYPE HOURS                                    LIST       NET      TOTAL
A CLIENT REPORTS THE CHECK ENGINE LIGHT IS ON.
     071100 MOTOR CHECK AND ADJUST
            296    CP                                                   180.00     180.00
     071171 SOCKET BOX CONNECT (AFTER READING OUT
            FAULT MEMORY)
            296    CP                                                    45.00      45.00
     071172 INDIVIDUAL COMPONENTS AS PER FAULT
            CODE/COMPLAINT CHECK (AFTER DIAGNOSIS)
            296    CP                                                   195.00     195.00
     478252 REGENERATION SWITCHOVER VALVE FOR
            EVAPORATIVE EMISSION CONTROL SYSTEM REPLACE
            (AFTER CHECK)
            296    CP                                                    45.00      45.00
          1 000-470-87-93 VAVL/FON                              152.32  152.32     152.32
     471690 FUEL HOSE FROM CHARCOAL CANISTER TO TANK
            LINE, REPL.
            296    CP                                                   120.00     120.00
          1 129-476-01-26 HOSE/EAST                              22.10   22.10      22.10
PARTS:      174.42  LABOR:      585.00  OTHER:       0.00  TOTAL LINE A:          759.42
 81619 PERFORMED ENGINE CHECKS. FOUND DTC P0441 PURGING NOT
 OPERATING. PERFORMED DIAGNOSIS AND FOUND PURGE VALVE NOT FUNCTIONING
 AND LEAK IN HOSE FROM CHARCOAL CANISTER TO TANK LINE. REPLACED PURGE
 VALVE AND FUEL HOSE. TEST DROVE VEHICLE AND ENGINE CONTROL MODULE TESTS
 OF PURGING COMPLETED WITHOUT FAULT.
            ***************************************************
B CHECK AND SET TIRE PRESSURES TO THEIR RECOMMENDED TIRE PRESSURE
        RATING PER CARB REGULATIONS. SECTION 95550 TITLE 17.
     PRESSURE CHECK AND SET TIRE PRESSURES TO THEIR
        RECOMMENDED TIRE PRESSURE RATING PER CARB
        REGULATIONS. SECTION 95550 TITLE 17.
            296 I67C                                                                (N/C)
PARTS:        0.00  LABOR:        0.00  OTHER:       0.00  TOTAL LINE B:            0.00
 81619
            ***************************************************
```

I acknowledge notice of an increase of the original estimated price and additional customer or warranty work performed, and or receipt of vehicle.

X_____

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INS/ADJ.	
SALES TAX	
PLEASE PAY THIS AMOUNT	

FOLLOW US ON FACEBOOK

Thank you for choosing Mercedes-Benz of Palm Springs. We greatly appreciate your business. It is our sincere hope that your service experience was a pleasant one, and it is our intention to make your ownership experience one of complete satisfaction. If for any reason you cannot answer the questions in the manufacturer s survey with the highest rating, please contact our Service Manager at (760) 328-6525. Thank you.

Mercedes-Benz

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION IN THE BACK. ***Customer Copy*** **Page 1 of 2**

Customer Number: **21033** Invoice No: **303116**

[redacted]

INVOICE

PAGE 2

Mercedes-Benz of Palm Springs

Mercedes-Benz MAYBACH

4095 E. Palm Canyon Drive Palm Springs, CA 92264-5233

(760) 328-6525

BAR REG. # ARD36339 EPA # CAD 981659337

LA [redacted]2253

Home: **Bus:** **Cell:**

Email: EMAIL|| OM|HOME

SERVICE ADVISOR: **650 MICHAEL MROFCHAK**

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	97	MERCEDES-BENZ SL320	WDBFA63FXVF149786	KIDLESS	81614 81619	T3294

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
17MAR97	28JAN97	16MAR2001	16:00 20APR17		150.00	CASH	19APR17

R.O. OPENED	READY
07:16 17APR17	14:27 19APR17

OPTIONS: DLR:05766 ENG:10499112026386 1)RADIO 61561 2)129063-1F-149786 3)WESTERN GENERAL (800)242-9442 #1100-125653 9-11-04/100K

```
LINE OPCODE TECH TYPE HOURS                                    LIST      NET      TOTAL
C CAR WASH $15.00, PROVIDED FREE OF CHARGE DURING REPAIR OR MAINTENANCE
      VISIT.
    WASH CAR WASH $15.00, PROVIDED FREE OF CHARGE
         DURING REPAIR OR MAINTENANCE VISIT.
            99 I67C                                                                (N/C)
PARTS:        0.00  LABOR:       0.00  OTHER:       0.00   TOTAL LINE C:          0.00
         ***************************************************

EST: 800.00          17APR17 18:22  SA: 650
   CONTACT: RICHARD ARENS                  (415)279-4454
```

This dealership includes a separate charge for the management & disposal of hazardous wastes. These charges are included only on those particular repairs or services which generate hazardous wastes. These charges are calculated periodically and are available on request.

Mercedes-Benz

FOLLOW US ON FACEBOOK

I acknowledge notice of an increase of the original estimated price and additional customer or warranty work performed, and or receipt of vehicle.

X_____

CUSTOMER SIGNATURE

Thank you for choosing Mercedes-Benz of Palm Springs. We greatly appreciate your business. It is our sincere hope that your service experience was a pleasant one, and it is our intention to make your ownership experience one of complete satisfaction. If for any reason you cannot answer the questions in the manufacturer s survey with the highest rating, please contact our Service Manager at (760) 328-6525. Thank you.

DESCRIPTION	TOTALS
LABOR AMOUNT	$ 585.00
PARTS AMOUNT	$ 174.42
GAS, OIL, LUBE	$ 0.00
SUBLET AMOUNT	$ 0.00
MISC. CHARGES	$ 0.00
TOTAL CHARGES	$ 759.42
LESS INS/ADJ.	$ 0.00
SALES TAX	$ 15.26
PLEASE PAY THIS AMOUNT	**$ 774.68**

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION IN THE BACK. ***Customer Copy*** **Page 2 of 2**

Customer Number: **21033** Invoice No: **302441**

INVOICE

PAGE 1

Mercedes-Benz of Palm Springs

Mercedes-Benz MAYBACH

4095 E. Palm Canyon Drive Palm Springs, CA 92264-5233

(760) 328-6525

BAR REG. # ARD36339 EPA # CAD 981659337

LA QUINTA, CA 92253

Home: **Bus:** **Cell:**

Email:

SERVICE ADVISOR: **650 MICHAEL MROFCHAK**

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	97	MERCEDES-BENZ SL320	WDBFA63FXVF149786	KIDLESS	81491 81492	T3064

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
17MAR97	28JAN97	16MAR2001	16:00 30MAR17		150.00	CASH	04APR17

R.O. OPENED	READY
16:48 24MAR17	09:53 04APR17

OPTIONS: DLR:05766 ENG:10499112026386 1)RADIO 61561 2)129063-1F-149786 3)WESTERN GENERAL (800)242-9442 #1100-125653 9-11-04/100K

```
LINE OPCODE TECH TYPE HOURS                                    LIST      NET      TOTAL
A LUBE, OIL & FILTER SERVICE
     0001 LUBE, OIL & FILTER SERVICE
            296   CPC                                                   41.00     41.00
        1 104-180-01-09-10 FILTER ELEMENT                        19.55   16.62     16.62
        1 007603-014106 SEAL RING,VLRUB                           3.61    3.07      3.07
        9 000-989-83-01-USB9 MB OIL 5W-40                         8.39    8.39     75.51
PARTS:      95.20  LABOR:      41.00  OTHER:        0.00  TOTAL LINE A:          136.20
 81492
            ***************************************************
B CLIENT STATES HYDRAULIC OIL LEAKED INSIDE THE CAR AFTER OPERATING THE
       CONVERTIBLE TOP.
     773002 DIAGNOSIS WITH OFFICIAL TEST SCHEDULE
          PERFORM CONTROL AND OPERATING CIRCUIT FOR
          ROADSTERTOP
            296    CP
     770000 R&R BOTH FRONT TOP LATCHES AND REPLACE                                180.00    180.00
          HYDRAULIC CYLINDERS.
            296    CP
        2 129-800-16-72 VACUUM CYLINDER                          239.36  450.00    450.00
        1 000-989-91-03-10 HYDRAULIC FLUID                        21.25  239.36    478.72
     774001 REPLACE RIGHT LATCH FOR UPPER PART OF SOFT                        21.25     21.25
          TOP COMPARTMENT LID
            296    CP
        1 129-800-16-74 LOCK                                     925.75  225.00    225.00
     774178 HYDRAULIC CYLINDERS FOR SOFT TOP                                 925.75    925.75
          COMPARTMENT COVER, LEFT AND RIGHT REPLACE
          (AFTER CHECK)
            296    CP
        1 129-800-20-72 VACUUM CYLINDER                          367.20  360.00    360.00
        1 129-800-20-72 CYLIN/FON                                367.20  367.20    367.20
     678052 REPLACE INNER CENTER COVER ON WINDSHIELD             367.20  367.20    367.20
            296    CP
PARTS:    2160.12  LABOR:    1305.00  OTHER:        0.00  TOTAL LINE B:           90.00     90.00
 81492 PERFORMED TOP FUNCTION TEST CHECK LEAKS. R&R BOTH FRONT TOP                          3465.12
```

Mercedes-Benz

I acknowledge notice of an increase of the original estimated price and additional customer or warranty work performed, and or receipt of vehicle.

X_____

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INS/ADJ.	
SALES TAX	
PLEASE PAY THIS AMOUNT	

FOLLOW US ON FACEBOOK

Thank you for choosing Mercedes-Benz of Palm Springs. We greatly appreciate your business. It is our sincere hope that your service experience was a pleasant one, and it is our intention to make your ownership experience one of complete satisfaction. If for any reason you cannot answer the questions in the manufacturer s survey with the highest rating, please contact our Service Manager at (760) 328-6525. Thank you.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION IN THE BACK. ***Customer Copy*** **Page 1 of 3**

Customer Number: **21033** Invoice No: **302441**

INVOICE

PAGE 2

Mercedes-Benz of Palm Springs

Mercedes-Benz MAYBACH

4095 E. Palm Canyon Drive Palm Springs, CA 92264-5233

(760) 328-6525

BAR REG. # ARD36339 EPA # CAD 981659337

4

LA QUINTA, CA 92253

Home: **Bus:** **Cell:**

Email:

SERVICE ADVISOR: **650 MICHAEL MROFCHAK**

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	97	MERCEDES-BENZ SL320	WDBFA63FXVF149786	KIDLESS	81491 81492	T3064

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
17MAR97	28JAN97	16MAR2001	16:00 30MAR17		150.00	CASH	04APR17

R.O. OPENED	READY
16:48 24MAR17	09:53 04APR17

OPTIONS: DLR:05766 ENG:10499112026386 1)RADIO 61561 2)129063-1F-149786 3)WESTERN GENERAL (800)242-9442 #1100-125653 9-11-04/100K

```
LINE OPCODE TECH TYPE HOURS                                    LIST      NET      TOTAL
 LATCHES AND REPLACED HYDRAULIC CYLINDERS. REPLACED RIGHT TOP
 COMPARTMENT COVER LATCH. REPLACED BOTH COMPARTMENT COVER LIFTING
 CYLINDERS. R&R WINDSHIELD TRIM AND CLEAN OIL.
          ***************************************************
C CHECK AND SET TIRE PRESSURES TO THEIR RECOMMENDED TIRE PRESSURE
       RATING PER CARB REGULATIONS. SECTION 95550 TITLE 17.
    PRESSURE CHECK AND SET TIRE PRESSURES TO THEIR
       RECOMMENDED TIRE PRESSURE RATING PER CARB
       REGULATIONS. SECTION 95550 TITLE 17.
          296 I67C
PARTS:      0.00  LABOR:      0.00  OTHER:      0.00  TOTAL LINE C:      (N/C)
 81492                                                                    0.00
          ***************************************************
D CAR WASH $15.00, PROVIDED FREE OF CHARGE DURING REPAIR OR MAINTENANCE
       VISIT.
    WASH CAR WASH $15.00, PROVIDED FREE OF CHARGE
       DURING REPAIR OR MAINTENANCE VISIT.
          99 I67C
PARTS:      0.00  LABOR:      0.00  OTHER:      0.00  TOTAL LINE D:      (N/C)
                                                                          0.00
          ***************************************************
E** TECH NOTED RIGHT SUNVISOR MIRROR COVER IS BROKEN.
    NC REPLACE RIGHT SUNVISOR MIRROR COVER.
          296   CP
      1 129-811-06-61-8F33 CAP MIRROW MOUNT                     0.00     0.00
      1 129-811-05-61-8F33 CAP/FON                   89.70     89.70     89.70
      1 129-810-23-17-8F30 MIRR/FON                  89.70     89.70     89.70
PARTS:    389.32  LABOR:      0.00  OTHER:      0.00  TOTAL LINE E:     209.92
 81492                                                                   389.32
          ***************************************************
F** REPLACE REAR BRAKE PADS
    4202 REPLACE REAR BRAKE PADS
          296   CP
      1 004-420-92-20-41 PADS/FON                   150.00    150.00
      1 140-540-12-17 BRAKE WEAR SENSOR     106.26  106.26    106.26
                                             12.00   12.00     12.00
```

I acknowledge notice of an increase of the original estimated price and additional customer or warranty work performed, and or receipt of vehicle.

X_____

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INS/ADJ.	
SALES TAX	
PLEASE PAY THIS AMOUNT	

FOLLOW US ON FACEBOOK

Thank you for choosing Mercedes-Benz of Palm Springs. We greatly appreciate your business. It is our sincere hope that your service experience was a pleasant one, and it is our intention to make your ownership experience one of complete satisfaction. If for any reason you cannot answer the questions in the manufacturer s survey with the highest rating, please contact our Service Manager at (760) 328-6525. Thank you.

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION IN THE BACK. ***Customer Copy*** **Page 2 of 3**

Customer Number: **21033** Invoice No: **302441**

INVOICE

PAGE 3

Mercedes-Benz of Palm Springs

Mercedes-Benz MAYBACH

4095 E. Palm Canyon Drive Palm Springs, CA 92264-5233

(760) 328-6525

BAR REG. # ARD36339 EPA # CAD 981659337

LA QUINTA, CA 92253

Home: **Bus:** **Cell:**

Email: EMAIL| VIE

SERVICE ADVISOR: **650 MICHAEL MROFCHAK**

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	97	MERCEDES-BENZ SL320	WDBFA63FXVF149786	KIDLESS	81491 81492	T3064

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
17MAR97	28JAN97	16MAR2001	16:00 30MAR17		150.00	CASH	04APR17

R.O. OPENED	READY
16:48 24MAR17	09:53 04APR17

OPTIONS: DLR:05766 ENG:10499112026386 1)RADIO 61561 2)129063-1F-149786 3)WESTERN GENERAL (800)242-9442 #1100-125653 9-11-04/100K

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	245-125	VOC	BR.CLEAN		14.60	14.60	14.60
1	001-989-94-51-12		BRAKE PASTE		18.50	18.50	18.50

PARTS: 151.36 LABOR: 150.00 OTHER: 0.00 TOTAL LINE F: 301.36

81492

****

EST: 3,260.00 28MAR17 07:56 SA: 650

CONTACT: MR ARENS (415)279-4454

This dealership includes a separate charge for the management & disposal of hazardous wastes. These charges are included only on those particular repairs or services which generate hazardous wastes. These charges are calculated periodically and are available on request.

Mercedes-Benz

FOLLOW US ON FACEBOOK

I acknowledge notice of an increase of the original estimated price and additional customer or warranty work performed, and or receipt of vehicle.

X_____ CUSTOMER SIGNATURE

Thank you for choosing Mercedes-Benz of Palm Springs. We greatly appreciate your business. It is our sincere hope that your service experience was a pleasant one, and it is our intention to make your ownership experience one of complete satisfaction. If for any reason you cannot answer the questions in the manufacturer s survey with the highest rating, please contact our Service Manager at (760) 328-6525. Thank you.

DESCRIPTION	TOTALS
LABOR AMOUNT	$ 1496.00
PARTS AMOUNT	$ 2796.00
GAS, OIL, LUBE	$ 0.00
SUBLET AMOUNT	$ 0.00
MISC. CHARGES	$ 0.00
TOTAL CHARGES	$ 4292.00
LESS INS/ADJ.	$ 0.00
SALES TAX	$ 244.65
PLEASE PAY THIS AMOUNT	**$ 4536.65**

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION IN THE BACK. ***Customer Copy*** **Page 3 of 3**

[redacted]
[redacted] T
SONOMA, CA 95476
HOME: [redacted] BUS: CELL: [redacted]
EMAIL:

Invoice #: 123090
Tag #: T2166
Customer #: 711496
Service Advisor: 101 NICK STAUER

Smothers EUROPEAN
2880 TALMADGE DR.
SANTA ROSA, CA 95407
(707) 542-4811
BAR# RG 223139
EPA# CAL 000250231
Mercedes-Benz

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
	97	MERCEDES SL320R/95	WDBFA63FXVF 149786		61431	61431

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
17MAR97			17:00 03JUL07			CASH	18JUL07	11:53 03JUL07	09:13 18JUL07

OPTIONS: ENG:195 CU IN - 3199 CC

		LIST	NET	TOTAL
1	129-758-08-98 SEAL TRUNK	10.29	10.29	10.29
1	129-820-04-11 INF RECIEVER	236.00	236.00	236.00
1	129-800-27-75 ELEMENT	61.25	61.25	61.25

LABOR: 250.00 **PARTS:** 709.24 **OTHER:** 0.00 **TOTAL LINE C:** $ 959.24

,,,,61431 VERIFIED CONCERN, REMOVED KEY LOCK TO INSPECT. FOUND FAULTY
,,,,INFARED RECIEVER. ALSO FOUND LATCH BREAKING WHERE VACUUM LINE. REPLACED
,,,,LATCH, AND INFARED RECIEVER AS NEEDED. FOUND WORKING AS DESIGNED AT
,,,,THIS TIME.

****

EST: 375.00 03JUL07 11:53 SA: 101
CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER
AUTH RICH 7.6 3PM FOR LATCHES,
INFARED AND FRON T LATCH TOTAL
2986.29 9353644

5.00

Mercedes-Benz

PAID BY CREDIT CARD

Thank You!

Customer Copy

Original Estimate $ _____
Please read the important information on the reverse side of invoice.
_____ I acknowledge receipt of this invoice.
_____ I acknowledge the warranty repairs performed.
_____ I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.
Signature X_____

I acknowledge notice and oral approval of an increase in the original estimated price.
_____ Initals

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item\items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

NOTICE TO CUSTOMERS
WE MAKE A SEPERATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL 000077883
RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES.
THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY
It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

DESCRIPTION	TOTALS
LABOR AMOUNT	1062.50
PARTS AMOUNT	1800.49
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	5.00
TOTAL CHARGES	2867.99
ADJUSTMENTS	0.00
SALES TAX	144.04
PLEASE PAY THIS AMOUNT	3012.03

APPOINTMENTS: (707) 524-4811

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

THANK YOU!

Invoice #: 123090
Tag #: T2166
Customer #: 711496
Service Advisor: 101 NICK STAUER

Smothers EUROPEAN
2880 TALMADGE DR.
SANTA ROSA, CA 95407
(707) 542-4811
BAR# RG 223139
EPA# CAL 000250231
Mercedes-Benz

SONOMA, CA 95476
HOME:
BUS:
CELL:
EMAIL:

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
	97	MERCEDES SL320R/95	WDBFA63FXVF 149786		61431	61431

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
17MAR97			17:00 03JUL07			CASH	18JUL07	11:53 03JUL07	09:13 18JUL07

OPTIONS: ENG:195 CU IN - 3199 CC

RICH ARENS

Smothers European Would Like To Thank You For Your Continued Patronage

Thank You!

		LIST	NET	TOTAL
A	**CUST STATES TOP WONT COME UP CK AND ADVISE**			
	00 SERVICE			
	67 CM			
1	129-800-17-74 SOFT TOP LOCK			750.00
1	129-800-08-74 ROOF LOCK	588.30	588.30	588.30
	00 SERVICE	460.00	460.00	460.00
	90 IM			
	LABOR: 750.00 **PARTS:** 1048.30 **OTHER:** 0.00 **TOTAL LINE A:**			(N/C) $ 1798.30
	,,,,61431 VERIFIED CONCERN, PERFORMED SHORT TEST. FOUNC CODES FOR			
	,,,,IMPLAUSABLE SWITCHES. USING ACTUAL VALUES FOUND RIGHT REAR TOP SWITCH			
	,,,,NOT READINGF CORRECTLY WHEN TOP UP. UPON INSPECTION FOUND LATCH FALLING			
	,,,,APART. REPLACED LATCH AS NEEDED. AFTER REPAIR FOUND RIGHT FRONT TOP			
	,,,,LATCH LEAKIN G FLUID. REPLACED AS NEEDED. FOUND WORKING AS DESIGNED AT			
	,,,,THIS TIME.			
	**********			
B	**LUBE,OIL AND FILTER SERVICE**			
	LOF LUBE,OIL AND FILTER SERVICE			
	67 CM			
1	104-180-01-09 OIL FILTER	18.57	18.57	62.50
1	007603-014106 RING	0.72	0.72	18.57
7	2050 CASTROL20/50	3.38	3.38	0.72
	LABOR: 62.50 **PARTS:** 42.95 **OTHER:** 0.00 **TOTAL LINE B:**			23.66 $ 105.45
	,,,,61431 PERFOMRED LOF AS NEEDED			
	**********			
C	**CUST STATES WHEN USING REMOTE AT BACK OF VEHICLE IS INOP, LIGHTS ON DISPLAY WONT COME ON CK AND ADVISE**			
	00 REAR LATCH			
	67 CM			
1	129-750-36-91 TRUCKLOCK	401.70	401.70	250.00 401.70

Mercedes-Benz
Customer Copy

Original Estimate $ _____
Please read the important information on the reverse side of invoice.
_____ I acknowledge receipt of this invoice.
_____ I acknowledge the warranty repairs performed.
_____ I acknowledge notice and oral approval of additional Warranty repairs discovered and corrected during this repair visit.
Signature X_____

I acknowledge notice and oral approval of an increase in the original estimated price.
_____ Initals

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item\items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

NOTICE TO CUSTOMERS
WE MAKE A SEPERATE CHARGE FOR THE DISPOSAL OF TOXIC WASTES. CAL 000077883
RATHER THAN RECOVER THESE COSTS BY INCREASING OUR LABOR RATES TO ALL OF OUR SERVICE CUSTOMERS, WE MAKE THIS CHARGE ONLY ON THOSE PARTICULAR REPAIRS OR SERVICES WHICH GENERATE THESE WASTES.
THESE ARE UNIFORM CHARGES WHICH ARE CALCULATED ANNUALLY FOR EACH PARTICULAR SERVICE AND ARE AVAILABLE UPON REQUEST.

SMOTHERS EUROPEAN CUSTOMER SATISFACTION POLICY
It is our intention to make service the number one priority at Smothers European. If there is any suggestion you can make to provide a better Service Department, please let us know. By law, you may choose another facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
ADJUSTMENTS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

APPOINTMENTS: (707) 524-4811

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

THANK YOU!

CUSTOMER COPY

34392

528728

INVOICE

MERCEDES BENZ OF WALNUT CREEK
1301 PARKSIDE DRIVE
WALNUT CREEK, CA 94596
(925) 937-1655

DANVILLE, CA 94506-2153
HOME: 1 BUS:

PAGE 1

SERVICE ADVISOR: 50 BRIAN POPE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
	97	MERCEDES SL320	WDBFA63FXVF149786	MKSMIDY	57640/57641	T866.

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
01JAN00 IS 01JAN00 DD	01JAN00	01JAN2004	17:00 21OCT06	0.00	CASH	24OCT06

R.O. OPENED	READY	OPTIONS:
16:45 20OCT06	09:08 24OCT06	ENG:195_CU_IN_-_3199_CC

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A FIX DENT IN PASS RF DOOR			
00 GENERAL INSPECTION PER CLIENTS REQUEST			
65 CC		0.00	0.00
MISC DENT WIZ			
PO#5423			
CC		100.00	100.00
PARTS: 0.00 LABOR: 0.00 OTHER: 100.00 TOTAL LINE A:			100.00
57641			
**********			
B CUSTOMER REQUEST OIL AND FILTER CHANGE WITH MULTI POINT VISUAL INSPECTION			
Q CUSTOMER REQUEST OIL AND FILTER CHANGE WITH MULTI POINT VISUAL INSPECTION			
65 CQ		30.00	30.00
1 104-180-01-09-28 FILTER ELEM	10.50	0.00	0.00
1 007603-014106 RING,GENERAL	0.70	0.00	0.00
8 Q-1-09-0053 DELVAC 1300	3.50	0.00	0.00
1 OFS HAZARDOUS WASTE	1.51	1.51	1.51
1 OFC	29.95	29.95	29.95
PARTS: 31.46 LABOR: 30.00 OTHER: 0.00 TOTAL LINE B:			61.46
57640 T .50 PERF OIL & FILTER CHANGE W/INSPECTION. BRAKES 50% REMAINING-OK, TIRES 9/32-OK. A FEW VERY MINOR OIL LEAKS- REC NO REPAIR YET. V-BELT IS DRY- REC REPL TODAY.			
**********			
C REMOTES DO NOT FUNCTION			
80 * INSPECT CENTRAL LOCKING SYSTEM AND ADVISE			
65 CC		14.00	14.00
2 000-828-03-88 BATTERY (2PK	18.85	18.85	37.70
PARTS: 37.70 LABOR: 14.00 OTHER: 0.00 TOTAL LINE C:			51.70
57640 T .10 REPL BATTERIES IN 2 REMOTE KEYS. BOTH WORK NOW. NOTE: 1 OF THE REMOTES IS STARTING TO COME APART, BUT IT STILL WORKS.			

CHARGE
AC# MC
OCT 25 2006
MERCEDES BENZ OF WALNUT CREEK

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item\items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES/ADJ.	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

BAR# *EPA#*

CUSTOMER COPY

34392

528728

INVOICE

MERCEDES BENZ OF WALNUT CREEK
1301 PARKSIDE DRIVE
WALNUT CREEK, CA 94596
(925) 937-1655

DANVILLE, CA 94506-2153

HOME: BUS:

SERVICE ADVISOR: 50 BRIAN POPE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
	97	MERCEDES SL320	WDBFA63FXVF149786	MKSMIDY	57640/57641	T866.

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
01JAN00 IS 01JAN00 DD	01JAN00	01JAN2004	17:00 21OCT06	0.00	CASH	24OCT06

R.O. OPENED	READY	OPTIONS:
16:45 20OCT06	09:08 24OCT06	ENG:195_CU_IN_-_3199_CC

```
LINE OPCODE TECH TYPE HOURS                                  LIST      NET     TOTAL
D REAR VIEW MIRROR LOOSE
    88 DETACH PANEL & INSPECT
            65   CC                                                    0.00      0.00
PARTS:      0.00  LABOR:      0.00  OTHER:      0.00  TOTAL LINE D:            0.00

57640 T 0.00 INSPECT INSIDE REAR VIEW MIRROR. THE PIVOT SOCKET INSIDE
THE MIRROR IS CRACKED- WILL NEED NEW MIRROR.
          ****************************************************
E REPLACE WIPER REFILLS
    WW * REPLACE WIPER BLADE(S)
            65   CC                                                   14.00     14.00
        1 000-824-36-27-01 WINDSHIELD W                   13.24      13.24     13.24
PARTS:     13.24  LABOR:     14.00  OTHER:      0.00  TOTAL LINE E:           27.24

57640 T .10 REPL WIPER REFILL.
          ****************************************************
F** REPLACE CRACKED DRIVE BELT
    13 DRIVE BELT INSPECTION OR R&R
            65   CC                                                  140.00    140.00
        1 011-997-21-92 V-BELT                            60.75      60.75     60.75
PARTS:     60.75  LABOR:    140.00  OTHER:      0.00  TOTAL LINE F:          200.75

57641 T 1.00 REPL POLY V BELT
          ****************************************************

  EST: 500.00          20OCT06  16:45  SA: 50

                                   BAR AL242307 SMOG RL242307 EPA CAL000300337
```

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item\items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

DESCRIPTION	TOTALS
LABOR AMOUNT	198.00
PARTS AMOUNT	143.15
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES/ADJ.	100.00
TOTAL CHARGES	441.15
LESS INSURANCE	0.00
SALES TAX	11.68
PLEASE PAY THIS AMOUNT	452.83

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

BAR# *EPA#*

094082

283513

INVOICE

Stead MOTORS of Walnut Creek
1301 Parkside Drive
Walnut Creek, CA 94596
(925) 937-1655

[redacted]
[redacted]E
DANVILLE, CA 94506
HOME: [redacted] BUS: [redacted]2

PAGE 1

SERVICE ADVISOR: 552 PHILIP TORRES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
721/265	97	MERCEDES-BENZ SL320R	WDBFA63FXVF149786	KIDLESS	38928/38929	T8690

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
17MAR1997	28JAN97	19MAR2001	16:30 06SEP02		CASH	09SEP2002

R.O. OPENED	READY	OPTIONS:
07:30 03SEP02	13:13 09SEP02	DLR:05766 ENG:195_CU_IN_-_3199_CC

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A CUST STATES - ROTATE BALANCE AND ALIGN			
46 ALIGN FRONT AND REAR, ROTATED AND BALANCED TIRES			
158 C		231.00	231.00
38929 REQUESTED ALIGN,ROTATE AND BALANCE ALIGNED FRT AND REAR,ROTATED AND BALANCED TIRES NEEDS IDLER ARM BUSHINGS			
**********			
B QUICK SERVICE OIL AND FILTER CHANGE			
Q QUICK SERVICE OIL AND FILTER CHANGE			
582 C		20.00	20.00
1 OIL-FILTER-KIT SPECIAL	19.95	19.95	19.95
00 * GENERAL SERVICING			
582 IPD			(N/C)
1 104-180-01-09 FILTER ELEME			(N/C)
1 007603-014106 RING,GENERAL			(N/C)
8 ENGOIL00250 15W40			(N/C)
38928 OIL AND FILTER WATER PUMP SEEPIONG COOLANT.HEAD GASKET MINOR OIL LEAK.BELT CRACKED.RECOMMEND BRAKE FLUID FLUSH			
**********			
C REPLACE WIPERS .			
88 CHANGED WIPER			
582 C		0.00	0.00
1 000-824-36-27-01 WINDSHIELD W	10.58	10.58	10.58
38928 CHANGED WIPER			
**********			
D** CUST STATES - REPLACE REAR PADS AND REAR ROTORS			
42 REPLACED REAR BRAKE PADS AND ROTORS			
582 C		176.00	176.00
2 129-423-04-12 BRAKE DISC	112.00	112.00	224.00
1 003-420-49-20 BRAKE SHOE	80.58	80.58	80.58
1 AD-89 ANTI SQ	9.95	9.95	9.95
1 001-989-10-51 PASTE FOR BR	1.06	1.06	1.06
1 140-540-12-17 SENDER UNIT,	3.38	3.38	3.38
38928 WORN OUT REAR BRAKE PADS AND ROTORS REPLACED REAR BRAKE PADS AND			

Original Estimate $

Please read the important information on the reverse side invoice!

I acknowledge receipt of this invoice.

☐ I acknowledge the warranty repairs performed.

☐ I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.

Signature X _____

I acknowledge notice and oral approval of an increase in the original estimate price.

Initials X _____

Stead MOTORS
of Walnut Creek
1301 Parkside Drive
Walnut Creek, California 94596
(925) 937-1655

BAR #AB-005446 EPA #CAD981418726

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INS / ADJ	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

094082

283513

INVOICE

Stead MOTORS of Walnut Creek
1301 Parkside Drive
Walnut Creek, CA 94596
(925) 937-1655

[redacted]
DANVILLE, CA 94506
HOME: [redacted] BUS: [redacted]

PAGE 2

SERVICE ADVISOR: 552 PHILIP TORRES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
721/265	97	MERCEDES-BENZ SL320R	WDBFA63FXVF149786	KIDLESS	38928/38929	T8690

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
17MAR1997	28JAN97	19MAR2001	16:30 06SEP02		CASH	09SEP2002

R.O. OPENED	READY
07:30 03SEP02	13:13 09SEP02

OPTIONS: DLR:05766 ENG:195_CU_IN_-_3199_CC

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
ROTORS			
**********			
E** CUST STATES - REPLACE DRIVE BELT			
VB REPL V-BELT			
582 C		110.00	110.00
1 011-997-21-92 V-BELT	42.56	42.56	42.56
38929 CRACKED BELT REPLACED DRIVE BELT AND CHECKED TENSION			
**********			
F** * BRAKE FLUID CHANGE			
BFC * BRAKE FLUID CHANGE			
582 C		59.40	59.40
1 BKFLUID01000 BRAKEFLUID	13.95	13.95	13.95
38928 DIRTY BRAKE FLYUID FLUSHED OUT BRAKE FLUID			
**********			
G** REPLACE IDLER ARM BUSHINGS (SEE EXTENDED WARRANTY OK'S)			
32 REPLACED IDLER ARM BUSHINGS			
158 C		319.00	319.00
1 129-460-00-19 STEERNG ARM	64.96	64.96	64.96
38929 PLAY IN IDLER ARM REPLACED IDLER ARM BUSHINGS **********			
WESTERN GENERAL EXTRENDED WARRANTY OK'D AMOUNT OF $367.29 /AUTHO #C 936997.			
**********			
H** REPLACE HEADGASKET			
01 *ENGINE/CYL HEAD WORK			
582 C		1078.00	1078.00
1 104-010-37-20 CYLINDER HEA	115.50	115.50	115.50
1 104-010-21-30 CYL HEAD COV	62.72	62.72	62.72
1 017-997-16-48 SEAL RING.OI	1.88	1.88	1.88
1 012-997-51-48 SEAL RING.WA	1.25	1.25	1.25
1 002-989-73-20-10 SEALING COMP	14.39	14.39	14.39
3 7481 2" DISC	4.50	4.50	13.50
1 0038 CLEANER	15.95	15.95	15.95
1 104-016-03-38 SCREW	0.98	0.98	0.98
6 6203 CABLE TIE	0.95	0.95	5.70

Original Estimate $

Please read the important information on the reverse side invoice!

I acknowledge receipt of this invoice.

☐ I acknowledge the warranty repairs performed.

☐ I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.

Signature X _____

I acknowledge notice and oral approval of an increase in the original estimate price.

Initials X _____

Stead MOTORS
of Walnut Creek
1301 Parkside Drive
Walnut Creek, California 94596
(925) 937-1655
BAR #AB-005446 EPA #CAD981418726

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INS / ADJ	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

094082

283513

INVOICE

Stead MOTORS of Walnut Creek
1301 Parkside Drive
Walnut Creek, CA 94596
(925) 937-1655

DANVILLE, CA 94506
HOME: BUS:

PAGE 3

SERVICE ADVISOR: 552 PHILIP TORRES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
721/265	97	MERCEDES-BENZ SL320R	WDBFA63FXVF149786	KIDLESS	38928/38929	T8690

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
17MAR1997	28JAN97	19MAR2001	16:30 06SEP02		CASH	09SEP2002

R.O. OPENED	READY	OPTIONS:
07:30 03SEP02	13:13 09SEP02	DLR:05766 ENG:195_CU_IN_-_3199_CC

```
LINE OPCODE TECH TYPE HOURS                                   LIST      NET     TOTAL
38929 LEAKING HEAD GASKET REPLACED HEAD GASKET AND STEAM CLEANED AREA
**********************\ WESTERN GENERAL FIREMANS FUND EXTENDED
WARRANTY HEADGASKET OPERATIONS OK'D $1,129.28 /$100.00 DEDUCTABLE
/AUTHO # C936994 .
          ******************************************************
I** REPLACE WATER PUMP ( SEE EXT WRNTY OK'S)
    20 *ENG COOLING SYSTEM
          582    C                                                 638.00   638.00
     1 104-200-57-01 WATER PUMP                            266.00   266.00   266.00
     1 110-200-05-15 COOLING WATE                           27.06    27.06    27.06
     1 Q-1-03-0002 ANTI-FREEEZE                             14.81    14.81    14.81
38929 LEAKING WATER PUMP REPLACED WATER PUMP ************************
WESTERN GENERAL FIREMANS FUNBD EXTENDED WARRANT Y WATER PUMP OPERATION
COVERED AMOUNT $912.98 / AUTHO #C937461.
          ******************************************************

  EST: 55.00          03SEP02  07:30  SA: 552
```

CHARGE
AC# VISA
SEP 09 2002
STEAD MOTORS
OF WALNUT CREEK

3725
L1315
A2410 pd warranty
paid

Original Estimate $

Please read the important information on the reverse side invoice!
I acknowledge receipt of this invoice.
☐ I acknowledge the warranty repairs performed.
☐ I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.
Signature X _____
I acknowledge notice and oral approval of an increase in the original estimate price.
Initials X _____

Stead MOTORS
of Walnut Creek
1301 Parkside Drive
Walnut Creek, California 94596
(925) 937-1655
BAR #AB-005446 EPA #CAD981418726

DESCRIPTION	TOTALS
LABOR AMOUNT	2631.40
PARTS AMOUNT	1010.71
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	3642.11
LESS INS / ADJ	0.00
SALES TAX	83.38
PLEASE PAY THIS AMOUNT	3725.49

CUSTOMER COPY

21033

117447

INVOICE

Mercedes-Benz of Palm Springs

The only authorized Mercedes-Benz Retail Center in the Coachella Valley

4095 E. Palm Canyon Drive Palm Springs, CA 92264-5233

(760) 328-6525

PAGE 1

BAR REG. # AJ036339 EPA # CAD 981659337

WEBD

HOME: BUS:

SERVICE ADVISOR: 360 CHRISTIAN WILLIAMS

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	97	MERCEDES-BENZ SL320	WDBFA63FXVF149786		35037/35038	T388

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
17MAR1997	28JAN97	16MAR2001	16:00 12FEB02		80.00	CASH	12FEB2002

R.O. OPENED	READY	OPTIONS:
15:50 11FEB02	10:28 12FEB02	DLR:05766 ENG:10499112026386 1)RADIO 61561 2)SERIAL T09703305 3)10499112026386 4)129063-1F-149786

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A LUBE, OIL & FILTER SERVICE. (DOES NOT INCLUDE SALES TAX OR HAZARDOUS MATERIAL DISPOSAL FEE)			
0001 LUBE, OIL & FILTER SERVICE. (DOES NOT INCLUDE SALES TAX OR HAZARDOUS MATERIAL DISPOSAL FEE)			
388 CPC 0.80		42.25	42.25
1 104-180-01-09 FILTER ELEME	11.90	11.90	11.90
1 24400 OIL CHRG	9.80	7.00	7.00
1 007603-014106 RING,GENERAL	1.10	1.10	1.10
HAZOF HAZARDOUS MATERIAL MANAGEMENT AND DISPOSAL CHARGE FOR USED ENGINE OIL AND OIL FILTER. (SEE MESSAGE AT THE END OF THIS INVOICE)			
388 CHAZ 0.00		2.75	2.75
PARTS: 20.00 LABOR: 45.00 OTHER: 0.00 TOTAL LINE A:			65.00
**********			
B CHECK BRAKES AND ADVISE			
NC CHECKED BRAKES (OK).			
388 CP 0.00		0.00	0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B:			0.00
**********			
C CHECK ALL HEAT SHIELDS, A RATTLE CAN BE HEARD WHEN PULLING INTO GARAGE			
NC CHECKED HEAT SHIELDS (OK).			
388 CP 0.00		0.00	0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C:			0.00
**********			

SERVICE DEPARTMENT HOURS

MONDAY - FRIDAY
7:30 AM - 5:30 PM

FOR APPOINTMENT CALL
MONDAY - FRIDAY
9:00 AM - 5:00 PM

ORIGINAL ESTIMATE $

TOTAL REVISED ESTIMATE $

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.

CUST. SIGN. X

I ALSO ACKNOWLEDGE ANY OR ALL WARRANTY WORK AS STATED ON THIS REPAIR ORDER AND OR RECEIPT OF THIS VEHICLE.

CUST. SIGN. X

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CLIENT COPY

21033

117447

INVOICE

Mercedes-Benz of Palm Springs

The only authorized Mercedes-Benz Retail Center in the Coachella Valley

4095 E. Palm Canyon Drive Palm Springs, CA 92264-5233

(760) 328-6525

BAR REG. # AJ036339 EPA # CAD 981659337

HOME: BUS:

SERVICE ADVISOR: 360 CHRISTIAN WILLIAMS

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	97	MERCEDES-BENZ SL320	WDBFA63FXVF149786		35037/35038	T388

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
17MAR1997	28JAN97	16MAR2001	16:00 12FEB02		80.00	CASH	12FEB2002

R.O. OPENED	READY	OPTIONS:
15:50 11FEB02	10:28 12FEB02	DLR:05766 ENG:10499112026386 1)RADIO 61561 2)SERIAL T09703305 3)10499112026386 4)129063-1F-149786

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

This dealership includes a separate charge for the management & disposal of hazardous wastes. These charges are included only on those particular repairs or services which generate hazardous wastes. These charges are calculated periodically and are available on request.

SERVICE DEPARTMENT HOURS

MONDAY - FRIDAY
7:30 AM - 5:30 PM

FOR APPOINTMENT CALL
MONDAY - FRIDAY
9:00 AM - 5:00 PM

ORIGINAL ESTIMATE $ 65

TOTAL REVISED ESTIMATE $

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.

CUST. SIGN. X

I ALSO ACKNOWLEDGE ANY OR ALL WARRANTY WORK AS STATED ON THIS REPAIR ORDER AND OR RECEIPT OF THIS VEHICLE.

CUST. SIGN. X

DESCRIPTION	TOTALS
LABOR AMOUNT	45.00
PARTS AMOUNT	20.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	65.00
LESS INSURANCE	0.00
SALES TAX	1.55
PLEASE PAY THIS AMOUNT	66.55

CLIENT COPY

094082

276669

INVOICE

Stead MOTORS of Walnut Creek
1301 Parkside Drive
Walnut Creek, CA 94596
(925) 937-1655

[redacted]/E
DANVILLE, CA 94506
HOME: [redacted] BUS: [redacted]

PAGE 1

SERVICE ADVISOR: 50 BRIAN POPE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
721/265	97	MERCEDES-BENZ SL320R	WDBFA63FXVF149786		36953/36953	2787.

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
17MAR1997	28JAN97	19MAR2001	16:30 17MAY02		CASH	17MAY2002

R.O. OPENED	READY	OPTIONS:
13:10 17MAY02	16:39 17MAY02	DLR:05766 ENG:195_CU_IN_-_3199_CC

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A ENGINE,LIGHT			
CAUSE: .			
071100 ENGINE CHECKS AND ADJUSTMENTS, PERFORM			
520 W93			(N/C)
1 000-094-18-48 AIR MASS SEN			(N/C)
071402 FUEL PRESS. & INTERNAL LEAKDOWN - FUEL INJ. SYST., TEST			
520 W93			(N/C)
071171 ELECTRIC TEST PROGRAM - FOR FUEL INJ., PREPARE FOR TEST			
520 W93			(N/C)
071172 INDIVIDUAL COMPONENTS WITH FAULT CODES, CHECK			
520 W93			(N/C)
071404 MASS AIR FLOW SENSOR (ONE) - FUEL INJ. SYST., TEST			
520 W93			(N/C)
075206 OXYGEN SENSOR(S) WITH WIRING, TEST			
520 W93			(N/C)
071606 MASS AIR FLOW SENSOR, SINGLE - FUEL INJ. SYST.,R & R / REPL.			
520 W93			(N/C)

CHARGE
AC# N/SA
MAY 23 2002
STEAD MOTORS
OF WALNUT CREEK

36953 ENG CHECK & ADJUST DTC P0170 SELF ADAPTATION FUEL PRESS CHECK 3.6 BAR LAMBDA BEFORE REP -1 1 PREPAIR FOR EL TEST PERFORM EL TEST FOR INJ SYST POWER FOR B2/5 PIN2 FROM Z7/25 12.3 V GROUND FOR B2/5 FROM W27 PIN4 0.4 OMS MASS AIR FLOW SEND TEST O2S WIRING TEST HEATER 2.4 OMS C2 VERIFY AIR MASS SEND INTERM OUT OF NOMINAL VALUE 24 KG AT IDLE C3 REPL AIR MASS SEND LAMBDA AFTER REPAIRE -2 3

****

B 37,500 MILE SERVICE
7500 PERFORM 7500 C SERVICE FRONT BRAKE PADS @70%,REAR BRAKE PADS @30%

Original Estimate $

Please read the important information on the reverse side invoice!
I acknowledge receipt of this invoice.
☐ I acknowledge the warranty repairs performed.
☐ I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.
Signature X _____
I acknowledge notice and oral approval of an increase in the original estimate price.
Initials X _____

Stead MOTORS
of Walnut Creek
1301 Parkside Drive
Walnut Creek, California 94596
(925) 937-1655
BAR #AB-005446 EPA #CAD981418726

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INS / ADJ	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

094082

276669

INVOICE

Stead MOTORS of Walnut Creek
1301 Parkside Drive
Walnut Creek, CA 94596
(925) 937-1655

DANVILLE, CA 94506
HOME: BUS:

PAGE 2

SERVICE ADVISOR: 50 BRIAN POPE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
721/265	97	MERCEDES-BENZ SL320R	WDBFA63FXVF149786		36953/36953	2787.

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
17MAR1997	28JAN97	19MAR2001	16:30 17MAY02		CASH	17MAY2002

R.O. OPENED	READY
13:10 17MAY02	16:39 17MAY02

OPTIONS: DLR:05766 ENG:195_CU_IN_-_3199_CC

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
520 C		95.00	95.00
1 104-180-01-09 FILTER ELEME	11.99	11.99	11.99
1 007603-014106 RING,GENERAL	0.70	0.70	0.70
8 ENGOIL00250 15W40	3.18	3.18	25.44

36953 7500 MILE SERV BR PADS FR 70% R 30%

****

EST: 300.00 17MAY02 13:10 SA: 50

Original Estimate $

Please read the important information on the reverse side invoice!

I acknowledge receipt of this invoice.

☐ I acknowledge the warranty repairs performed.

☐ I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.

Signature X _____

I acknowledge notice and oral approval of an increase in the original estimate price.

Initials X _____

Stead MOTORS
of Walnut Creek
1301 Parkside Drive
Walnut Creek, California 94596
(925) 937-1655

BAR #AB-005446 EPA #CAD981418726

DESCRIPTION	TOTALS
LABOR AMOUNT	95.00
PARTS AMOUNT	38.13
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	133.13
LESS INS / ADJ	0.00
SALES TAX	3.15
PLEASE PAY THIS AMOUNT	136.28

CUSTOMER COPY

094082

251636

INVOICE

Stead MOTORS of Walnut Creek
1301 Parkside Drive
Walnut Creek, CA 94596
(925) 937-1655

PAGE 2

HOME: BUS:

SERVICE ADVISOR: 50 BRIAN POPE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
721/265	97	MERCEDES-BENZ SL320R	WDBFA63FXVF149786		31087/31087	T904

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
17MAR1997	28JAN97	19MAR2001	16:30 09APR01		CASH	10APR2001

R.O. OPENED	READY	OPTIONS:
09:29 09APR01	10:32 10APR01	DLR:05766 ENG:195_CU_IN_-_3199_CC

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
F** SUPPLY AND INSTALL GOLD CENTER CAPS FOR WHEELS--ACC.			
00 * GENERAL SERVICING			
532 C		9.50	9.50
4 GOLD-STAR CENTERCAP	25.00	25.00	100.00

****

EST: 750.00 09APR01 09:29 SA: 50

Radio Code: 61561

CHARGE
AC# Amex
APR 11 2001
STEAD MOTORS
OF WALNUT CREEK

Original Estimate $

Please read the important information on the reverse side invoice!

I acknowledge receipt of this invoice.

☐ I acknowledge the warranty repairs performed.

☐ I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.

Signature X _____

I acknowledge notice and oral approval of an increase in the original estimate price.

Initials X _____

Stead MOTORS
of Walnut Creek
1301 Parkside Drive
Walnut Creek, California 94596
(925) 937-1655

BAR #AB-005446 EPA #CAD981418726

DESCRIPTION	TOTALS
LABOR AMOUNT	370.50
PARTS AMOUNT	282.58
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	653.08
LESS INS / ADJ	0.00
SALES TAX	22.61
PLEASE PAY THIS AMOUNT	675.69

CUSTOMER COPY

094082

251636

INVOICE

Stead MOTORS of Walnut Creek
1301 Parkside Drive
Walnut Creek, CA 94596
(925) 937-1655

ALAMO, CA 94507

PAGE 1

HOME: BUS:

SERVICE ADVISOR: 50 BRIAN POPE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
721/265	97	MERCEDES-BENZ SL320R	WDBFA63FXVF149786		31087/31087	T904

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
17MAR1997	28JAN97	19MAR2001	16:30 09APR01		CASH	10APR2001

R.O. OPENED	READY	OPTIONS:
09:29 09APR01	10:32 10APR01	DLR:05766 ENG:195_CU_IN_-_3199_CC

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A PERFORM 30,000 MILE MAINTENANCE AS PER MANUFACTURES RECOMENDATIONS			
30K PERFORM 30,000 MILE MAINTENANCE AS PER MANUFACTURES RECOMENDATIONS			
532 C		361.00	361.00
1 003-094-73-04 AIR FILTER	41.25	41.25	41.25
6 003-159-67-03 SPARK PLUG	3.95	3.95	23.70
1 104-180-01-09 FILTER ELEME	10.58	10.58	10.58
1 007603-014106 RING	0.50	0.50	0.50
8 ENGOIL00250 15W40	2.60	2.60	20.80
1 001-986-44-71-10 W/W FLUID	3.25	3.25	3.25
1 65740 ADDITIVE	12.95	12.95	12.95
1 000-824-36-27-01 WINDSHIELD W	11.70	11.70	11.70
1 129-835-00-47 FILTER,HVAC	50.60	50.60	50.60
**********			
B PASSENGERS SEAT BACK FALLING OFF			
918153 SEAT CUSHION COVER - FRONT PASS. SEAT, R & R / DETERM. COND. (SEAT REMOVED)			
532 W93			(N/C)
1 SCREW SCREW			(N/C)
**********			
C RADIO CODE--61561			
00 * GENERAL SERVICING			
532 C		0.00	0.00
**********			
D CRACKLING NOISE FROM FRONT GRILLE AREA WHILE ENGINE IS IDLING			
00 * GENERAL SERVICING			
532 C		0.00	0.00
**********			
E ORDER NEW SERVICE BOOK			
00 * GENERAL SERVICING			
532 C		0.00	0.00
1 S-6515-8021-13 MB ALL 97 (&	7.25	7.25	7.25

Original Estimate $

Please read the important information on the reverse side invoice!

I acknowledge receipt of this invoice.

☐ I acknowledge the warranty repairs performed.

☐ I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.

Signature X _____

I acknowledge notice and oral approval of an increase in the original estimate price.

Initials X _____

Stead MOTORS of Walnut Creek
1301 Parkside Drive
Walnut Creek, California 94596
(925) 937-1655

BAR #AB-005446 EPA #CAD981418726

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INS / ADJ	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

STEAD MOTORS

EZ SERVICE 30000 MILE SERVICE INTERVAL
GASOLINE AND DIESEL MODELS

OIL CHANGE:
- [✓] Change Engine Oil and Filter
- [NA] Change Transmission Fluid and Filter (excluded on 1996 and on 140/129)

CHECK/TOP OFF FLUID LEVELS, ADVISE ON LEAKS AND CONDITION OF:
- [✓] Engine
- [✓] Battery Electrolyte Level
- [✓] Clean Battery Terminals
- [] Soft Top Fluid If Applicable
- [✓] Coolant and Protection Level 34°
- [✓] Automatic Transmission Fluid
- [NA] Level Control Fluid If Applicable
- [✓] Brake Master Cylinder Fluid
- [✓] Power Steering Fluid
- [✓] Windshield Washer Fluid
- [✓] Adjust Wiper Fluid Nozzles
- [NA] Rear Windshield Washer Fluid If Applic.
- [✓] Differential Fluid
- [✓] Fuel Lines and Hoses
- [✓] Air Conditioning Refrigerant

CHASSIS AND BODY--CHECK AND ADVISE:
- [✓] Tire Pressures
- [✓] Tire Wear--Alignment Recommended???
- [✓] Rotate Tires
- [✓] Lube Throttle Linkages
- [✓] Engine Hoses and Lines
- [✓] Adjust V-Belts/Polybelts
- [] Wiper Blades
- [✓] Shocks/Struts/Front End Components
- [✓] Front Axle Ball Joint Free Play
- [✓] Flex Discs
- [✓] Brake Pad % Life Left; Front 70% Rear 30%
- [✓] Rotor Measurments; Front 26.4 Rear 10.7
- [✓] Clean Antenna Mast
- [✓] Lighting
- [✓] Instrumentation
- [✓] Exhaust System
- [✓] Engine Mounts
- [NA] Adjust Valves--Engines 616, 617 Check Clearance - Engine 102.983
- [NA] Adjust Timing--Engines 602 and 603
- [✓] Replace Spark Plugs
- [NA] Distributor Cap and Rotor (60k)
- [NA] Replace Fuel Filter (Gas) (60k)
- [NA] Replace Diesel Fuel and Pre Filter(60k 1996 models and on)
- [✓] Charging System
- [✓] Lube Hood Hinges and Latches
- [NA] Sunroof Operation If Applicable
- [✓] Clean Sunroof Drains If Applicable
- [NA] Lube Sunroof Rails If Applicable
- [✓] Soft Top Operation If Applicable
- [✓] Replace Air Filter(60k 1996 models and on)
- [✓] Replace Vent System Dust Filter--Models 202, 124, 129, 140, 210
- [✓] Soft Top Locking Tabs If Applicable
- [✓] Adjust Parking Brake
- [✓] Torque Steering Box Bolts
- [✓] Seatbelt Operation
- [✓] Lube Door Hinges and Latches
- [✓] Clean Cassette Player Head
- [✓] Horn
- [✓] Power Windows
- [✓] Transmission Shift Quality

IF APPLICABLE:
- [] Every 45000 Miles Replace Air Recirculation Filter on Model 140
- [] Every 45000 Miles Replace Activated Charcoal Pre Filter on Model 140
- [] Every 75000 Miles Replace Activated Charcoal Filter on Model 140, 210

ADDITIONAL RECOMMENDATIONS WITH APPLICABLE CHARGES:
- [] Recommended Every 6 Months--Full Detail
- [] Recommended Every Year--Alignment
- [] Recommended Every 2 Years--Brake Fluid Change
- [] Recommended Every 3 Years--Engine Coolant Change

[] QUALITY CONTROL CHECK:

_____

_____

_____

_____

TECHNICIAN NOTES: _____

_____

_____

_____

_____

TECHNICIAN NAME Troy Huper 2

SIGNATURE Troy Huper

DATE 4-8-01

094082

239641

INVOICE

Stead MOTORS of Walnut Creek
1301 Parkside Drive
Walnut Creek, CA 94596
(925) 937-1655

ALAMO, CA 94507
HOME: BUS:

PAGE 1

SERVICE ADVISOR: 50 BRIAN POPE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
721/265	97	MERCEDES-BENZ SL320R	WDBFA63FXVF149786		28816/28816	T90

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
17MAR1997	28JAN97	19MAR2001	16:30 13SEP00		CASH	13SEP2000

R.O. OPENED	READY	OPTIONS:
07:44 12SEP00	17:08 13SEP00	DLR:05766 ENG:195_CU_IN_-_3199_CC

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A PERFORM 7500 MILE SERVICE AS PER MANUFACTURES RECOMENDATIONS			
7500 PERFORM 7500 MILE SERVICE AS PER MANUFACTURES RECOMENDATIONS			
490 C		66.50	66.50
1 104-180-01-09 FILTER ELEME	10.58	10.58	10.58
1 007603-014106 RING	0.50	0.50	0.50
8 ENGOIL00250 15W40	2.60	2.60	20.80
**********			
B TRUNK LAMP OUT			
CAUSE: .			
821015 ELECTRICAL SYSTEM, DIAGNOSE MALFUNCTION			
490 W93			(N/C)
1 129-750-03-84 FASTENER,TRU			(N/C)
888273 TRUNK LID CATCH (UPPER & LOWER PART), R & R/REPL. REQ. PARTS			
490 W93			(N/C)
**********			
C REPLACE GAS CAP WITH MBZ CAP			
47 *FUEL TANK,LINES,EVAP WORK			
490 C		0.00	0.00
1 140-470-00-05 FILLER CAP	9.30	9.30	9.30
**********			
D INSTALL LICENCE PLATES AND FRAMES			
88 *DETACH PANEL WORK			
490 C		0.00	0.00
**********			
E PLEASE CHECK CAR OVER--JUST PURCHASED			
00 * GENERAL SERVICING			
1 C		0.00	0.00
**********			
F** MODEL 129 1997 - 1998 REPLACEMENT OF DRIVERS AIR BAG			
CAUSE: RECALL			

Original Estimate $

Please read the important information on the reverse side invoice!

I acknowledge receipt of this invoice.

☐ I acknowledge the warranty repairs performed.

☐ I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.

Signature X _____

I acknowledge notice and oral approval of an increase in the original estimate price.

Initials X _____

Stead MOTORS
of Walnut Creek
1301 Parkside Drive
Walnut Creek, California 94596
(925) 937-1655

BAR #AB-005446 EPA #CAD981418726

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INS / ADJ	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

094082

239641

INVOICE

Stead MOTORS of Walnut Creek
1301 Parkside Drive
Walnut Creek, CA 94596
(925) 937-1655

[redacted] ANDREWS LANE
ALAMO, CA 94507
HOME: BUS:

PAGE 2

SERVICE ADVISOR: 50 BRIAN POPE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
721/265	97	MERCEDES-BENZ SL320R	WDBFA63FXVF149786		28816/28816	T90

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
17MAR1997	28JAN97	19MAR2001	16:30 13SEP00		CASH	13SEP2000

R.O. OPENED	READY	OPTIONS:
07:44 12SEP00	17:08 13SEP00	DLR:05766 ENG:195_CU_IN_-_3199_CC

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
910000 GROUP 91 - NO OPERATION NO. AND TIME GIVEN			
490 W93			(N/C)
1 170-460-02-98-8F94 AIR BAG			(N/C)
**********			
G** OIL LEAK AT ENGINE			
CAUSE: .			
011010 ENGINE, CHECK FOR OIL LEAK(S)/LOSS			
490 W93			(N/C)
1 104-010-37-20 CYLINDER HEA			(N/C)
1 104-010-21-30 CYL HEAD COV			(N/C)
1 002-989-73-20-10 SEALING COMP			(N/C)
3 7481 2" DISC			(N/C)
1 0181 AEROSOLVE II			(N/C)
1 0286 ZEP-CARB			(N/C)
1 017-997-16-48 SEAL RING.OI			(N/C)
1 012-997-51-48 SEAL RING.WA			(N/C)
1 Q-1-03-0002 ANTI-FREEEZE			(N/C)
2 6200 TIE STRAP			(N/C)
6 6201 TIE STRAP			(N/C)
015760 CYLINDER HEAD - SINGLE, R & R			
490 W93			(N/C)
**********			
H** CUSTOMER CARE			
CAUSE: CUSTOMER CARE			
CC CUSTOMER CARE			
1 W93			(N/C)
LUBE CLEAN01500			
PO#50			

Original Estimate $

Please read the important information on the reverse side invoice!
I acknowledge receipt of this invoice.
☐ I acknowledge the warranty repairs performed.
☐ I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.
Signature X _____
I acknowledge notice and oral approval of an increase in the original estimate price.
Initials X _____

Stead MOTORS
of Walnut Creek
1301 Parkside Drive
Walnut Creek, California 94596
(925) 937-1655
BAR #AB-005446 EPA #CAD981418726

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INS / ADJ	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

094082

239641

INVOICE

Stead MOTORS of Walnut Creek
1301 Parkside Drive
Walnut Creek, CA 94596
(925) 937-1655

8
ALAMO, CA 94507
HOME: BUS:

PAGE 3

SERVICE ADVISOR: 50 BRIAN POPE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
721/265	97	MERCEDES-BENZ SL320R	WDBFA63FXVF149786		28816/28816	T90

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
17MAR1997	28JAN97	19MAR2001	16:30 13SEP00		CASH	13SEP2000

R.O. OPENED	READY	OPTIONS:
07:44 12SEP00	17:08 13SEP00	DLR:05766 ENG:195_CU_IN_-_3199_CC

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
W93			(N/C)
LUBE TOPOFF02400			
PO#50			
W93			(N/C)
**********			
I** ALTERNATE TRANSPORTATION HAS BEEN OFFERED TO THIS CUSTOMER - HE/SHE			
SELECTED _____ / /			
AT ALTERNATE TRANSPORTATION HAS BEEN OFFERED TO			
THIS CUSTOMER - HE/SHE SELECTED			
1 C		0.00	0.00
**********			

EST: 200.00 12SEP00 07:44 SA: 50

CHARGE
AC# Visa
SEP 14 2000
STEAD MOTORS
OF WALNUT CREEK

Original Estimate $

Please read the important information on the reverse side invoice!
I acknowledge receipt of this invoice.
☐ I acknowledge the warranty repairs performed.
☐ I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.
Signature X _____
I acknowledge notice and oral approval of an increase in the original estimate price.
Initials X _____

Stead MOTORS
of Walnut Creek
1301 Parkside Drive
Walnut Creek, California 94596
(925) 937-1655
BAR #AB-005446 EPA #CAD981418726

DESCRIPTION	TOTALS
LABOR AMOUNT	66.50
PARTS AMOUNT	41.18
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	107.68
LESS INS / ADJ	0.00
SALES TAX	3.40
PLEASE PAY THIS AMOUNT	111.08

CUSTOMER COPY

STEAD MOTORS

C SERVICE 7500 MILE SERVICE INTERVAL GAS MODELS
5000 MILE SERVICE INTERVAL DIESEL MODELS

OIL CHANGE:

[✓] Change Engine Oil and Filter

CHECK/TOP OFF FLUID LEVELS, ADVISE ON LEAKS AND CONDITION OF:

[✓] Engine
[✓] Battery Electrolyte Level
[✓] Soft Top Fluid If Applicable
[✓] Coolant and Protection Level -30°
[] Automatic Transmission Fluid
[] Level Control Fluid If Applicable
[✓] Brake Master Cylinder Fluid
[✓] Power Steering Fluid
[✓] Windshield Washer Fluid
[] Rear Windshield Washer Fluid If Applic.
[✓] Differential Fluid

CHASSIS AND BODY--CHECK AND ADVISE:

[✓] Tire Pressures
[] Tire Wear--Alignment or Rotation???
[✓] Lube Throttle Linkages
[✓] Engine Hoses and Lines
[✓] Adjust V-Belts/Polybelts
[✓] Wiper Blades
[✓] Shocks/Struts/Front End Components
[✓] Flex Discs
[✓] Brake Pad % Life Left; Front 90, Rear 60
[✓] Clean Antenna Mast
[✓] Lighting
[✓] Instrumentation
[✓] Exhaust System

ADDITIONAL RECOMMENDATIONS WITH APPLICABLE CHARGES:

[] Recommended Every 6 Months--Full Detail
[] Recommended Every Year--Alignment
[] Recommended Every 2 Years--Brake Fluid Change
[] Recommended Every 3 Years--Engine Coolant Change

[] ***QUALITY CONTROL CHECK***

_____
_____
_____
_____

[] ***TECHNICIAN NOTES:*** _____
_____
_____
_____
_____

TECHNICIAN NAME MIKE TOLMAN

SIGNATURE [signature]

DATE 07-12-08

STEAD MOTORS RECOMMENDS IN BETWEEN OIL AND FILTER CHANGES ON GAS ENGINES EVERY 3750 MILES AND ON DIESEL ENGINES EVERY 2500 MILES