

ACCOUNT NUMBER **877294 188876**  
 NAME (PRINT) **J. O. BRAYTON**  
 ADDRESS **3875 WILSHIRE BLVD**  
 CITY AND ZIP CODE **LA**  
 PHONE (AREA CODE) **(213) 389-3538**

**REG - 13.7**  
  
**BAD BATT**

No. 1461742

Sears, Roebuck and Co. #1088  
 235 North Central Avenue  
 Glendale, CA 91203  
 LA 44222170

190-LABOR	SHOP CODE	CHARGES	WORK DONE BY
INSTALL TIRES/WHEEL BALANCE			
BATTERY SERVICE	PTC	200	31
SHOCKS			
LUBE/OIL CHANGE OIL FILTER			
TRANSMISSION OIL/FILTER SERVICE			
ALIGNMENT REPAIR			
ALIGNMENT			
ENGINE DIAGNOSIS			
EXHAUST SYSTEM/MUFFLER/TAIL PIPE/EXHAUST PIPE			
BRAKE SERVICE			
COOLING SERVICE FLUSH			

SRC/SC CASH C/C MCA CREDIT APPROVAL STATE LICENSE NO. (if applicable)

SELLING STORE NO. **1088** DATE OF SALE **7-21-84** SALES NO. **10421**

MAKE OF CAR **BENTLEY** COLOR **67** YEAR **67**

LICENSE NO. **833KBJ** ODOMETER READING

VEHICLE IDENTIFICATION NO.

TIME IN READY BY

4252	451088/228	10421
228	4384	
BATTERY		NDS 74.99
56		CR 5.000
190	21023	
CO-PRO		NDS 3.000
		STL 71.99
		TAX 4.87

(if applicable) TAX

**(A)** LABOR TOTAL (incl. tax if applicable) **200**

REPLACED PARTS REQUESTED BY CUSTOMER  YES  NO DATE

INITIAL ESTIMATE REVISED ESTIMATE TIME OF DAY

PARTS PARTS CUSTOMER CONTACTED BY

LABOR LABOR  IN PERSON  BY PHONE

TOTAL **76.86** TOTAL NO.

877294188876/0  
 7/21/84 2 SC TTL 76.86

QTY.	STOCK NO.	UNIT PRICE	AMOUNT OF SALE (CASH PRICE)	USED, REBUILT OR RECONDITIONED	DESCRIPTION OF PARTS ALL PARTS NEW UNLESS OTHERWISE STATED
1	<del>43364</del>		74.99		
	4341		5.00		
			69.99		
			4.87		
			<b>74.86</b>		

SEE WARRANTY ON REVERSE SIDE

WORK AUTHORIZED BY *J. O. Brayton*

**(B)** MERCHANDISE TOTAL (including tax) **76.86**

**(A) + (B) =** TOTAL AMOUNT OF SALE

DEPOSIT

BALANCE

This purchase is made under my SearsCharge Account Agreement, which is incorporated herein by reference, for the credit sales price consisting of the cash price plus the **FINANCE CHARGE**. This order is subject to the approval of the Credit Sales Department of Sears, Roebuck and Co.

*J. O. Brayton*  
 PURCHASED BY

**NOTICE TO OUR CALIFORNIA CUSTOMERS**

A buyer of this product in California has the right to have this product serviced or repaired during the warranty period. The warranty period will be extended for the number of whole days that the product has been out of the buyer's hands for warranty repairs. If a defect exists within the warranty period, the warranty period will not expire until the defect has been fixed. The warranty period will also be extended if the warranty repairs have not been performed due to delays caused by circumstances beyond the control of the buyer, or if the warranty repairs did not remedy the defect and the buyer notifies the manufacturer or seller of the failure of the repairs within 60 days after they were completed. If, after a reasonable number of attempts, the defect has not been fixed, the buyer may return this product for a replacement or a refund subject, in either case, to deduction of a reasonable charge for usage. This time extension does not affect the protections or remedies the

SEARS, ROEBUCK AND CO.



**INVOICE**

Print Date : 05/22/2010

**Advani, Sabu**

1967 Bently - T Series

Tucson, AZ 85718

Lic # : 756KGY

Odometer In : 20050

Home 4 ---- Cellula

Unit # :

Odometer Out : 20053

Cust ID : 1084

Vin # : **SBX 1950**

Ref # :

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
Gear oil RTV (For rear end seal) 765 1944	1.00	7.69	7.69	CHANGE DIFFEERENTIAL GREASE (INCLUDES) Change trunnion joint oil	1.00	93.25
Mobile 1 synthetic gear lube 75W90	4.00	14.88	59.52	REPLACE LEAKING FUEL PUMP (INCLUDES) Test for leaks	2.00	186.50
#6 Steel braided hose EA 420006	2.00	17.88	35.76	Found leak at fuel pump -and 1 of 2 fuel lines		
Classic car motor oil (Old specs) Pre cat BP 20W50	8.50	8.28	70.38	Replace leaking steel braided -flexible fuel line		
Bently Crewe oil filter 3750	1.00	59.63	59.63	(We used customer supplied -fuel pump)		
Shop Supplies		39.73	39.73	3000 K OIL SERVICE (INCLUDES) Change oil and filter Check all fluids	0.50	46.63
				MISC LABOR (INCLUDES) Check hard starting Check lights and repair Found 1 license plate light -out and replaced bulb Found both reverse lights -out and traced fault to -steering column micro -switch and reset actuator	1.30	121.23
				Environmental Fee		5.00



**INVOICE**

Print Date : 05/22/2010

**Advani, Sabu**

1967 Bently - T Series

Tucson, AZ 85718  
 Home 34 ---- Cellular  
 Cust ID : 1084

Lic # : 756KGY  
 Unit # :  
 Vin # : **SBX 1950**  
 Hat # :

Odometer In : 20050  
 Odometer Out : 20053

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
---------------------------	-----	------	----------	-------------------	-------	----------

[ Technicians : PRICE, G.; PRICE, GARY; FRICKS, S ]

Org. Estimate \$747.41	Revisions \$0.00	Current Estimate \$ 747.41	Additional Cost	Revised Estimate
------------------------	------------------	----------------------------	-----------------	------------------

<b>Labor:</b>	<b>452.61</b>
<b>Parts:</b>	<b>272.71</b>
<b>Sublet:</b>	<b>0.00</b>
	-----
<b>Sub:</b>	<b>725.32</b>
<b>Tax:</b>	<b>22.09</b>
<b>Total:</b>	<b>747.41</b>
<b>Bal Due:</b>	<b>\$747.41</b>

[ Payments - ]

Warranty on parts and labor is 2 year or 24,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....



**BENTLEY**

**BENTLEY ZIONSVILLE**  
360 SOUTH FIRST STREET  
ZIONSVILLE, IN 46077  
PH:(317)873-2360 FAX:(317)873-6860  
www.bentleyzionsville.com  
BILL TO:

PAGE: 1

**INVOICE**

INVOICE NO. 264977  
DATE 12/03/07  
CUSTOMER ACCT. NO. ADV85718  
TELEPHONE NO.

SHIP TO:

SABU ADVANI  
TUCSON, AZ 85718

ERNIE'S BRITISH CARS  
1121 W. WETMOR ROAD  
TUCSON, AZ 85705

DATE	TIME	BY	CUSTOMER P.O. NUMBER	SPECIAL INSTRUCTIONS
12/3/2007	12:53:33 PM	MCW		SO#: 106425 0248588303

TERMS	SHIP VIA
Prepaid	UPS 2ND DAY

QUANTITY ORDERED	QUANTITY SHIPPED	B.O.	PART NUMBER	DESCRIPTION	EACH	TOTAL
				SBX 1950		
6	6		RR 363L1	(PQ12)BRAKE FLUID BRAKE FLUID!! BRAKE FLUID!!	25.75	154.50
1	1		UE 36600	FAILSAFE THERMOSTAT ***1960-1998 CARS*** (88 DEGREE CELSIUS)	97.14	97.14
1	1		UE 73635R	SY/SZ THERM GASKET- REPRO.	3.00	3.00
					Subtotal:	254.64
					Discount:	0.00
					Freight:	63.19
					Misc Charge:	0.00
					Sales Tax:	0.00
					Total:	0.00
Payments Received:					317.83	
Deposits Applied:					0.00	



ERNIE'S BRITISH CARS, PARTS, AND SERVICE, INC.  
1121 W. WETMORE  
TUCSON, AZ 85705  
520-888-3055

12/07/07

Name Sabu  
Address 0  
Address 0  
Phone # 4  
Vehicle Bentley  
0

Total of Services:

Parts	\$	164.85
Environmental fee	\$	5.00
Service	\$	800.00
Total:	\$	969.85
Tax	\$	10.06
Total due:	\$	979.91

<u>Spark plug wire resistance</u>	
<u>RH bank</u>	<u>LH bank</u>
1 open/16.0K	18.4K
2 open/19.5K	15.9K
3 14.5K	open/14.3K
4 open/10.8K	12.2K
coil open - replace	

(old spark PLUGS : CHAMPION 2405)

Thank you for allowing us to serve you.





ERNIE'S BRITISH CARS, PARTS, AND SERVICE, INC.  
1121 W. WETMORE  
TUCSON, AZ 85705  
520-888-3055

**Customer information:**

12/07/07

Sabu

0

0

Bentley

**# of  
hours**

**Repair info:**

Customer request: see attached.

Checked prolonged engine cold start cranking. Inspected fuel pump, filter, and carbs. Fuel flow to carbs was excellent. Fuel pump (output 3.1 lbs/PSI). And filter ok. Inspected choke solenoid. All ops functioning. Checked ignition system. Points, condenser, and rotor ok. Checked dist cap and ignition wires. Resistance results listed on front page.

Repaired cap and wire junctions that were open or too high resistance. Cleaned all other junctions. Replaced ignition coil as high tension socket was corroded. Replaced bad coil to distributor high tension wire and connectors.

Checked secondary cranking system to coil and ballast resistor. Found system not working. Running voltage at coil + was 6 volts. Cranking voltage should be 10-12 volts and it was 5 volts. Made new wire harness from coil +, ballast resistor output, and secondary cranking power wire. Checked spark plugs. Found all in good electrical condition, but slightly dirty. Cleaned and re-gapped. Adjusted carb for best idle. Changed engine oil and filter. Customer supplied 20/50 Castrol and Bentley oil filter.

4.00

0.50

Replaced engine coolant. Used 25% to 75% antifreeze (Peak green ethylene glycol) to water ratio. Replaced thermostat and gasket (customer supplied).

0.50

Attempted chassis grease/lube. Rear u-joints on half shafts had conventional zerk fitting. All other grease points are Bentley special.

0.00

**ERNIE'S BRITISH CARS, PARTS, AND SERVICE, INC.**  
**1121 W. WETMORE**  
**TUCSON, AZ 85705**  
**520-888-3055**

Purged old brake fluid from reservoirs. Purged and bleed  
accumulators. Purged and bleed high pressure calipers.  
Purged and bleed master cylinder brake system. Customer  
supplied Castrol RR363 brake fluid. 4.00  
Changed diff gear oil. Removed 90 wt. Filled with Mobil 1  
75W/90 synth gear oil. Changed trunion joints gear oil.  
Removed 90 wt. Filled with Mobil 1 75W/90 synth gear oil. 1.00

Total hours 10.00  
Service \$80.00 per hour \$ 800.00  
Total service \$ 800.00



**AREA B  
VEHICLE  
INSPECTION  
REPORT**

**ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
ARIZONA CAR CARE PROGRAM**

1749604



- This test was conducted in accordance with the Federal Short Test Procedure in 207B. If your vehicle failed, it may be covered by the manufacturer's warranty (see supplemental brochure for more information).
- Vehicle registrations expire on the 15th or last day of the registration month. You will not have to pay a late registration fee provided: Your vehicle failed the first test prior to registration expiration, is repaired, retested and passed, and the registration renewal is postmarked within 30 days of the first test.
- The Arizona Vehicle Emissions Inspection Program is administered by the Arizona Department of Environmental Quality.

**THE FINAL RESULT OF THIS INSPECTION IS COMPLIANCE BASIC**

LICENSE PLATE	VEHICLE IDENTIFICATION NUMBER	MODEL YEAR/MAKE	STYLE	ODOMETER	FUEL	CYL	STD CLASS
756KBY DEC	8BX1950	07 ROLLS	0D	110	G	08	4
STATION/LANE	INSPECTOR(S)	DATE	TIME	TEST TYPE	INSPECTION NUMBER	REPRINT	FEE
P02 4	4377 4315	12/05/05	15:03	INITIAL	P024A123	ND	\$12.25

**EQUIPMENT INSPECTION RESULTS**

SYSTEM	RESULT	SYSTEM	RESULT
GAS CAP TEST	PASS		

**EMISSIONS INSPECTION RESULTS**

IDLE TEST POLLUTANT	FINAL READING	IDLE STANDARD	RESULT
HYDROCARBONS (HC) IN PPM	122	450	PASS
CARBON MONOXIDE (CO) IN %	2.17	5.00	PASS

THIS IS AN INITIAL INSPECTION OF THIS VEHICLE. THIS VEHICLE HAS PASSED THE EQUIPMENT INSPECTION AND THE EMISSIONS TEST. CONGRATULATIONS! THANK YOU FOR HELPING CLEAN OUR AIR. USE THE TEAR-OUT SECTION BELOW FOR REGISTERING YOUR VEHICLE. KEEP THE UPPER PORTION OF THIS VIF UNTIL YOU RECEIVE YOUR NEW REGISTRATION. IT IS YOUR PROOF OF COMPLIANCE WITH CAR CARE REQUIREMENTS!

TEAR HERE

ARIZONA VEHICLE EMISSIONS INSPECTION CERTIFICATE

1749604

IF THIS PORTION IS NOT VOIDED, SUBMIT IT WITH YOUR REGISTRATION DOCUMENTS.

TESTING REQUIREMENTS MUST BE COMPLETED BEFORE REGISTRATION

LICENSE PLATE	VEHICLE IDENTIFICATION NUMBER	MODEL YEAR/MAKE
756KBY DEC	8BX1950	07 ROLLS
CERTIFICATE DATE	INITIAL TEST DATE	FEE PAID
12/05/05	12/05/05	\$12.25
CERTIFICATE TYPE		
BASIC Y COMPLIANCE		

**VOID IF ALTERED**

**PIMA COUNTY INSPECTION VALID ONLY IN PIMA COUNTY**

**PIMA COUNTY INSPECTION VALID ONLY IN PIMA COUNTY**

Questions? Call: 800-284-7748

The Arizona Department of Environmental Quality shall preserve, protect and enhance the environment and public health and shall be a leader in the development of public policy to maintain and improve the quality of Arizona's air, land and water resources.

JAN 2002



**AREA B  
VEHICLE  
INSPECTION  
REPORT**

**ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
ARIZONA CAR CARE PROGRAM**

2415186



- This test was conducted in accordance with the Federal Short Test Procedure in 207B. If your vehicle failed, it may be covered by the manufacturer's warranty (see supplemental brochure for more information).
- Vehicle registrations expire on the 15th or last day of the registration month. You will not have to pay a late registration fee provided: Your vehicle failed the first test prior to registration expiration, is repaired, retested and passed, and the registration renewal is postmarked within 30 days of the first test.
- The Arizona Vehicle Emissions Inspection Program is administered by the Arizona Department of Environmental Quality.

**THE FINAL RESULT OF THIS INSPECTION IS:**

COMPLIANCE BASIC

LICENSE PLATE	VEHICLE IDENTIFICATION NUMBER	MODEL YEAR/MAKE	STYLE	ODOMETER	FUEL	CYL	STD CLASS
756KGY DEC	SBX1950	67 ROLLS	SD	119	G	08	4
STATION/LANE	INSPECTOR(S)	DATE	TIME	TEST TYPE	INSPECTION NUMBER	REPRINT	FEE
P02 5	4316 4323	12/12/06	09:56	INITIAL	P025A005	NO	\$12.25

**EQUIPMENT INSPECTION RESULTS**

SYSTEM	RESULT	SYSTEM	RESULT
GAS CAP TEST	PASS		

**EMISSIONS INSPECTION RESULTS**

IDLE TEST POLLUTANT	FINAL READING	IDLE STANDARD	RESULT
HYDROCARBONS (HC) IN PPM	195	450	PASS
CARBON MONOXIDE (CO) IN %	2.54	5.00	PASS

THIS IS AN INITIAL INSPECTION OF THIS VEHICLE.  
THIS VEHICLE HAS PASSED THE EQUIPMENT INSPECTION AND THE EMISSIONS TEST.  
CONGRATULATIONS! THANK YOU FOR HELPING CLEAN OUR AIR.  
USE THE TEAR-OUT SECTION BELOW FOR REGISTERING YOUR VEHICLE.  
KEEP THE UPPER PORTION OF THIS VIR UNTIL YOU RECEIVE YOUR NEW REGISTRATION.  
IT IS YOUR PROOF OF COMPLIANCE WITH CAR CARE REQUIREMENTS!

TEAR HERE

ARIZONA VEHICLE EMISSIONS INSPECTION CERTIFICATE

2415186

IF THIS PORTION IS NOT VOIDED, SUBMIT IT WITH YOUR REGISTRATION DOCUMENTS.

TESTING REQUIREMENTS MUST BE COMPLETED BEFORE REGISTRATION

LICENSE PLATE	VEHICLE IDENTIFICATION NUMBER	MODEL YEAR/MAKE
756KGY DEC	SBX1950	67 ROLLS
CERTIFICATE DATE	INITIAL TEST DATE	FEE PAID
12/12/06	12/12/06	\$12.25
CERTIFICATE TYPE		
BASIC V COMPLIANCE		

VOID IF ALTERED

PIMA COUNTY INSPECTION VALID ONLY IN PIMA COUNTY

09:56

**PIMA COUNTY INSPECTION VALID  
ONLY IN PIMA COUNTY**

Questions? Call: 800-284-7748

The Arizona Department of Environmental Quality shall preserve, protect and enhance the environment and public health and shall be a leader in the development of public policy to maintain and improve the quality of Arizona's air, land and water resources.



**AREA B  
VEHICLE  
INSPECTION  
REPORT**

**ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
ARIZONA CAR CARE PROGRAM**

0896429



- This test was conducted in accordance with the Federal Short Test Procedure in 207B. If your vehicle failed, it may be covered by the manufacturer's warranty (see supplemental brochure for more information).
- Vehicle registrations expire on the 15th or last day of the registration month. You will not have to pay a late registration fee provided: Your vehicle failed the first test prior to registration expiration, is repaired, retested and passed, and the registration renewal is postmarked within 30 days of the first test.
- The Arizona Vehicle Emissions Inspection Program is administered by the Arizona Department of Environmental Quality.

**THE FINAL RESULT OF THIS INSPECTION IS:**

COMPLIANCE BASIC

LICENSE PLATE 756KBY DEC	VEHICLE IDENTIFICATION NUMBER 8BX1950	MODEL YEAR/MAKE 67 ROLLS	STYLE SD	ODOMETER 118	FUEL 6	CYL 08	STD CLASS 4
STATION/LANE P02 2	INSPECTOR(S) 4339 4300	DATE 12/12/03	TIME 11:00	TEST TYPE INITIAL	INSPECTION NUMBER P022A018	REPRINT NO	FEE \$11.75

**EQUIPMENT INSPECTION RESULTS**

SYSTEM	RESULT	SYSTEM	RESULT
GAS CAP TEST	PASS		

**EMISSIONS INSPECTION RESULTS**

IDLE TEST POLLUTANT	FINAL READING	IDLE STANDARD	RESULT
HYDROCARBONS (HC) IN PPM	212	450	PASS
CARBON MONOXIDE (CO) IN %	2.85	3.00	PASS

THIS IS AN INITIAL INSPECTION OF THIS VEHICLE.  
THIS VEHICLE HAS PASSED THE EQUIPMENT INSPECTION AND THE EMISSIONS TEST.  
CONGRATULATIONS! THANK YOU FOR HELPING CLEAN OUR AIR.  
USE THE TEAR-OUT SECTION BELOW FOR REGISTERING YOUR VEHICLE.  
KEEP THE UPPER PORTION OF THIS VEHICLE UNTIL YOU RECEIVE YOUR NEW REGISTRATION.  
IT IS YOUR PROOF OF COMPLIANCE WITH CAR CARE REQUIREMENTS!

TEAR HERE

ARIZONA VEHICLE EMISSIONS INSPECTION CERTIFICATE

0896429

IF THIS PORTION IS NOT VOIDED, SUBMIT IT WITH YOUR REGISTRATION DOCUMENTS.

TESTING REQUIREMENTS MUST BE COMPLETED BEFORE REGISTRATION

LICENSE PLATE 756KBY DEC	VEHICLE IDENTIFICATION NUMBER 8BX1950	MODEL YEAR/MAKE 67 ROLLS
CERTIFICATE DATE 12/12/03	INITIAL TEST DATE 12/12/03	FEE PAID \$11.75
CERTIFICATE TYPE COMPLIANCE		

**PIMA COUNTY INSPECTION VALID  
ONLY IN PIMA COUNTY**



Questions? Call: 800-284-7748

The Arizona Department of Environmental Quality shall preserve, protect and enhance the environment and public health and shall be a leader in the development of public policy to maintain and improve the quality of Arizona's air, land and water resources.

JAN 2002

VOID IF ALTERED

**PIMA COUNTY INSPECTION VALID ONLY IN PIMA COUNTY**



**AREA B  
VEHICLE  
INSPECTION  
REPORT**

**ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
ARIZONA CAR CARE PROGRAM**

1395186



- This test was conducted in accordance with the Federal Short Test Procedure in 207B. If your vehicle failed, it may be covered by the manufacturer's warranty (see supplemental brochure for more information).
- Vehicle registrations expire on the 15th or last day of the registration month. You will not have to pay a late registration fee provided: Your vehicle failed the first test prior to registration expiration, is repaired, retested and passed, and the registration renewal is postmarked within 30 days of the first test.
- The Arizona Vehicle Emissions Inspection Program is administered by the Arizona Department of Environmental Quality.

**THE FINAL RESULT OF THIS INSPECTION IS:**

COMPLIANCE BASIC

LICENSE PLATE	VEHICLE IDENTIFICATION NUMBER	MODEL YEAR/MAKE	STYLE	ODOMETER	FUEL	CYL	STD CLASS
756KCV DEC	3BX1950	07 BENT	30	101	6	88	4
STATION/LANE	INSPECTOR(S)	DATE	TIME	TEST TYPE	INSPECTION NUMBER	REPRINT	FEE
P02 2	A345 4377	12/03/04	10:00	INITIAL	P02LAW04	NO	\$12.25

**EQUIPMENT INSPECTION RESULTS**

SYSTEM	RESULT	SYSTEM	RESULT
BAS CAP TEST	PASS		

**EMISSIONS INSPECTION RESULTS**

IDLE TEST POLLUTANT	FINAL READING	IDLE STANDARD	RESULT
HYDROCARBONS (HC) IN PPM	237	450	PASS
CARBON MONOXIDE (CO) IN %	3.36	5.00	PASS

THIS IS AN INITIAL INSPECTION OF THIS VEHICLE.  
THIS VEHICLE HAS PASSED THE EQUIPMENT INSPECTION AND THE EMISSIONS TEST.  
CONGRATULATIONS! THANK YOU FOR HELPING CLEAN OUR AIR.  
USE THE TEAR-OUT SECTION BELOW FOR REGISTERING YOUR VEHICLE.  
KEEP THE UPPER PORTION OF THIS VEHICLE UNTIL YOU RECEIVE YOUR NEW REGISTRATION.  
IT IS YOUR PROOF OF COMPLIANCE WITH CAR CARE REQUIREMENTS!

TEAR HERE

ARIZONA VEHICLE EMISSIONS INSPECTION CERTIFICATE

1395186

IF THIS PORTION IS NOT VOIDED, SUBMIT IT WITH YOUR REGISTRATION DOCUMENTS,

TESTING REQUIREMENTS MUST BE COMPLETED BEFORE REGISTRATION

LICENSE PLATE	VEHICLE IDENTIFICATION NUMBER	MODEL YEAR/MAKE
756KCV DEC	3BX1950	07 BENT
CERTIFICATE DATE	INITIAL TEST DATE	FEE PAID
12/03/04	12/03/04	\$12.25
CERTIFICATE TYPE		
BASIC COMPLIANCE		

MRHDAJJK 10:00 **VOID IF ALTERED**

**PIMA COUNTY INSPECTION VALID ONLY IN PIMA COUNTY**

**PIMA COUNTY INSPECTION VALID  
ONLY IN PIMA COUNTY**

Questions? Call: 800-284-7748

The Arizona Department of Environmental Quality shall preserve, protect and enhance the environment and public health and shall be a leader in the development of public policy to maintain and improve the quality of Arizona's air, land and water resources.











**AREA B  
VEHICLE  
INSPECTION  
REPORT**



**ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY  
ARIZONA CAR CARE PROGRAM**

- This test was conducted in accordance with the Federal Short Test Procedure in 207B. If your vehicle failed, it may be covered by the manufacturer's warranty (see supplemental brochure for more information).
- Vehicle registrations expire on the 15th or last day of the registration month. You will not have to pay a late registration fee provided: Your vehicle failed the first test prior to registration expiration, is repaired, retested and passed, and the registration renewal is postmarked within 30 days of the first test.
- The Arizona Vehicle Emissions Inspection Program is administered by the Arizona Department of Environmental Quality.

**THE FINAL RESULT OF THIS INSPECTION IS:**

COMPLIANCE BASIC

LICENSE PLATE NP DEC		VEHICLE IDENTIFICATION NUMBER SBX1950		MODEL YEAR/MAKE 67 BENTL	STYLE SD	ODOMETER 070	FUEL G	CYL 08	STD CLASS 4
STATION/LANE P02 5	INSPECTOR(S) 4346 4352	DATE 12/16/02	TIME 13:18	TEST TYPE INITIAL		INSPECTION NUMBER P025A096	REPRINT NO	FEE \$11.75	

**EQUIPMENT INSPECTION RESULTS**

SYSTEM	RESULT	SYSTEM	RESULT
GAS CAP TEST	PASS		

**EMISSIONS INSPECTION RESULTS**

IDLE TEST POLLUTANT	FINAL READING	IDLE STANDARD	RESULT
HYDROCARBONS (HC) IN PPM	177	450	PASS
CARBON MONOXIDE (CO) IN %	4.75	5.00	PASS

THIS IS AN INITIAL INSPECTION OF THIS VEHICLE.  
THIS VEHICLE HAS PASSED THE EQUIPMENT INSPECTION AND THE EMISSIONS TEST.  
CONGRATULATIONS! THANK YOU FOR HELPING CLEAN OUR AIR.  
USE THE TEAR-OUT SECTION BELOW FOR REGISTERING YOUR VEHICLE.  
KEEP THE UPPER PORTION OF THIS VIR UNTIL YOU RECEIVE YOUR NEW REGISTRATION.  
IT IS YOUR PROOF OF COMPLIANCE WITH CAR CARE REQUIREMENTS!

TEAR HERE



**ERNIE'S BRITISH CARS, PARTS & SERVICE, INC.**

1121 West Wetmore Road  
TUCSON, ARIZONA 85705  
(520) 888-3055

NAME <b>SABU</b>		DATE <b>1-3-03</b>	
ADDRESS			
PHONE			
SOLD BY	CASH	C.O.D.	CHARGE
ON ACCT.	MDSE. RET'D		
QTY.	DESCRIPTION	AMOUNT	
	INDUBLC SHOOT WATLE UPON BRAKING AND LEFT TURN. POSSIBLE COOLING FAN TO RADIATION SHROUD RUBBING WAS FOUND		
	PAID LABOR		25 00
	MIC		
	TAX		
RECEIVED BY	TOTAL		

3231

**NEBS** To Reorder:  
800-225-6380 or nebs.com

**Thank You**

All claims and returned goods MUST be accompanied by this bill.

**ERNIE'S BRITISH CARS, PARTS & SERVICE, INC.**

1121 West Wetmore Road  
TUCSON, ARIZONA 85705  
(520) 888-3055

NAME <b>SABU</b>		DATE <b>12/16/02</b>	
ADDRESS			
PHONE			
SOLD BY	CASH	C.O.D.	CHARGE
ON ACCT.	MDSE. RET'D		
QTY.	DESCRIPTION	AMOUNT	
	FLUSH COOLANT SYSTEM. REPAIR RADIATOR TAP. CLEAR BLOCK DRAIN VALVES.		
	EMISSIONS CHECK ADJUST AIR FUEL MIXTURE		
	LABOR \$45/HR 3-0HR		135 00
	PAID		
	MIC		
	TAX		
RECEIVED BY	TOTAL		

3188

**NEBS** To Reorder:  
800-225-6380 or nebs.com

**Thank You**

All claims and returned goods MUST be accompanied by this bill.













# LONE WOLF

ROLLS ROYCE • BENTLEY  
SERVICE • REPAIR • RESTORATION  
12301 MILLS AVE., NO. 25  
CHINO, CA 91710  
PHONE (909) 464-1877/FAX (909) 464-1876



LONE WOLF

5369 9300 4094 0779  
MASTECARD  
DATE 7-26-01  
RES. PHONE  
CHECK CHARG  
CASH

NAME SABA ADVANI LICENSE NO. 833 KR  
ADDRESS 15108  
YEAR 07 MODEL Y SERIAL NO. 5BX 1950 MAKE BENTLEY  
MILEAGE 15108

I, the Registered Owner, authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted heretofore is an estimate only. Your employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. I agree to pay reasonable storage on vehicle left more than 48 hours after notification that repairs are completed. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto, including those from any prior work or repair contract on this vehicle. In the event an attorney is retained to foreclose this lien or bring suit for collection on any sums due, I agree to pay cost of collection and reasonable attorney fees.

Authorized by: \_\_\_\_\_

## LABOR INSTRUCTIONS

3,000 MILE 3 MONTH SERVICE 180.00

INSTALL AUX. STARTER SWITCH

WIRE THROUGH RIGHT SIDE BUCK HEND USING

FACTORY BUCK HEND CONNECTORS, WIRE TO

SWITCH LOCATED NEAR HAND BRAKE

LEATHER TRIM SURROUND, 360.00

QUAN.	PART NO.	DESCRIPTION	PRICE
1	UV 30809 PA	BENTLEY SW.	47.95
1	RH 10003	OIL FILTER	36.00
		MISC ELECTRICAL	65.00
TOTAL PARTS			148.95

BRAKE PADS — APPROX. % REMAINING		FRT.	REAR	TOTAL LABOR
SUBLET		QTS. OIL @ 3.65	29.20	540.00
ENVIRONMENTAL	350	QTS. ATF @ 2.65	2.65	148.95
FRETSHT	800	90 WT	3.50	11.50
		GREASE	3.50	
		MARVEL MYSTERY	12.50	
		TOTAL	51.35	
		OIL & FLUIDS		51.35
		TAX		15.02
		TOTAL		766.82



# LONE WOLF

ROLLS ROYCE • BENTLEY  
SERVICE • REPAIR • RESTORATION  
12301 MILLS AVE., NO. 25  
CHINO, CA 91710  
PHONE (909) 464-1877/FAX (909) 464-1876



DATE **7-10-1999**  
DEC PHONE **805**  
RINS PHONE **89**  
CASH CHECK CHARGE  
LICENSE NO. **833KB3**  
MILEAGE

NAME **SABU ADJANI** SERIAL NO. **SBX 1950** MAKE **BENTLEY**  
ADDRESS **5456 ROCK 90041**

RETURN OLD PARTS  
 YES  NO  
DATE TIME AUTHORIZED BY  
DATE TIME AUTHORIZED BY

ORIGINAL ESTIMATE \$  
REVISED ESTIMATE \$  
REVISED ESTIMATE \$

LABOR INSTRUCTIONS  
**REPLACE ALL RIGHT REAR TAIL LIGHT LENSES**  
**REPLACE (1) BULB, CLEAN UP BROKEN PARTS. 65.00**  
**REPLACE ONE WHEEL COVER AND CONVERT**  
**BEQUITY TRIM RIMS FROM OLD CAR TO NEW CAR. 65.00**

I, the Registered Owner, authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted heretofore is an estimate only. Your employees may operate vehicle or inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. I agree to pay reasonable storage on vehicle left more than 48 hours after notification that repairs are completed. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs hereto, including those from any prior work or repair contract on this vehicle. In the event an attorney is retained to foreclose this lien or bring suit for collection on any sums due, I agree to pay cost of collection and reasonable attorney fees.

Authorized by:

QUAN.	PART NO.	DESCRIPTION	PRICE
1	CD 5741	LENS	30.64
1	CD 4864	REAR LENS	34.04
1	CD 5714	LENS REVERSE	15.22
1	RD 6602	BULB	6.78
1	RH 20590	DISP	29.94
1	WS 12135	HYB CAP	520.00
6	WS 4158	SPIRE NMTS	25.30
TOTAL PARTS			661.88

BRAKE PADS — APPROX. % REMAINING	FRT.	REAR	TOTAL LABOR
SUBLET	QTS. OIL @		130.00
<b>FRESH (VIA ENCLMD) 23.95</b>	QTS. ATF @		661.88
			23.95
			GAS
			OIL & FLUIDS
			TAX
			51.29
			TOTAL
			867.12













# LONE WOLF

ROLLS ROYCE • BENTLEY  
SERVICE • REPAIR • RESTORATION  
12301 MILLS AVE., NO. 25  
CHINO, CA 91710  
PHONE (909) 464-1877/FAX (909) 464-1876

DATE 4-24-99  
PAGE 1  
CASH CHECK CHARGE BI  
LICENSE NO. 833 KBJ  
MILEAGE 110,978 KM

NAME SABY ADUAN I  
ADDRESS 15LE ROCK CA 90041  
SERIAL NO. SBX 1950  
MODEL 07  
YEAR 07  
MAKE BOUTLEY

RETURN OLD PARTS  
 YES  NO  
DATE TIME AUTHORIZED BY  
DATE TIME AUTHORIZED BY

LABOR INSTRUCTIONS

HYDRAULIC PRESSURE TEST  
SYSTEM # 1 SYSTEM # 2  
NITROGEN PRESS. 900 LBS. 700 LBS.  
MAXIMUM PRESS. 2200 LBS. 2350 LBS.  
RECOVERY PRESS. 1700 LBS. 1900 LBS. (VARIES)  
PRESS. SW. PRESS. 900 LBS. STOPS AT 700 LBS.  
BOTH BRAKE PUMPS HAVE VERY LOW PRESSURE BUILD UP.  
TEST LAMP QUADRANT IN OP; R/R DASH AS NEEDED  
TO GAIN ACCESS FOR TESTING, FOUND LOOSE CONNECTION  
BEHIND ALUMINUM SWITCH.  
NO START - INTERMITTENT; REMOVE STEERING BEZEL AND  
CHECK SHIFTER CONTACTS, CLEAN CONTACTS, REPLACE  
FRAME MOUNTED STARTER SOLENOID (ORIGINAL) REPLACE  
CONNECTIONS AS NEEDED.  
BRAKE LIGHTS INTERMITTENT; R/R RAT TRAP COVER -  
REMOVE SWITCH FOR INSPECTION, REBUILD SWITCH-ADJUST,  
R/R BOTH BRAKE PRESSURE SWITCHES FOR OVERHAULING

QUAN.	PART NO.	DESCRIPTION	PRICE
1	MISC ELECTRICAL	CONNECTIONS	32.00
1	WD 15723	SOLENOID	37.68
2	DB 525	CONTACTS	13.56
1	CD 4758	KIT SEAL	77.18
1	CD 6083	GASKET KIT	82.18
4	CD 639	GASKET R	92.20
3	CD 641	GASKET R	44.08
2	CK 610	RINGS	10.10
2	WE 2513	SEAL RINGS	26.64
2	WD 18721	DIAPHRAGMS	51.08
2	WD 17876	PLUNGES	34.04
1	CD 633	ELEMENT	23.82
1	CD 660	BEARINGS	94.18
1	831-8 1/2'	AS RETURN HOSE	12.50
1	WE 35972	IGNITION COIL	60.55
2	WE 40534	HBSX BRAKE PUMPS	119.24
4	SPE 1957	SEAL RINGS	53.36
2	WE 35616	SEAL RINGS	9.26
1	WE 34105	RESISTOR BLOCK	34.56
2	00 JMBILEE	CLAMPS	11.90
		TOTAL PAGE 1	2032.94
		TOTAL PAGE 2	1105.00
		GROSS TOTAL	3137.94
		PAID INT-FULL	VISA 3/2002
		4264 2900	700 2472

BRAKE PADS — APPROX. % REMAINING	FRT.	REAR	TOTAL LABOR
SUBLET			552.30
FRESHAT	32.18		1860.11
FRESHAT	24.00		56.18
			20.00
			OIL & FLUIDS
			TAX
			144.15
			TOTAL
			2622.94

I, the Registered Owner, authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted heretofore is an estimate only. Your employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. I agree to pay reasonable storage on vehicle left more than 48 hours after notification that repairs are completed. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto, including those from any prior work or repair contract on this vehicle. In the event an attorney is retained to foreclose this lien or bring suit for collection on any sums due, I agree to pay cost of collection and reasonable attorney fees.

Authorized by:







1701

**JIM RICKMAN**  
 3240 E. Colorado Blvd.  
 PASADENA, CALIFORNIA 91107  
 (818) 793-5397  
 REG. #AC171388

DATE IN: 4/9/98 A.M. P.M.  
 DATE PROMISED: \_\_\_\_\_ A.M. P.M.  
 CUSTOMER ORDER NO. \_\_\_\_\_ ORDER WRITTEN BY \_\_\_\_\_  
 BUS. PHONE \_\_\_\_\_ EXT. \_\_\_\_\_  
 HOME PHONE \_\_\_\_\_  
 LICENSE NO. 833 KBT MILEAGE 09065 KLS  
 MECHANIC/TECHNICIAN  
 CALL WHEN READY  YES  NO  
 TERMS \_\_\_\_\_

NAME: Saban  
 ADDRESS: \_\_\_\_\_  
 CITY: \_\_\_\_\_ STATE: \_\_\_\_\_ ZIP: \_\_\_\_\_  
 YEAR, MAKE AND MODEL: 67 Bentley T  
 SERIAL NO./V.I.N. \_\_\_\_\_

SERVICES REQUESTED/DESCRIPTION OF WORK		AMOUNT
check for short in wiring		
correct trunk lock		
put Bentley cut off switch		
<div style="border: 1px solid black; border-radius: 50%; padding: 10px; display: inline-block;">           Paid #448         </div>		
TOTAL PARTS		

ESTIMATED COSTS		TOTAL
PARTS	LABOR	TOTAL
AUTHORIZED BY	<input type="checkbox"/> IN PERSON <input type="checkbox"/> BY PHONE	
DATE	TIME	CALL BY
REVISED ESTIMATE / ADDITIONAL WORK		
PARTS	LABOR	TOTAL
AUTHORIZED BY	<input type="checkbox"/> IN PERSON <input type="checkbox"/> BY PHONE	
DATE	TIME	CALL BY
TOTAL LABOR		260.00
TOTAL PARTS		39.45
TOTAL SUBTOTAL		
GAS, OIL AND GREASE		
EPA / WASTE DISPOSAL		
TAX		3.25
TOTAL		302.70

QTY.	PART NO. AND DESCRIPTION (All parts new unless otherwise specified)	AMOUNT
1	Ground Cable	4.50
1	Wiring short off switch	34.95
		394.5
TOTAL PARTS		

VEHICLES LEFT AFTER COMPLETION WILL BE CHARGED STORAGE AT \$10.00 A DAY  
 Estimated cost for teardown and reassembly, \$ \_\_\_\_\_  
 TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within \_\_\_\_\_ days of the date shown above if I choose not to authorize the services recommended.  
 SIGNATURE \_\_\_\_\_ DATE \_\_\_\_\_  
 I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control.  
 SIGNATURE \_\_\_\_\_ SAVE OLD PARTS  YES  NO















# LONE WOLF

ROLLS ROYCE • BENTLEY  
SERVICE • REPAIR • RESTORATION  
12301 MILLS AVE., NO. 25  
CHINO, CA 91710  
PHONE (909) 464-1877/FAX (909) 464-1876



LONE WOLF

DATE 9-97  
RES. PHONE 705-378-87  
MASTERCARD  
CASH  CHECK  CHARGE

LICENSE NO. 833 KBJ  
MILEAGE 107076  
LE ROCK CA 90041  
MAKE BENTLEY

NAME SABU ADWINI  
ADDRESS LE ROCK CA 90041  
YEAR 67 MODEL T SERIAL NO. SBX 1950 MAKE BENTLEY

I, the Registered Owner, authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted heretofore is an estimate only. Your employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. I agree to pay reasonable storage on vehicle left more than 48 hours after notification that repairs are completed. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereon, including those from any prior work or repair contract on this vehicle. In the event an attorney is retained, to foreclose this lien or bring suit for collection on any sums due, I agree to pay cost of collection and reasonable attorney fees.

RETURN OLD PARTS  
 YES  NO  
AUTHORIZED BY  
DATE TIME DATE TIME  
AUTHORIZED BY  
DATE TIME DATE TIME

LABOR INSTRUCTIONS

1 YEAR SERVICE  
REPLACE IGNITION WIRES  
REMOVE DISTRIBUTOR AND DIS-ASSEMBLE  
INSPECT / CLEAN / REPLACE PARTS AS NEEDED

QUAN.	PA. NO.	DESCRIPTION	PRICE
1	RA10003	OIL FILTER KIT	35.00
1	TY 393	IGNITION WIRES	15.12
1	TY 394	IGNITION WIRES	15.12
1	CD 3044	DIST CAP	105.77
1	CD 3046	ROTOR ARM	37.02
2	CD 3047	CONTACTS	35.54
1	CD 3049	CONDENSOR	26.81
1	GR 19273	FORM	12.62
1	WBART	BRAKE CLEAN	5.95
1	CARB	CLEAN	5.95
1	MISC	SUPPLIES	8.00
2	2Y05	PLUGS	46.80
TOTAL PARTS			622.38

*See next card  
9/10/97*

BRAKE PADS — APPROX. % REMAINING	FRT.	REAR	TOTAL LABOR
SUBLET	12	2,402880	450.00
FREIGHT	5.75		622.38
		GREASE 3.50	
		90 WT 3.50	
		OIL & FLUIDS 35.80	
		TAX 51.01	
		TOTAL	1164.94

# SMOG CHECK VEHICLE INSPECTION REPORT

## PUBLIC AWARENESS STATEMENT

SMOG CHECK IS MAKING A DIFFERENCE - AND YOU ARE HELPING. EMISSIONS HAVE BEEN REDUCED BY MORE THAN 50 PERCENT ON VEHICLES FAILING A SMOG CHECK INSPECTION. KEEP YOUR VEHICLE TUNED UP AND IN GOOD RUNNING CONDITION BETWEEN SMOG CHECKS AND USE PUBLIC TRANSIT WHENEVER YOU CAN. WORKING TOGETHER, WE CAN CONTINUE TO IMPROVE OUR AIR QUALITY.

### OVERALL TEST RESULT:

**PASSED**

CERTIFICATE OF COMPLIANCE ISSUED W85983547

Initial Smog Check Performed on: FEB 04, 1997 at 03:35 PM

### CONGRATULATIONS!

Your vehicle has passed the California Smog Check Inspection.

### EMISSION CONTROL SYSTEM UNDERHOOD INSPECTION RESULTS

PCV system	PASS
Carburetor	PASS
Other Emissions Related Components	PASS

### MANUAL FUNCTIONAL CHECK RESULTS

Ignition Timing	PASS
VEHICLE'S IDLE IGNITION TIMING	26° BTDC

### EMISSION TEST RESULTS

#### 2500 RPM

	<u>MAXIMUM ALLOWABLE EMISSIONS</u>	<u>AVERAGE EMISSIONS</u>	<u>MEASURED</u>	<u>RESULT</u>
HC PPM	0600	0187	0218	PASS
CO %	4.50	01.70	0.59	PASS
CO2			11.3	
O2			0.0	
RPM			2637	

#### IDLE RPM


	<u>MAXIMUM ALLOWABLE EMISSIONS</u>	<u>AVERAGE EMISSIONS</u>	<u>MEASURED</u>	<u>RESULT</u>
HC PPM	0700	0117	0305	PASS
CO %	5.50	02.30	3.39	PASS
CO2			10.8	
O2			0.5	
RPM			2829	



VEHICLE IDENTIFICATION INFORMATION

License Plate Number	833K8J
License Issuing State	CALIFORNIA
Vehicle ID Number (VIN)	8BX1958
Vehicle Type	PASSENGER CAR
Vehicle Make	BENTLEY
Vehicle Model	T-SERIES SEDAN
Vehicle Model Year	87
Number of Cylinders	8
Vehicle Engine Size	6.2L
Transmission Type	AUTOMATIC
Certification Type	CALIFORNIA
Odometer Reading	89200
Test Type	INITIAL INSPECTION
Vehicle Fuel Type	GASOLINE
Type of Exhaust	SINGLE
Inspection Reason	BIENNIAL INSPECTION
DMV ID	299129998710

The true and correct odometer reading is 89200.  
I certify, to the best of my knowledge, under penalty  
of perjury under the laws of the State of California that  
the mileage information herein is true and accurate.

  
\_\_\_\_\_  
Technician's Signature

STATION IDENTIFICATION INFORMATION

SMOG PROS  
144 N. VERDUGO RD.  
GLENDALE, CA 91206-8000

Station Telephone	818-241-1643
Station Number	PK163252
Mechanic's Qualification Number:	EU304144
Mechanic's Name:	HAJJDAD SAMIR SALIM
Software Version	9611

The vehicle described above has been inspected in  
accordance with all bureau requirements and the  
information listed on this vehicle inspection report  
is true and correct.

  
\_\_\_\_\_  
Technician's Signature

Results communicated

YOUR ELECTRONIC CERTIFICATE WILL AUTOMATICALLY BE TRANSMITTED TO THE DMV.  
RETAIN THIS COPY FOR USE ON RETEST OR AS A RECEIPT FOR DMV  
DO NOT MAIL THIS FORM TO DMV  
UNLESS REQUESTED BY DMV







LONE



WOLF

# LONE WOLF

ROLLS ROYCE • BENTLEY  
 SERVICE • REPAIR • RESTORATION  
 12301 MILLS AVE., NO. 25  
 CHINO, CA 91710  
 PHONE (909) 464-1877/FAX (909) 464-1876

DATE: 10-25-96  
 RES. PHONE: \_\_\_\_\_  
 CASH: \_\_\_\_\_ CHECK: \_\_\_\_\_ CHARGE: \_\_\_\_\_  
 MAKE: BENTLEY  
 LICENSE NO: 853KBS  
 MILEAGE: 104,925 KM

NAME: SARY ADAMI / JUDY WALKER  
 ADDRESS: 166E ROCK CA 90041  
 SERIAL NO: SBY 1950  
 MAKE: BENTLEY  
 YEAR: 67 MODEL: "T"

RETURN OLD PARTS: YES  NO   
 AUTHORIZED BY: \_\_\_\_\_ DATE: 10/25/83  
 AUTHORIZED BY: \_\_\_\_\_ DATE: \_\_\_\_\_  
 REVISSED ESTIMATE \$: 8879.83  
 REVISSED ESTIMATE \$: \_\_\_\_\_

### LABOR INSTRUCTIONS

REPLACE COMPLETE EXHAUST SYSTEM. 270.00  
 REMOVE OIL PAN FOR INSPECTION, REPLACE OIL PAN GASKET CLEAN OIL PAN INSIDE AND OUT. 450.00  
 CLEAN UP FRONT END TIE ROD LINK ARMS ETC. 90.00  
 REPLACE BOTH OUTER BOOTS. REPLACE BOTH STEERING ARM AND DAMPER ARM BOOTS. 90.00  
 CHECK OIL LEVER SENDER/CIRCUIT FOR FUNCTION. 45.00  
 REPAIR OIL LEVER SENDER - BROKEN WIRES INSIDE UNIT. 90.00  
 RESEAL FRONT TIMING COVER COMPLETE. 630.00  
 ADD EXTRA TIME FOR EXCESSIVE DIRT DEPOSITS. 90.00  
 ADD EXTRA TIME FOR FROZEN CRANK FULLY REMOVAL. 90.00  
 REMOVE OIL PUMP FOR INSPECTION, DIS-ASSEMBLE COMPLETE (BENCH WORK) INSTALL NEW RELIEF VALVE AND SPRINGS (WEAK). REPLACE ALL SEALS AND GASKETS. 180.00  
 CLEAN UP OIL PUMP PICK UP AND TUBES. 135.00  
 RGR OIL FILTER HOUSING TO CHECK RELIEF VALVE OPERATIONS / FRONT HAIR LINE CRACK (REPAIR SUBLET).  
 REPAIR LOWER TIMING COVER TO FRONT MOTOR MOUNT. 270.00  
 IN CAR AFTER INSTALLATION 2 TIMES. THROATS PULLED (SUBLET)

BRAKE PADS - APPROX. % REMAINING		FRT.		REAR		TOTAL LABOR
QTS. OIL @	2.35	21	15			TOTAL PARTS 2499.47
QTS. ATF @	2.20	13	20			SUBLET 369.27
GREASE		3	50			GAS
EXHAUST WELDING		85	00			OIL & FLUIDS 37.85
FREIGHT		44	27			7,759 TAX 196.64
TOTAL		37.85				TOTAL 5443.23

QUAN.	PART NO.	DESCRIPTION	PRICE
1	WD-11662	TEMP. TRANS MITTER	38.00
1	RH-10003	OIL FILTER KIT	35.66
1	SM-400	TRANS. ELEC. COMM.	12.50
1	LAE-73915	OIL PUMP GASKET	5.60
1	LAR-16154	FAN COWL	136.49
1	LAR-16156	FAN COWL	136.49
1	LAR-16155	FAN COWL	222.50
1	LAE-73635	THERM. GASKET	10.60
1	LAD-20505	COVER (OILER)	26.90
2	LAD-20506	ROLL PIN COMM.	11.24
1	LAE-70684	OUTLET THERMIDSTAT	196.25
2	LAR-12187	TIE ROD END BOOTS	12.16
2	LAR-14673	TIE ROD END BOOTS	23.08
2	LE-5710	OIL FILTER HANG. GSKTS.	7.10
1	CK-865	OIL DIP STK SEAL	4.55
1	2309	WIRE BRUSH	8.49
2	252x6	FITINGS	10.60
2	3300x6	FITINGS	13.80
1	30 AMP	CIRCUIT BREAKER	12.50
1	30 AMP	REZAM	34.00
	MISC. ELECTRICAL WIRES/COMM/ETC.		140.00
2	FS 10A-2	10" PUSHER FANS	350.00
1	5562	5/16x24 BLS SECT KIT	60.05
1	ME-5204	OIL PUMP PIPE GSKT	5.65
1	ME-39592	FAN SENSOR	142.11
1	ME-38753	GASKET SENSOR	5.42
3	X-1913-2	SCREEN 2 BA	14.70
1	ME-37118	W/P 134 PASSERBOW	113.15
1	ME-37117	134 PASS BOBBIN	165.83
2	RE-25307	HAZ F CLAMPS	70.04
1	LR-5367	ALIVE RING	35.02
2	LR-5666	EXHAUST BOLTS	18.88
1	7881	BLACK AEROSOL	7.27
1	7922	SILVER AEROSOL	7.27
1	BK-770	1806 SHROUD SEALS	12.00
	WURTH SEALANTS		15.00
	MISC. NUTS BOLTS / HARDWARE		70.00
1	CD-4082	FRONT CALIPER KITS	99.65
4	RR-363	BRAKE FLUID	66.00
24	WURTH	BRAKE CLEANER	142.80
TOTAL PARTS			2499.47

I, the Registered Owner, authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted hereon is an estimate only. You will not be responsible for loss or damage to vehicle or inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. I agree to pay reasonable storage on vehicle left more than 48 hours after notification that repairs are completed. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto, including those from any prior work or repair on this vehicle. In the event an attorney is retained to foreclose this lien or bring suit for collection on any sums due, I agree to pay cost of collection and reasonable attorney fees.

Authorized by: *Sary Adami*







**Wayne's Tire, Inc.**

PLEASE REMIT TO:  
 P.O. Box 6150 - Santa Maria, CA 93456  
 Business Office (805) 925-0454

- 125 W. Main St  
Santa Maria, CA 93454  
925-0971
- 302 Betteravia  
Santa Maria, CA 93455  
928-2661
- Hwy 101 & 46 West  
Paso Robles, CA 93446  
238-7880
- 303 E. Ocean Ave.  
Lompoc, CA 93436  
736-3103 or 736-9973

TELEPHONE: \_\_\_\_\_  
 VEH: \_\_\_\_\_  
 LIC NO. \_\_\_\_\_

MIL. ◀

ACCOUNT NO.	INVOICE DATE	INVOICE NO.

TIRES • ALIGNMENT • BRAKES  
 SHOCKS • RETREADING • ROAD SERVICE

O I D L O S

O I D L O S

CONTROL NO.	ORDER DATE	CUST. ORDER NO.	SLS	TERMS	DATE SHIPPED	SHIPPED VIA	SLS ORDER
66058	06-22-96			DASH	06-22-96	BOR # AG 154918	

ITEM NO	DESCRIPTION	QUANTITY	ORDERED	B/O	SHIPPED	F.E.T.	PRICE	EXTENSION
---------	-------------	----------	---------	-----	---------	--------	-------	-----------

01322	215/7516 MICH XM4 WMT NO TIRE LEFT FOR DISPOSAL	4					89.75	355.00
134187								

NECESSARY MATERIALS, YOU AND YOUR EMPLOYEES MAY OPERATE  
 VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY  
 JUNE THE AMOUNT OF REPAIRS THERE TO, YOU WILL NOT BE HELD  
 RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN  
 VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT, DAMAGE FROM FREEZING DUE  
 TO LACK OF ANTI-FREEZE OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

YES PARTS RETURNED UPON  
 REQUEST, BEFORE JOB  
 NO STARTS FOR REPAIRS

ACCOUNT CHARGES ARE DUE AND PAYABLE. ALL  
 CLAIMS AND RETURNED GOODS MUST BE  
 ACCOMPANIED BY THIS BILL AS TERMS INDICATED.

SUB TOTAL 355.00  
 SALES TAX 25.74

INVOICE TOTAL



380.74

MINIMUM FINANCE CHARGE \$1.50.

SIGNATURE









**LONE WOLF**  
 ROLLS ROYCE • BENTLEY  
 SERVICE • REPAIR • RESTORATION  
 12301 MILLS AVE., NO. 25  
 CHINO, CA 91710  
 PHONE (909) 464-1877/FAX (909) 464-1876

DATE 10-14-95  
 RES. PHONE 705  
 CHECK CHARGE  
 CASH  
 LICENSE NO. 833 KBJ  
 MILEAGE 101,855  
 MAKE BENTLEY

NAME SABY ADVANT  
 ADDRESS 166E ROCK CA. 90041  
 SERIAL NO. SBY 1950  
 YEAR 67  
 ORIGINAL ESTIMATE \$  
 REVISD ESTIMATE \$ 3302.40  
 REVISD ESTIMATE \$

RETURN OLD PARTS  
 YES  NO  
 AUTHORIZED BY  
 DATE TIME  
 AUTHORIZED BY  
 DATE TIME

LABOR INSTRUCTIONS

LOW COOLANT CAMP W/OP; REPLACE THERMOSTAT 22 50  
 R/R DASH ROLL - CONVERT EARLY LOW COOLANT 180 00  
 AMPLIFIER TO NEW TAPE / REPAIR COIL WIRE. }  
 REPAIR WIRING AT SURGE TANK PROBE. }  
 SURGE TANK BAFFLE LOOSE! }  
 R/R SURGE TANK (SUBLET REPAIR BAFFLE AND }  
 RESOLDER 2 HALVES) RESTORE AND COMPLETELY }  
 RESALC SURGE TANK, REPLACE ALL (4) COOLANT HOSES }  
 R/R RADIATOR FOR RECORDING, MODIFY RADIATOR }  
 BRACKETS FOR ADAPTING FAN SHROUD UPDATE (AT }  
 A LATER DATE) RE-CONDITION W/P PULLEY & FAN }  
 REPLACE ALL 4 DRIVE BELTS }  
 OVERHAUL & RESTORE WATER PUMP }  
 SERVICE TRANS MISSION - REPLACE TRANS }  
 COOLER WATER HOSES AND CLAMPS, REPAIR }  
 LEAK AT TRANS COOLER HARD LINES, RESTORE FAN }  
 REPLACE FRONT MOTOR MOUNT }  
 REPLACE LEFT REAR MOTOR MOUNT (TORN) }  
 REPLACE AIR FILTER WITH NEW STYLE PAPER TYPE }

BRAKE PADS - APPROX. % REMAINING		FRT.	REAR	TOTAL LABOR
SUBLET				1282 50
SURGE TANK REPAIR	8	QTS. OIL @		1766 51
DIS-ASSEMBLE	8	QTS. ATF @ 2.40	19 20	115 00
COMPOSITE - RE	290 00			
PARTS BAFFLE				
RE SOLDER COMPLETE				
BEAD BASTING	25 00			19 20
TAX				138 39
TOTAL				3302 40

QUAN.	PART NO.	DESCRIPTION	PRICE
1	RADIATOR	RECORD	395 00
3	BLACK ENGINE	PAIN	17 85
1	WD-14927	COOLANT AMPLIFIER	139 47
1	RH-2667	COOLANT RELIEF VALVE	127 30
1	UE-3086	WASHER SEAL	18 20
1	UE-3088	GASKET	4 18
1	UR-11325	COOLANT PROBE	114 14
1	UA-11325	"O" RING	3 85
1	UR-13701	CIRCLIP	2 94
4	UA-11401-2	PROBE NUTS	14 76
1	UR-5538	SEAL/CAP	33 72
1	RH-9266	BERT TWIN	48 64
1	UE-32658	FAN BELTS	56 26
1	UR-19203	FRONT ENG MOUNT	83 80
1	RH-10166	-SP W/P SET	215 36
1	UE-36000	2 THERMOSTAT	49 10
1	UE-31232	THERM. GASKET	2 10
1	UR-17759	2 HOSE NRT	39 96
1	UR-17762	2 HOSE TOP	43 48
1	UR-17761	2 HOSE BOTTOM	44 72
2	UR-2424	STAINLESS CLAMPS	12 40
2	UR-2428	STAINLESS CLAMPS	12 40
2	UR-2410	STAINLESS CLAMPS	10 40
2	UR-00149	CLAMPS	9 90
1	1 FT 5/16	HYDRAIC HOSE	12 95
1	UR-15238	COOLANT PROBE BOOT	14 73
1	UE-36200	AIR FILTER	39 92
4	UR-2408	STAINLESS STEEL CLAMP	20 40
1	5/8	HEATER HOSE	12 00
1	UR-14551	TRANS FILTER	43 10
1	UR-14546	TRANS GASKET	11 95
1	UR-14432	TRANS GEAR PINS	13 05
1	UR-13402	MOD MOTOR "O" RING	2 16
1	UR-19204	REAR ENGINE MOUNT	89 00
1	PRESTONE	COOLANT	4 50
2	ARROW HEAT	DISTILLED WATER	34 50
	BALANCE DUE	\$ 1802.40	
	PAYD CHECK #	202	
	TOTAL PARTS		1766 51





**LONE WOLF**  
 ROLLS ROYCE • BENTLEY  
 SERVICE • REPAIR • RESTORATION  
 12301 MILLS AVE., NO. 25  
 CHINO, CA 91710  
 PHONE (909) 464-1877/FAX (909) 464-1876

DATE 8-18-95  
 RES. PHONE ---  
 BUS. PHONE ---  
 LICENSE NO. 833-KBS  
 MILEAGE 101113 KM

NAME SABY ADUANI SERIAL NO. SBX 1950 MAKE BENTLEY  
 ADDRESS EASLE ROCK 90041

ORIGINAL ESTIMATE \$ 203.59 RETURN OLD PARTS  YES  NO  
 REVISED ESTIMATE \$ 100 AUTHORIZED BY \_\_\_\_\_  
 REVISED ESTIMATE \$ \_\_\_\_\_ AUTHORIZED BY \_\_\_\_\_

LABOR INSTRUCTIONS

SERVICE COOLING SYSTEM  
OIL PRESS LAMP COME ON AT TIMES  
AT IDLE  
REPLACE OIL PRESSURE SWITCH  
3 000 MILE 3 MONTH SERVICE  
SMOS CERTIFY  
SUBLET

PAID #191  
CHECK #100

QUAN.	PART NO.	DESCRIPTION	PRICE
1	RH 10003	OIL FILTER KIT	35.66
1	PRESTONE	COOLANT	8.50
2	ARBOROW HEAD	DISTILLAD WATER	3.50
1	RISKONE	LIFTER ADDITIVK	4.95
1	OIL PRESSURE	SWITCH	12.50
TOTAL PARTS			65.11

BRAKE PADS — APPROX. % REMAINING		FRT.	REAR
SUBLET	8	QTS. OIL @ 2.10	19.20
SMG	32.70	QTS. ATF @	---
		GREASE	3.50
		90 WT	3.50
TOTAL LABOR		112.50	
TOTAL PARTS		65.11	
SUBLET		32.70	
GAS		20.00	
OIL & FLUIDS		20.20	
TAX		7.00	
TOTAL		263.50	

I, the Registered Owner, authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted herebefore is an estimate only. Your employees may operate vehicle or inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. I agree to pay reasonable storage on vehicle left more than 48 hours after notification that repairs are completed. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto, including those from any prior work or repair contract on this vehicle. In the event an attorney is retained to foreclose this lien or bring suit for collection on any sums due, I agree to pay cost of collection and reasonable attorney fees.

Authorized by: \_\_\_\_\_