

1992
Land Rover
Range Rover HSE

SALHV1246NA618427





Vehicle History Report™

US \$39.99

1992 LAND ROVER RANGE ROVER VIN: SALHV1246NA618427 4 DOOR WAGON/SPORT UTILITY 3.9L V8 F GASOLINE ALL WHEEL DRIVE	<input checked="" type="checkbox"/>	No accidents or damage reported to CARFAX
		7 Service history records
		CARFAX 1-Owner vehicle
		Last owned in California
		24 Detailed records available
		148,136 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/4/22 at 3:47:14 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History The number of owners is estimated		Owner 1
Year purchased		1992
Type of owner		—
Estimated length of ownership		29 yrs. 9 mo.
Owned in the following states/provinces		California
Estimated miles driven per year		5,130/yr
Last reported odometer reading		148,136

CARFAX Title History CARFAX guarantees the information in this section		Owner 1
Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/>	Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/>	Guaranteed No Problem
GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. Register View Terms View Certificate		

CARFAX Additional History Not all accidents / issues are reported to CARFAX		Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/>	No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/>	No Issues Reported

Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check with an authorized Land Rover dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty No data reported to CARFAX.	No Data Reported

CARFAX Detailed History

Owner 1




Purchased:
1992



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

5,130 mi/yr

Date	Mileage	Source	Comments
09/02/1992		California Motor Vehicle Dept.	Title issued or updated - First owner reported
08/18/1995	35,045	California Inspection Station Santa Rosa, CA	Passed emissions inspection
08/02/1999	69,888	Service Facility Santa Rosa, CA	Vehicle serviced
08/02/1999		California Inspection Station Santa Rosa, CA	Passed emissions inspection
08/15/1999		California Motor Vehicle Dept. Santa Rosa, CA	Title issued or updated
08/20/2001	80,236	Service Facility Santa Rosa, CA	Vehicle serviced
08/20/2001		California Inspection Station Santa Rosa, CA	Passed emissions inspection
06/13/2003	88,997	Service Facility Santa Rosa, CA	Vehicle serviced
06/13/2003		California Inspection Station Santa Rosa, CA	Passed emissions inspection
08/04/2003	90,557	Service Facility	Vehicle serviced
07/20/2005	99,403	California Inspection Station	Passed emissions inspection
08/08/2007	105,918	California Inspection Station	Passed emissions inspection
03/09/2009		California Motor Vehicle Dept. Santa Rosa, CA	Title issued or updated
06/08/2009	108,931	California Inspection Station Santa Rosa, CA	Passed emissions inspection

08/17/2011	121,928	California Inspection Station Santa Rosa, CA	Failed emissions inspection
08/22/2011	121,999	California Inspection Station Santa Rosa, CA	Passed emissions inspection
05/17/2012	125,095	Sears Auto Center Santa Rosa, CA 707-571-5628 searsauto.com ★ 4.4 / 5.0 29 Verified Reviews	 Vehicle serviced - Battery serviced - Tire condition and pressure checked
10/04/2013	129,357	California Inspection Station Santa Rosa, CA	Passed emissions inspection
08/24/2015	135,069	California Inspection Station Santa Rosa, CA	Passed emissions inspection
08/16/2017	140,797	California Inspection Station Santa Rosa, CA	Passed emissions inspection
04/11/2019	145,200	Mission Quik Lube Santa Rosa, CA 707-537-2040 missioncarwash.com ★ 4.4 / 5.0 23 Verified Reviews ♥ 110 Customer Favorites	 Vehicle serviced - Oil and filter changed
08/23/2019	145,524	California Inspection Station Santa Rosa, CA	Passed emissions inspection
08/27/2019	145,573	Big O Tires #005026 Santa Rosa, CA 707-528-2446 bigotires.com ★ 3.9 / 5.0 19 Verified Reviews ♥ 10 Customer Favorites	 Vehicle serviced - Tire(s) replaced
07/10/2021	148,136	California Inspection Station Santa Rosa, CA	Passed emissions inspection

Have Questions? Please visit our Help Center at www.carfax.com.



Glossary

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio,

Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:facebook.com/CARFAX[@CARFAXinc](https://twitter.com/CARFAXinc)**About CARFAX**

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2022 CARFAX, Inc., part of S&P Global. All rights reserved.
6/4/22 3:47:14 PM (CDT)

Invoice No.
 311112003

Order Date 11/12/21 02:55 pm
 Closed 4/16/2022

8092

Silberg, Dr Barry
 1111...
 707-...

92 Land Rover RANGE ROVER LS
 Mileage in:148908 out:148908
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 11/12/21 02:55pm 5519.69
 DR Silberg by phone 707-696-3

8092
 Deposit on repair- \$3500.00 11/12/21 2:56 pm visa

Job01 Transmission Replacement Labor: \$1,140.00

Including change transfer case oil

4HP22	REBUILT TRANSMISSION-N	1.0 @	3285.71 =\$	3285.71
ATF	TRAN/STR DOMSTC (pnts-N	16.0 @	8.73 =\$	139.68
C42666	BANJO WASHER (new styl-N	2.0 @	6.30 =\$	12.60
AT200	TRANS FLUSH KIT-N	1.0 @	44.48 =\$	44.48
ICV100000	SEAL, OUTPUT TFR CASE-N	1.0 @	32.31 =\$	32.31
ETC4524	EXHAUST FLANGE GASKET-N	2.0 @	12.68 =\$	25.36
250.8.25	STUD-N	6.0 @	6.20 =\$	37.20
369.8.135	EX MANIFOLD NUT(rov)-N	6.0 @	4.13 =\$	24.78 3602.12

Status: Completed Tech: SJD

Scheduled for: 02/23/22 08:30 am

Job Subtotal: \$4,742.12

Job02 Secure Seat Cover D.Side Labor: \$0.00

Reglue velcro trim and refit

Status: Completed Tech: SJD

Job Subtotal: \$0.00

Job03 Pass Front Window Down Not Up!! Labor: \$0.00

Cleaned switch contacts, works up/down now

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

----->----->----->-----Continued on the next page----->----->----->----->

Invoice No.
311112003

Order Date 11/12/21 02:55 pm
Closed 4/16/2022

8092

Job04 Rear Lighter Refit/Secure	Labor: \$0.00
---------------------------------	---------------

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Job05 Seat Release Behind Driver	Labor: \$198.50
----------------------------------	-----------------

Back seat does not tilt very well..., latch bound up, had to remove trim (was glued in place and broken) adjust and lubed latch, recheck operation and refit

Status: Completed Tech: SJD

Job Subtotal: \$198.50

Recommendations: Radiator seeping fluid out of left lower seem of tank, front swivel seals leaking worst now onto backing plates now (noted prior notes) right rear axle seeping fluid out of outer seal onto rotor hub. when performing axle repairs- service both diffs- both are marginal- transmission fluid level full- recommend to add anti slip additive and road test again.

****Prior Notes****

Coolant hoses including heater hoses need to be replaced- getting old and hard. Outer tie rod end left side dust boot split but no free play, seepage from front hub swivel seals, oil seeping head gasket and intake area . Possible transfer case chain getting loose, lots of noise from drivetrain when shift from drive to reverse and back...

Tire Pressure: LF[34] RF[34] LR [42] RR [42]

In Adherence With Guidelines For Essential Businesses During The Covid-19 Pandemic, Customer Signature May Not Have Been Available, Work May Have Been Authorized Verbally. (if no signature present on work order)

tWe assume no liability for theft or damage to vehicles left in our

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
311112003

Order Date 11/12/21 02:55 pm
Closed 4/16/2022

8092

at ANY time

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	1338.50
Parts	3602.12
Freight	150.00
Add Freight	300.00
Subtotal	5390.62
Tax	342.20
Total	\$5732.82

1 11/21/21 3500.00 Visa deposit
2 04/16/22 2232.82 On Acct
--A/R Pmt Allocations--
05/04/22 \$2,232.82
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 310811003

Order Date 08/11/21 09:32 am
 Closed/Paid: 08/11/21 03:07 pm

8827

92 Land Rover RANGE ROVER LS
 Mileage in:148273 out:148273
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 08/11/21 09:37am 433.14
 Dr in person.

8827

Job01 Trasmission Slipping? Labor: \$189.50

In the morning- goes to take off and seems to slip/hesitates

Status: Completed Tech: Dr.

Job Subtotal: \$189.50

Job02 (5/4.0) Rover Oil, Lube Service Labor: \$105.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL CASTROL (pnt)-N	13.0 @	4.60 =\$	59.80
ERR3340	OIL FILTER (rov)-N	1.0 @	43.07 =\$	43.07
00748	WASHER FLUID-N	1.0 @	4.98 =\$	4.98
ALU1403L	OIL DRAIN SEAL-N	1.0 @	4.39 =\$	4.39
46580	PARTS CLEANER/BRAKE-N	1.0 @	7.98 =\$	7.98
				120.22

Status: Completed Tech: GV

Job Subtotal: \$225.22

Job03 Seat Switch Secure Labor: \$0.00

Passenger seat switch loose

Status: Completed Tech: GV

Job Subtotal: \$0.00

Job04 Results- Labor: \$0.00

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
310811003

Order Date 08/11/21 09:32 am
Closed/Paid: 08/11/21 03:07 pm

8827

Job04 Results-

Radiator seeping fluid out of left lower seem of tank, front swivel seals leaking worst now onto backing plates now (noted prior notes) right rear axle seeping fluid out of outer seal onto rotor hub. when performing axle repairs- service both diffs- both are marginal- transmission fluid level full- recommend to add anti slip additive and road test again.

Status: Completed Tech: GV

Job Subtotal: \$0.00

Recommendations: Radiator seeping fluid out of left lower seem of tank, front swivel seals leaking worst now onto backing plates now (noted prior notes) right rear axle seeping fluid out of outer seal onto rotor hub. when performing axle repairs- service both diffs- both are marginal- transmission fluid level full- recommend to add anti slip additive and road test again.

****Prior Notes****

Coolant hoses including heater hoses need to be replaced- getting old and hard. Outer tie rod end left side dust boot split but no free play, seepage from front hub swivel seals, oil seeping head gasket and intake area . Possible transfer case chain getting loose, lots of noise from drivetrain when shift from drive to reverse and back...

Tire Pressure: LF[28] RF[28] LR [41] RR [41]

In Adherence With Guidelines For Essential Businesses During The Covid-19 Pandemic, Customer Signature May Not Have Been Available, Work May Have Been Authorized Verbally. (if no signature present on work order)

tWe assume no liability for theft or damage to vehicles left in our parking lot at ANY time

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
310811003

Order Date 08/11/21 09:32 am
Closed/Paid: 08/11/21 03:07 pm

8827

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Status: Closed Work Order

Payments: \$433.14

1 08/11/21 433.14 Visa

Labor	294.50
Parts	120.22
Haz Waste	7.00
Subtotal	421.72
Tax	11.42
Total	\$433.14
Payments	433.14
Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 301103002

Order Date 11/03/20 09:23 am
 Closed 11/7/2020

7855

Silberg, Dr Barry	92 Land Rover RANGE ROVER LS Mileage in:146854 out:146854 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	<u>Quotes</u> 1 11/04/20 11:40am 1507.57 <u>dr silberg by phone 707-528-0</u>
-------------------	--	---

Job01 Battery Fault- Labor: \$181.00

Customer states... had to jump start vehicle- Suspect battery fault... could not shift from part on first jump start of the vehicle- after shutting off and re starting- was able to shift vehicle...

Status: Completed Job Subtotal: \$181.00

Job02 Results- Labor: \$0.00

Battery will not take a charge- weak- Alternator not working correctly- comes and goes- will need a replacement alternator and replacement battery first and re check systems- service due by age- also per sticker in window, last service had incorrect oil viscosity used as well. factory calls for 20/50 to be used...

Status: Completed Job Subtotal: \$0.00

Job03 Battery- Labor: \$0.00

MTP-24	BATTERY (4.0/6 ROV)-N	1.0 @	208.56 =\$	208.56	208.56
--------	-----------------------	-------	------------	--------	--------

Status: Completed Job Subtotal: \$208.56

Job04 (E5) 92-95 Replace Alternator Labor: \$217.20

Test alternator as required. Remove and replace with exchange unit.

0986URO701	ALTERNATOR-BOSCH-N	1.0 @	589.92 =\$	589.92	589.92
------------	--------------------	-------	------------	--------	--------

Status: Completed Tech: GV Job Subtotal: \$807.12

Job05 (5/4.0) Rover Oil, Lube Service Labor: \$84.00

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
 301103002

Order Date 11/03/20 09:23 am
 Closed 11/7/2020

7855

Job05 (5/4.0) Rover Oil, Lube Service

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL CASTROL (pnt)-N	13.0 @	5.56 =\$	72.28	
ERR3340	OIL FILTER (rov)-N	1.0 @	43.07 =\$	43.07	
00748	WASHER FLUID-N	1.0 @	4.98 =\$	4.98	
ALU1403L	OIL DRAIN SEAL-N	1.0 @	4.39 =\$	4.39	
46580	PARTS CLEANER/BRAKE-N	1.0 @	7.98 =\$	7.98	132.70

Status: Completed

Job Subtotal: \$216.70

Job06 Wiper Blades	Labor: \$36.20
--------------------	----------------

40518	WIPER BLADE-N	2.0 @	12.90 =\$	25.80	
40516	WIPER BLADE 16"-N	1.0 @	11.33 =\$	11.33	37.13

Status: Completed Tech: GV

Job Subtotal: \$73.33

Recommendations: Coolant hoses including heater hoses need to be replaced-
 getting old and hard. Outer tie rod end left side dust boot split but no free
 play, seepage from front hub swivel seals, oil seeping head gasket and intake
 area . Possible transfer case chain getting loose, lots of noise from drivetrain
 when shift from drive to reverse and back...

Tire Pressure:LF[28] RF[28] LR [41] RR [41]Spare [41]

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
301103002

Order Date 11/03/20 09:23 am
Closed 11/7/2020

7855

Payments to British European Motors

Cost Summary

Labor	518.40
Parts	968.31
Haz Waste	7.00
Ca.Battery Fee	1.00
Subtotal	1494.71
Tax	89.57
Total	\$1584.28

1 11/07/20 1584.28 On Acct
--A/R Pmt Allocations--
11/11/20 \$1,584.28
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 290916004

Order Date 09/16/19 03:09 pm
 Closed/Paid: 10/02/19 04:18 pm

Silberg, Dr. Barry
 1111 1st St
 Cotati, CA 94931
 Phone: 707-528-0000

92 Land Rover RANGE ROVER LS
 Mileage in:145861 out:145861
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 09/16/19 03:17pm 181.00
 Dr in person.
 2 09/23/19 03:46pm 1165.91
 Dr Silberg by phone 707-528-0
 added to 02

Job01 Tow In/Crank No Start Labor: \$181.00

Customer states- vehicle is cranking and not starting... Found bad fuse, replacement fuse pum,p ran couple of seconds, fuse blew, checked amperage draw, replacement fuel pump recommended

Status: Completed Tech: Dr.

Job Subtotal: \$181.00

Job02 (F5) Replace Fuel Pump (91-92) Labor: \$289.60

Remove carpet in rear compartment. Lift under insulation and remove fuel pump cover plate. Remove fuel pump and install replacement. Update wiring harness (if applicable) and install replacement crimp fittings. Refit cover and carpet. Replacement of fuel filter and relay if listed in parts area.

NTC5859	FUEL PUMP SEAL (rov)-N	1.0 @	29.65 =\$	29.65	
NRC9771	FUEL PUMP FITTING-N	2.0 @	3.28 =\$	6.56	
PRC9409	FUEL PUMP*(rov)L91--N	1.0 @	480.02 =\$	480.02	
NRC9770	FUEL PUMP FITTING(rov)-N	2.0 @	6.53 =\$	13.06	
STC3683	HARNESS FUEL PUMP UPDA-N	1.0 @	73.94 =\$	73.94	603.23

Status: Completed Tech: Dr.

Job Subtotal: \$892.83

Recommendations: ****Prior Notes****

Possible transfer case chain getting loose, lots of noise from drivetrain when shift from drive to reverse and back...Coolant hoses including heater at next service.Tires are weather cracking

****Prior Notes****

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
290916004

Order Date 09/16/19 03:09 pm
Closed/Paid: 10/02/19 04:18 pm

Recommendations

Outer tie rod end left side dust boot split but no free play, some minor seepage and front hub swivel seals, oil seeping, headgasket area (R/F)

Tire Pressure:non stock

Payments to British European Motors

Cost Summary

Status: Closed Work Order

Payments: \$1,159.63

1 10/02/19 1159.63 Visa

Labor	470.60
Parts	603.23
Freight	30.00
Subtotal	1103.83
Tax	55.80
Total	\$1159.63
Payments	1159.63
Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 290610002

Order Date 06/10/19 08:39 am
 Closed/Paid: 06/14/19 12:01 pm

Silberg, Dr Barry
 1111...
 382 1381
 ...
 ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:145381 out:145381
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 06/10/19 08:49am 475.63
 Dr in person.
 2 06/10/19 04:31pm 1437.04
 DR SILBERG by phone 707-528-0
 ADDED TO 07
 3 06/14/19 09:50am 1483.78
 Dr Silberg by phone 707-528-0
 updated cost

Job01 Tow In/ Died While Driving Labor: \$181.00

Was driving and died while driving-

Status: Completed Tech: GV

Job Subtotal: \$181.00

Job02 Ac Blowing Warm Again- Re-Charge Labor: \$0.00

Status: Completed Tech: GV

Job Subtotal: \$0.00

Job03 (*)Air Conditioning Service 134 Labor: \$192.00

Hook up A/C rec machine, check pressures. Drain & evacuate system, measure amount of removed freon if any. Hold system in vacuum state to see if holds, if holds, recharge including leak dye to man specs. Visual inspection if any emediate leaks, if system starts to lose efficiency, a recheck for leaks maybe required.

R-134A	FREON R-134A-N	48.0 @	1.29 =\$	61.92	
BG702	LEAK DYE/LUBRICANT (a/c) -N	1.0 @	16.00 =\$	16.00	
BG708	FRIDGI QUIET-N	1.0 @	16.02 =\$	16.02	93.94

Status: Completed Tech: GV

Job Subtotal: \$285.94

Job04 Dist Rotor Labor: \$0.00

Warranty from 1/19

STC1857	DIST ROTOR (rr) -N	1.0 @	54.53 =\$	54.53	
---------	--------------------	-------	-----------	-------	--

----->----->----->-----Continued on the next page----->----->----->----->

Invoice No.
 290610002

Order Date 06/10/19 08:39 am
 Closed/Paid: 06/14/19 12:01 pm

Job04 Dist Rotor

STCI857 DIST ROTOR (rr)-N -1.0 @ 54.53 =\$ -54.53 0.00
 Status: Completed Tech: GV
 Job Subtotal: \$0.00

Job05 Results- Labor: \$0.00

Tested for spark at plugs, none, tested for spark at coil- had spark, remove cap, replace rotor- vehicle started...
 Ac blowing warm- preform ac service to fill system, check pressure- not switching pressure, clutch is functioning, compressor defective- recommend replacement ac compressor and ac dryer first re-charging system and road testing...

Status: Completed Tech: GV
 Job Subtotal: \$0.00

Job06 Ac Compressor Labor: \$181.00

14-SD7715 AC COMPRESSOR-S 1.0 @ 521.63 =\$ 521.63 521.63
 Status: Completed Tech: GV
 Job Subtotal: \$702.63

Job07 Ac Dryer Labor: \$181.00

BTR3717 REC/DRYER (rov)-N 1.0 @ 27.03 =\$ 27.03 27.03
 Status: Completed Tech: GV
 Job Subtotal: \$208.03

Job08 Additional Parts Labor: \$0.00

59007 PAG OIL-N 1.0 @ 24.48 =\$ 24.48 24.48
 Status: Completed
 Job Subtotal: \$24.48

Recommendations: ****Prior Notes****
 ----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
290610002

Order Date 06/10/19 08:39 am
Closed/Paid: 06/14/19 12:01 pm

Recommendations

Possible transfer case chain getting loose, lots of noise from drivetrain when shift from drive to reverse and back...Coolant hoses including heater at next service. Tires are weather cracking

****Prior Notes****

Outer tie rod end left side dust boot split but no free play, some minor seepage and front hub swivel seals, oil seeping, headgasket area (R/F)

Tire Pressure: LF[35] RF[35] LR [41] RR [41]

Payments to British European Motors

Cost Summary

Status: Closed Work Order

Payments: \$1,483.78

1 06/14/19 1483.78 Visa

Labor	735.00
Parts	667.08
Freight	20.00
Subtotal	1422.08
Tax	61.70
Total	\$1483.78
Payments	1483.78
Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 290110004

Order Date 01/10/19 03:04 pm
 Closed/Paid: 01/15/19 05:00 pm

7134

Silberg, Dr Barry
 1111 S. ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:144379 out:144379
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 01/14/19 12:41pm 1513.62
 Dr Silberg by phone 707-528-0

7134

Job01 Tow In Labor: \$0.00

Status: Completed Tech: SL

Job Subtotal: \$0.00

Job02 Crank No Start Labor: \$176.00

Cranks, no start, has spark, has fuel to rail- will need to check injectors and pulse . All function, check fuel pressure, vewrying and fluctuating high, removed all plugs and found wet, recommend replacement pressure regulator and spark plugs, closer inspection and checking records recommend changing cap rotor and p;luig wires

Status: Completed Tech: Dr.

Job Subtotal: \$176.00

Job03 Fuel Pressure Regulator Labor: \$140.80

Chec kpressure, not holding steady, removed and shook out debris similar to fuel filter

ETC8494	FUEL PRESSURE REQULATO-N	1.0 @	272.83 =\$	272.83	272.83
---------	--------------------------	-------	------------	--------	--------

Status: Completed Tech: Dr.

Job Subtotal: \$413.63

Job04 Spark Plugs,Dist Cap/Rotor/Wires Labor: \$440.00

Change spark plugs, ignition wires, distributor cap and rotor.

RN14YC	SPARK PLUG-N	8.0 @	6.98 =\$	55.84
STC1857	DIST ROTOR (rr)-N	1.0 @	54.53 =\$	54.53

----->----->----->-----Continued on the next page----->----->----->----->

Invoice No.
290110004

Order Date 01/10/19 03:04 pm
Closed/Paid: 01/15/19 05:00 pm

7134

Job04 Spark Plugs, Dist Cap/Rotor/Wires

STC8368	DIST CAP (rov)-N	1.0 @	60.93 =\$	60.93	
HLS101	PLUG WIRE SET(di/rov95-N	1.0 @	120.38 =\$	120.38	291.68

Status: Completed Tech: Dr.

Job Subtotal: \$731.68

Job05 Back Up Camera Update- Attempt Labor: \$140.80

Installed customer supplied harness, no change, contact tech support, run a couple tests, still no change, customer declined further diagnosis/repairs to back up camera...

Status: Completed Tech: Dr.

Job Subtotal: \$140.80

Recommendations: Possible transfer case chain getting loose, lots of noise from drivetrain when shift from drive to reverse and back...Coolant hoses including heater at next service. Tires are weather cracking

****Prior Notes****

Outer tie rod end left side dust boot split but no free play, some minor seepage and front hub swivel seals, oil seeping, headgasket area (R/F)

Tire Pressure: LF[35] RF[35] LR [41] RR [41]

Payments to British European Motors Cost Summary

Labor	897.60
Parts	564.51
Subtotal	1462.11

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
290110004

Order Date 01/10/19 03:04 pm
Closed/Paid: 01/15/19 05:00 pm

7134

Payments to British European Motors

Cost Summary

Tax	51.51
Total	\$1513.62
Payments	1513.62
Bal Due	0.00

Status: Closed Work Order

Payments: \$1,513.62

1 01/15/19 1513.62 Visa

Thank you for choosing British European Motors

Invoice No.
281126005

Order Date 11/26/18 12:37 pm
Closed/Paid: 12/07/18 05:00 pm

7089

Silberg, Dr Barry
1111...
...
...
...

92 Land Rover RANGE ROVER LS
Mileage in:144008 out:144008
Lic: 3BKH816/CA 8Cyl 4.0
Vin: SALHV1246NA618427 01/92
Eq: AT AC PS FI 4W
Last in 11/12/2021

Quotes

1 11/26/18 12:37pm 176.00
Dr in person.
2 11/27/18 11:26am 1471.19
Dr Silberg by phone 707-696-3
added 05

7089

Job01 Tow In- Crank Not Start Labor: \$176.00

Having vehicle towed in.
let sit for 1-2 weeks- tires to start but does not, prior, had tach not working
intermittently while driving....
Run system test, battery low voltage, enough to crank but maybe not enough power
in reserve to fire plugs and injectorsd, charge battery and load test, ok, engine
started, recommend replacement alternator since other related issues.

Status: Completed Tech: Dr.

Job Subtotal: \$176.00

Job02 Relays? Rusty- See Photo Labor: \$0.00

from email

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Job03 Battery Light Comes/Goes Labor: \$0.00

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Job04 (E5)92-95 Replace Alternator Labor: \$211.20

Test alternator as required. Remove and replace with exchange unit.

AMR4247 ALTERNATOR (4.0/4.2 EA-N 1.0 @ 589.97 =\$ 589.97 589.97

Status: Completed Tech: Dr.

Job Subtotal: \$801.17

----->----->----->-----Continued on the next page--->----->----->----->

Invoice No.
281126005

Order Date 11/26/18 12:37 pm
Closed/Paid: 12/07/18 05:00 pm

7089

Job05 (I5) Rplce Pwr Steer Pump/Feed Labor: \$281.60

Clean off area
Remove pulleys and belt
Drain reservoir and access pump
Remove from mounting bracket and disconnect hoses
Check hoses and replace as required
Install replacement pump and secure hoses with new seals as/if required
Top off and manually turn steering back and forth to bleed out system of air
run engine check operation
road test, top off fluid as required
Replace High side pressure hose from pump to steering rack
Add clean fluid and bleed as required
****Fill reservoir with clean fluid several times and flush through as per
suppliers instructions ****

30504	TRANS/STEER OIL (LTR)-N	3.0 @	18.61 =\$	55.83	
H/C 8-30024	HOSE CLAMP #8-N	2.0 @	3.55 =\$	7.10	
46580	PARTS CLEANER/BRAKE-N	2.0 @	7.98 =\$	15.96	
NTC4245	LOW PWR STEER HOSE(rov-N	1.0 @	66.43 =\$	66.43	145.32

Status: Completed Tech: Dr.

Job Subtotal: \$426.92

Job06 Add Diagnosis Elec Fault Labor: \$334.40

feedback fault and power loss, checked original camera wiring appeared to be directly related when shifting to reverse, all wnet back to normal, moved power wires to aux switch position, ran several times, no fault, checked camera for possible reverse image change, could not get to work correctly.....

Status: Completed Tech: Dr.

Job Subtotal: \$334.40

Recommendations: Possible transfer case chain getting loose, lots of noise from drivetrain when shift from drive to reverse and back...

****Prior Notes****

Front tires showing heavy cracks (seperation) between tread, looks like tires were installed in 2007 as date stamp on tire....pressures were ok. outer tie rod end left side dust boot split but no free play, some minor seepage and front hub

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
281126005

Order Date 11/26/18 12:37 pm
Closed/Paid: 12/07/18 05:00 pm

7089

Recommendations

swivel seals
oil seeping, headgasket area (R/F)

Tire Pressure: LF[28] RF[28] LR [41] RR [41]

Payments to British European Motors

Cost Summary

Status: Closed Work Order

Payments: \$1,491.98

1 12/07/18 1491.98 Visa

Labor	1003.20
Parts	735.29
Discount	287.38
Subtotal	1451.11
Tax	40.87
Total	\$1491.98
Payments	1491.98
Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 281226005

Order Date 12/26/18 02:20 pm
 Closed 12/29/2018

Silberg, Dr Barry
 1175 S...
 ...
 ...
 ...
 ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:144151 out:144151
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 12/26/18 02:53pm 154.79
 Dr in person.

Job01 (F5) Replace Fuel Filter Labor: \$123.20

Remove clamps drain and replace fuel filter

ERS4065	FUEL FILTER-S	1.0 @	15.03 =\$	15.03	
XR829166	O-RING SEAL TRAN/FILT-N	2.0 @	6.96 =\$	13.92	28.95

Status: Completed Tech: GV

Job Subtotal: \$152.15

Recommendations: Possible transfer case chain getting loose, lots of noise from drivetrain when shift from drive to reverse and back...

****Prior Notes****

Front tires showing heavy cracks (seperation) between tread, looks like tires were installed in 2007 as date stamp on tire....pressures were ok. outer tie rod end left side dust boot split but no free play, some minor seepage and front hub swivel seals

oil seeping, headgasket area (R/F)

Tire Pressure: LF[28] RF[28] LR [41] RR [41]

Payments to British European Motors Cost Summary

Labor 123.20
 Parts 28.95

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
281226005

Order Date 12/26/18 02:20 pm
Closed 12/29/2018

Payments to British European Motors

Cost Summary

Subtotal	152.15
Tax	2.64
Total	\$154.79

1 01/26/18 154.79 On Acct
--A/R Pmt Allocations--
01/18/19 \$154.79
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
280104002

Order Date 01/04/18 12:03 pm
Closed 1/6/2018

Silberg, Dr Barry 1111 Portal St Cotati, CA 94931 707 792-2737	92 Land Rover RANGE ROVER LS Mileage in:142113 out:142113 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021
---	--

air filter good, brakes all good

Job01 Pick Up Vehicle	Labor: \$0.00
-----------------------	---------------

Status: Completed
Scheduled for: 01/04/18 11:00 am

Job Subtotal: \$0.00

Job02 L/R Window Fault	Labor: \$300.60
------------------------	-----------------

Window will not operate.
Check both switches from console and at door, no operation of window motor.
Remove door panel and check power supply to motor, all good, access motor and
spray contact cleaner into armature, power direct battery feed and shock motor to
operate, run several times with separate power source, temp connect panel and run
motor with door and console switches, all good. Refit panel and secure, recheck
operation.

Status: Completed Tech: Dr.

Job Subtotal: \$300.60

Job03 R/H Seat Switch Fault	Labor: \$33.40
-----------------------------	----------------

Customer states, seat will move forward but not back... checked switch, moved
several time rapidly, spray contact cleaner, works all positions now.

Status: Completed Tech: Dr.

Job Subtotal: \$33.40

Job04 (5) Rover Oil, Lube Service	Labor: \$73.50
-----------------------------------	----------------

Raise vehicle // Drain oil and remove filter
Install new filter // add oil run check leaks // Lube fittings as required check
all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
 280104002

Order Date 01/04/18 12:03 pm
 Closed 1/6/2018

Job04 (5) Rover Oil, Lube Service

lights, oil leaks, fuel leaks general inspection of complete

20/50	ENGINE OIL CASTROL (pn-N	13.0 @	5.33 =\$	69.29	
ERR3340	OIL FILTER (rov)-N	1.0 @	39.43 =\$	39.43	
00748	WASHER FLUID-N	1.0 @	4.98 =\$	4.98	
46580	PARTS CLEANER/BRAKE-N	1.0 @	5.46 =\$	5.46	
ALU1403L	OIL DRAIN SEAL-N	1.0 @	4.35 =\$	4.35	123.51

Status: Completed Tech: GV

Job Subtotal: \$197.01

Recommendations: Front tires showing heavy cracks (seperation) between tread, looks like tires were installed in 2007 as date stamp on tire....pressures were ok. outer tie rod end left side dust boot split but no free play, some minor seepage and front hub swivel seals

****Prior Notes****

Power steering pump seal seeping, oil seeping, headgasket area (R/F)

Tire Pressure: LF[28] RF[28] LR [41] RR [41]

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	407.50
Parts	123.51
Haz Waste	7.00
Subtotal	538.01
Tax	11.27

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
280104002

Order Date 01/04/18 12:03 pm
Closed 1/6/2018

Payments to British European Motors

Cost Summary

Total \$549.28

1 01/05/18 549.28 On Acct

Thank you for choosing British European Motors

Invoice No.
 280420003

Order Date 04/20/18 01:12 pm
 Closed/Paid: 04/24/18 02:18 pm

6814

<p>Silvery, Dr Barry 1111 1st St Cotati, CA 94931 Phone: 707-528-0911</p>	<p>92 Land Rover RANGE ROVER LS Mileage in:143105 out:143105 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021</p>	<p>Quotes</p> <table border="1"> <tr> <td>1</td> <td>04/20/18 01:48pm</td> <td>176.00</td> </tr> <tr> <td colspan="3">Dr in person.</td> </tr> <tr> <td>2</td> <td>04/23/18 02:46pm</td> <td>1227.36</td> </tr> <tr> <td colspan="3">Dr Barry by phone 707-528-091 added 02-03</td> </tr> </table>	1	04/20/18 01:48pm	176.00	Dr in person.			2	04/23/18 02:46pm	1227.36	Dr Barry by phone 707-528-091 added 02-03		
1	04/20/18 01:48pm	176.00												
Dr in person.														
2	04/23/18 02:46pm	1227.36												
Dr Barry by phone 707-528-091 added 02-03														

6814

Job01 No Crank No Start Intermit Labor: \$105.60

Customer states... ignition key turns, no cranks, removes and trys again, no crank, on 3rd time holds key to on, then starts... Please inspect...
 Check battery, appears fine, hook up volt meter at starter and repeat starting, signal everytime, starter did not crank, recommend replacement starter and light charge of battery.

Status: Completed Tech: Dr.

Job Subtotal: \$105.60

Job02 (E5) Replace Starter Labor: \$281.60

Disconnect and remove old starter. Install replacement hook up wiring and secure
 Check operation.

RTC6061N	STARTER MOTOR (rov)-R	1.0 @	769.91 =\$	769.91	769.91
----------	-----------------------	-------	------------	--------	--------

Status: Completed Tech: GV

Job Subtotal: \$1,051.51

Job03 Topped Off Fluids Labor: \$0.00

Add pint engine oil, small amount of coolant

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Recommendations: ****Prior Notes****

Front tires showing heavy cracks (seperation) between tread, looks like tires were installed in 2007 as date stamp on tire...pressures were ok. outer tie rod
 ----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
280420003

Order Date 04/20/18 01:12 pm
Closed/Paid: 04/24/18 02:18 pm

6814

Recommendations

end left side dust boot split but no free play, some minor seepage and front hub swivel seals

Power steering pump seal seeping, oil seeping, headgasket area (R/F)

Tire Pressure: LF[28] RF[28] LR [41] RR [41]

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Status: Closed Work Order
Payments: \$1,227.36
1 04/24/18 1227.36 Visa

Labor	387.20
Parts	769.91
Subtotal	1157.11
Tax	70.25
Total	\$1227.36
Payments	1227.36
Bal Due	0.00

Thank you for choosing British European Motors

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 1

Invoice No.
271128003

Order Date 11/28/17 01:42 pm
Closed 12/2/2017

Slings, Dr. Mark 1111 1/2 1st St Cotati, CA 94931 707 792-2737	92 Land Rover RANGE ROVER LS Mileage in:141625 out:141625 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021
--	--

Job01 Light Front Bumper Lamps Labor: \$484.30

Remove front bump bar and bumper, remove lamps and install customer supplied replacements. Secure bumper and test lights

Status: Completed
Scheduled for: 12/05/17 01:00 pm

Job Subtotal: \$484.30

Recommendations: ****Prior Notes****

Power steering pump seal seeping, oil seeping, headgasket area (R/F)

Tire Pressure: LF
RF
LR
RR

Payments to British European Motors Cost Summary

Labor	484.30
Parts	0.00
Subtotal	484.30
Total	\$484.30

1 12/01/17 484.30 On Acct

Thank you for choosing British European Motors

Invoice No.
 270824005

Order Date 08/24/17 05:24 pm
 Closed 9/2/2017

6546

Silbert, Dr Barry
 1111...
 ...
 ...
 ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:140910 out:140910
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 08/29/17 01:51pm 721.67
 DrBarry in person.

6546

Job01 Pick Up Vehicle Labor: \$0.00

Status: Completed Tech: Dr. Job Subtotal: \$0.00

Job02 (*)Air Conditioning Service 134 Labor: \$192.00

Hook up A/C rec machine, check pressures, low.... Drain/evacuate, system only had .7lb (holds 2lbs)
 Recharge including leak dye to man specs, added leak dye and if system starts to get less efficient recheck for leak will be required

R-134A	FREON R-134A-N	34.0 @	1.29 =\$	43.86	
BG702	LEAK DYE/LUBRICANT(a/c)-N	1.0 @	16.00 =\$	16.00	
BG708	FRIDGI QUIET-N	1.0 @	16.02 =\$	16.02	75.88

Status: Completed Tech: SL Job Subtotal: \$267.88

Job03 Ck Belts? Making Noise Labor: \$0.00

Customer states- belts making noise-, glazed note made at last service, replacements required.

Status: Completed Tech: GV Job Subtotal: \$0.00

Job04 (C5) Replce All Drv Blts -92 Labor: \$317.30

Slacken off belts and remove. Install all new belts and adjust tention

ERC675	POWER STEER BELT(rov)-N	1.0 @	51.35 =\$	51.35	
--------	-------------------------	-------	-----------	-------	--

----->----->----->-----Continued on the next page----->----->----->----->

Invoice No.
270824005

Order Date 08/24/17 05:24 pm
Closed 9/2/2017

6546

Job04 (C5) Replce All Drv Blts -92

611612	BELT FAN (rov)-N	2.0 @	38.32 =\$	76.64	
ERR2073	ALT BELT (rov)-N	1.0 @	21.35 =\$	21.35	149.34
Status: Completed					Job Subtotal: \$466.64

Job05 Center Muffler Rattling? Labor: \$225.00

Center muffler need changing, when removing the muffler oieces of the right hand catalytic convertor were found inside, replqacement of the right sside convertor also required. Install both as recommended

RVF17832	MUFFLER-S	1.0 @	112.51 =\$	112.51	
439-339004	R/H CATALYTIC CONVTR-S	1.0 @	302.94 =\$	302.94	415.45

Status: Completed Tech: SL
Job Subtotal: \$640.45

Job06 Check Levels Top Off As Reqd Labor: \$0.00

check levels and tire presasures, top off as required

Status: Completed Tech: Dr.
Job Subtotal: \$0.00

Recommendations: ****Prior Notes****

Power steering pump seal seeping, oil seeping, headgasket area (R/F)

Tire Pressure: LF
RF
LR
RR

Payments to British European Motors Cost Summary

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
270824005

Order Date 08/24/17 05:24 pm
Closed 9/2/2017

6546

Payments to British European Motors

Cost Summary

Labor	734.30
Parts	640.67
Freight	20.00
Subtotal	1394.97
Tax	58.46
Total	\$1453.43

1 08/31/17 1453.43 On Acct

Thank you for choosing British European Motors

Invoice No.
 270217001

Order Date 02/17/17 08:36 am
 Closed/Paid: 02/17/17 01:04 pm

6269

Silber, Dr Barry
 11111111111111111111
 11111111111111111111
 11111111111111111111
 11111111111111111111

92 Land Rover RANGE ROVER LS
 Mileage in:139431 out:139431
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 02/17/17 08:38am 649.65
 Dr in person.

6269

Job01 Install Seat Switch Labor: \$77.00

1248208710	SEAT SWTCH R/H (disc)-N	1.0 @	229.73 =\$	229.73	229.73
------------	-------------------------	-------	------------	--------	--------

Status: Completed Tech: Dr.

Job Subtotal: \$306.73

Job02 Install F. Mud Flap Labor: \$77.00

Install front mud flap

MXC5587	MUD FLAP FNT/REAR 93-9-N	1.0 @	42.82 =\$	42.82	42.82
---------	--------------------------	-------	-----------	-------	-------

Status: Completed

Job Subtotal: \$119.82

Job03 (5/4.0) Rover Oil, Lube Service Labor: \$52.50

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL CASTROL (pnt)-N	13.0 @	4.96 =\$	64.48	
ERR3340	OIL FILTER (rov)-N	1.0 @	39.43 =\$	39.43	
00748	WASHER FLUID-N	1.0 @	3.07 =\$	3.07	
ALU1403L	OIL DRAIN SEAL-N	1.0 @	4.35 =\$	4.35	
MPS-100	PARTS CLEANER-N	1.0 @	18.09 =\$	18.09	129.42

Status: Completed

Job Subtotal: \$181.92

Job04 Air Filter Labor: \$0.00

RTC4683	AIR FILTER (rov)-N	1.0 @	17.42 =\$	17.42	17.42
---------	--------------------	-------	-----------	-------	-------

Status: Completed

Job Subtotal: \$17.42

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
270217001

Order Date 02/17/17 08:36 am
Closed/Paid: 02/17/17 01:04 pm

6269

Recommendations: ****Prior Notes****

alternator belt made noise, since driving now appears ok.

****Prior Notes****

Power steering pump seal seeping, oil seeping, headgasket area (R/F)

Tire Pressure: LF[32] RF[32] LR [44] RR [44]

606 Portal St E.P.A #CAL000418587

Payments to British European Motors

Cost Summary

Status: Closed Work Order

Payments: \$668.64

1 02/17/17 668.64 Visa

Labor	206.50
Parts	419.39
Haz Waste	5.00
Subtotal	630.89
Tax	37.75
Total	\$668.64
Payments	668.64
Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 261031003

Order Date 10/31/16 10:53 am
 Closed 11/5/2016

6128

92 Land Rover RANGE ROVER LS
 Mileage in:138387 out:138387
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 10/31/16 11:14am 154.00
 Dr in person.
 2 11/03/16 01:00pm 392.94
 Dr Silberg by phone 707-696-3
 added 03

6128

Job01 Tow In Labor: \$0.00

Status: Completed Tech: Dr.

Scheduled for: 01/09/00 12:00 am

Job Subtotal: \$0.00

Job02 No Crank No Start Labor: \$154.00

Customer states... Truck will not start... Had battery go dead, jump start, truck just cranks and does not start. battery wont last a week, possible draw on battery? Sears said battery was good a few months ago.

Charge battery, load test, bad 8.3 volts, has 22ma draw on system, well under specs. Unplugged under hood light, possible staying on. Recommend new higher amperage battery, and a trickle charger to keep system up to charge while not using truck

Status: Completed Tech: Dr.

Job Subtotal: \$154.00

Job03 Battery Install Labor: \$46.20

Remove and replace battery

MTP-24 BATTERY (4.0/6 ROV)-N 1.0 @ 176.42 =\$ 176.42 176.42

Job Subtotal: \$222.62

Status: Completed

Recommendations: ****Prior Notes****

alternator belt made noise, since driving now appears ok.

****Prior Notes****

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
261031003

Order Date 10/31/16 10:53 am
Closed 11/5/2016

6128

Recommendations

Power steering pump seal seeping, oil seeping, headgasket area (R/F)

Nitro

606 Portal St E.P.A #CAL000418587

Payments to British European Motors

Cost Summary

Labor	200.20
Parts	176.42
Subtotal	376.62
Tax	16.32
Total	\$392.94

1 11/04/16 392.94 On Acct
--A/R Pmt Allocations--
12/06/16 \$392.94
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 250728005

Order Date 07/28/15 03:37 pm
 Closed 8/8/2015

Silberg, Dr Barry
 1111 3rd Ave
 Cotati, CA 94931
 Phone: 707 792-2737
 Fax: 707 792-4454

92 Land Rover RANGE ROVER LS
 Mileage in:133755 out:133755
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 07/29/15 09:00am 470.98
 Dr in person.

Job01 (*)Air Conditioning Service 134 Labor: \$192.00

Hook up A/C rec machine // Drain/evacuate//hold test//recharge including leak dye
 to man specs
 Test leaks ok

R-134A	FREON R-134A-N	48.0 @	1.29 =\$	61.92	
BG702	LEAK DYE/LUBRICANT(a/c)-N	1.0 @	16.00 =\$	16.00	
BG708	FRIDGI QUIET-N	1.0 @	16.02 =\$	16.02	93.94

Status: Completed Tech: SL

Job Subtotal: \$285.94

Job02 (5/4.6) Rover Oil, Lube Service Labor: \$50.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL CASTROL (pnt)-N	15.0 @	4.96 =\$	74.40	
ERR3340	OIL FILTER (rov)-N	1.0 @	21.94 =\$	21.94	
UAM2857L	OIL DRAIN SEAL (rov4.0-)-N	1.0 @	3.15 =\$	3.15	
00748	WASHER FLUID-N	1.0 @	3.07 =\$	3.07	
MPS-100	PARTS CLEANER-N	0.5 @	17.04 =\$	8.52	111.08

Status: Completed

Job Subtotal: \$161.08

Recommendations: Power steering pump seal seeping, oil seeping, headgasket
 area (R/F) Battery tested at 9.2 volts

Tire Pressure: LF[28] RF[28] LR [41] RR [41]

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
250728005

Order Date 07/28/15 03:37 pm
Closed 8/8/2015

Payments to British European Motors

Cost Summary

Labor	242.00
Parts	205.02
Haz Waste	5.00
Subtotal	452.02
Tax	18.96
Total	\$470.98

1 07/29/15 470.98 On Acct
--A/R Pmt Allocations--
08/14/15 \$470.98
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
240423001

Order Date 04/23/14 08:42 am
Closed/Paid: 04/25/14 11:37 am

Silberg, Dr Barry
1770 North Ave
Cotati, CA 94931
Phone: 707-792-4454
Fax: 707-792-4454

92 Land Rover RANGE ROVER LS
Mileage in:131307 out:131307
Lic: 3BKH816/CA 8Cyl 4.0
Vin: SALHV1246NA618427 01/92
Eq: AT AC PS FI 4W
Last in 11/12/2021

Quotes

1 04/25/14 11:37am 267.01
Dr Silberg by phone 707-528-0

Job01 Passenger Seat Switch Labor: \$42.00

1248208710 SEAT SWTCH R/H (disc)-N 1.0 @ 206.91 =\$ 206.91 206.91

Status: Completed Tech: Dr.

Job Subtotal: \$248.91

Tire Pressure: LF
RF
LR
RR

Payments to British European Motors Cost Summary

Status: Closed Work Order
Payments: \$267.01
1 04/25/14 267.01 Visa

Labor 42.00
Parts 206.91
Subtotal 248.91
Tax 18.10
Total \$267.01
Payments 267.01
Bal Due 0.00

Thank you for choosing British European Motors

Invoice No.
240328002

Order Date 03/28/14 08:39 am
Closed/Paid: 04/04/14 03:38 pm

Silberg, Dr Barry	92 Land Rover RANGE ROVER LS	Quotes
	Mileage in:131068 out:131068 Lic: 3BKH816/CA 8Cyl 4.0	1 04/03/14 12:16pm 277.84 Dr Barry by phone 707-528-091
	Vin: SALHV1246NA618427 01/92	2 04/03/14 02:58pm 1120.17 DR SILBERG by phone 707-528-0 added 04-08
	Eq: AT AC PS FI 4W	
	Last in 11/12/2021	

no charge on job 01/02

Job01 Re-Adjust Engine Belts Labor: \$84.00

Belts have been replaced, adjust as required

Status: Completed

Job Subtotal: \$84.00

Job02 Install R/R Bumper Trim Labor: \$56.00

NTC7867	BUMPER RET CLIP-N	2.0 @	3.39 =\$	6.78	
NTC5232	END CAP R/R (rov)-N	1.0 @	105.89 =\$	105.89	112.67

Status: Completed

Job Subtotal: \$168.67

Job03 Rear Window Switches Labor: \$70.00

Attempt clean if possible, windows go down but not back up....

PRC5255	WINDOW SWITCH rov-N	1.0 @	32.42 =\$	32.42	
PRC5254	WINDOW SWITCH (rov/R)-N	1.0 @	30.76 =\$	30.76	63.18

Status: Completed

Job Subtotal: \$133.18

Job04 (5) Rover Oil, Lube Service Labor: \$40.00

Raise vehicle // Drain oil and remove filter
Install new filter // add oil run check leaks // Lube fittings as required check
all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
leaks general inspection of complete vehicle

20/50	ENGINE OIL CASTROL (pnt)-N	13.0 @	3.68 =\$	47.84	
ERR3340	OIL FILTER (rov)-N	1.0 @	26.62 =\$	26.62	
ETC7398	OIL DRAIN SEAL (disc/ro)-N	1.0 @	3.59 =\$	3.59	
MPS-100	PARTS CLEANER-N	0.5 @	17.02 =\$	8.51	86.56

Status: Completed

Job Subtotal: \$126.56

----->----->----->----->----->----->----->----->----->----->
----->----->----->----->----->----->----->----->----->----->
----->----->----->----->----->----->----->----->----->----->
----->----->----->----->----->----->----->----->----->----->

Continued on the next page

Invoice No.
 240328002

Order Date 03/28/14 08:39 am
 Closed/Paid: 04/04/14 03:38 pm

Job05 (J5) R&r C.Arm Bushings (rear) Labor: \$266.00

Remove control arms and front part of control arm bushing (rebound style) on rear suspension

STC618 CONTROL ARM MOUNT KIT-N 1.0 @ 87.92 =\$ 87.92 87.92

Job Subtotal: \$353.92

Status: Completed

Job06 (C5) Replace Engine Mounts(x2) Labor: \$336.00

Remove fan clutch to enable engine lift. Lossen eninge mounts and raise and to remove. Install new mounts Lower engine and secure mounts. Refit fan clutch and road test complete.

STC434 MOTOR/TRANS MOUNT(rov)-N 2.0 @ 42.97 =\$ 85.94 85.94

Job Subtotal: \$421.94

Status: Completed

Job07 Secured Steering Drop Arm Labor: \$0.00

Loose at steering box, turn full one and half turns to secure

Job Subtotal: \$0.00

Status: Completed

Job08 Wipers Labor: \$0.00

40718A WIPER BLADE 18"-N 3.0 @ 15.71 =\$ 47.13 47.13

Job Subtotal: \$47.13

Status: Completed

Tire Pressure: LF[38] RF[38] LR [38] RR [38]

Payments to British European Motors Cost Summary

Labor	852.00
Parts	483.40
Haz Waste	5.00
Discount	262.53
Subtotal	1077.87
Tax	42.30
Total	\$1120.17

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
240328002

Order Date 03/28/14 08:39 am
Closed/Paid: 04/04/14 03:38 pm

Payments to British European Motors

Cost Summary

Payments	1120.17
Bal Due	0.00

Status: Closed Work Order

Payments: \$1,120.17

1 04/04/14 1120.17 Visa

Thank you for choosing British European Motors

Invoice No.
 240304001

Order Date 03/04/14 08:50 am
 Closed/Paid: 03/06/14 02:13 pm

4628

Silvestro, Dr Barry
 11200
 11200

92 Land Rover RANGE ROVER LS
 Mileage in:130776 out:130776
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1	03/05/14 09:27am	140.00
Dr in person.		
2	03/05/14 02:46pm	1203.75
Barry by phone 707-528-0911		
#02-03		
3	03/06/14 02:00pm	1420.27
Barry by phone 707-528-0911		
#04		

4628
 \$434.16 01+02 jobs
 Engine noise when testing a/c, water pump bearing failure, alternator also sounds noisy, but water pump maybe transmitting echo through pulleys etc..change pump first

Job01 Diag A/C Operation Labor: \$140.00

Not blowing cold.
 Check system, found wiring fault at low pressure switch, switch test ok, with wires jump across each other system compressor will run but still not efficient
 Installed new terminals and re-test switch, system has lower than required pressure, recommend service

Status: Completed Tech: Dr.

Job Subtotal: \$140.00

Job02 (*)Air Conditioning Service 134 Labor: \$192.00

Hook up A/C rec machine // Drain/evacuate//hold test//recharge including leak dye to man specs
 Test leaks ok

R-134A	FREON R-134A-N	48.0 @	1.29 =\$	61.92	
BG702	LEAK DYE/LUBRICANT(a/c)-N	1.0 @	16.00 =\$	16.00	
BG708	FRIDGI QUIET-N	1.0 @	16.02 =\$	16.02	93.94

Status: Completed Tech: SL

Job Subtotal: \$285.94

Job03 (H5)Replace Water Pump(92) Labor: \$490.00

Drain cooling system and remove fan coupling. Remove hoses and remove water pump. Clean off area and install replacement water pump. Refit components and add coolant to strength. Road test complete.

----->----->----->-----Continued on the next page----->----->----->----->

Invoice No.
 240304001

Order Date 03/04/14 08:50 am
 Closed/Paid: 03/06/14 02:13 pm

4628

Job03 (H5) Replace Water Pump (92)

STC483	WATER PUMP (rov)-N	1.0 @	225.94 =\$	225.94	
ERR4685	PLUG SEAL (lr)-N	1.0 @	2.21 =\$	2.21	
AFPXA003	ANTIFREEZE/COOLANT(pnt-N	8.0 @	2.43 =\$	19.44	
ERR4686	RADIATOR/DIFF PLUG (lr-N	1.0 @	4.91 =\$	4.91	252.50

Status: Completed

Job Subtotal: \$742.50

Job04 ADD-Replce All Drv Blts 90-92	Labor: \$140.00
-------------------------------------	-----------------

Slacken off belts and remove. Install all new belts and adjust

ERR2073	ALT BELT (rov)-N	1.0 @	13.74 =\$	13.74	
611612	BELT FAN (rov)-N	2.0 @	19.32 =\$	38.64	
ERC675	POWER STEER BELT(rov)-N	1.0 @	17.98 =\$	17.98	70.36

Status: Completed

Job Subtotal: \$210.36

Tire Pressure: LF[42] RF[42] LR [42] RR [42]

by paying by check, you authorize us or our agent to process the check by traditional deposit, electronically, or through a 'preauthorized draft.' If the check is returned for any reason, you authorize us or our agent to re-present the check one or more times by such methods, and you authorize us or our agent to collect a returned check fee up to the maximum amount as permitted by law.

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	962.00
Parts	416.80
Haz Waste	5.00
Subtotal	1383.80
Tax	36.47
Total	\$1420.27
Payments	1420.27

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
240304001

Order Date 03/04/14 08:50 am
Closed/Paid: 03/06/14 02:13 pm

4628

Payments to British European Motors

Cost Summary

Bal Due 0.00

Status: Closed Work Order

Payments: \$1,420.27

1 03/06/14 1420.27 Visa

Thank you for choosing British European Motors

Invoice No.
 220716003

Order Date 07/16/12 11:54 am
 Closed/Paid: 07/20/12 09:09 am

Silbers, Dr Barry
 1st Name: Dr Barry
 Last Name: Silbers
 Title: Dr
 Address: 10000
 City: Cotati
 State: CA
 Zip: 94931

92 Land Rover RANGE ROVER LS
 Mileage in:125565 out:125565
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 07/16/12 11:54am 290.40
 Dr Barry in person.

Job01 Pick Up Check Steer Lock Labor: \$290.40

Remove trim and check for lock binding
 Remove from column and clean out tumblers, add lubricant and operate numerous times
 Refit and secure
 Recheck operation, feels much smoother and easier
 Refit and glue surround, broken from prior fixes, but not available new
 Recheck operation, ok

Status: Completed Job Subtotal: \$290.40

Job02 Secure Back Up Camera Labor: \$66.00

Cut dash small pad to allow for cable and secure camera

Status: Completed Job Subtotal: \$66.00

PLEASE UPDATE MILEAGE

Tire Pressure: LF[] RF[] LR [] RR []

Payments to British European Motors Cost Summary

Status: Closed Work Order	Labor	356.40
Payments: \$356.40	Parts	0.00
1 07/20/12 356.40 Visa	Subtotal	356.40
	Total	\$356.40
	Payments	356.40
	Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 220720002

Order Date 07/20/12 08:54 am
 Closed 7/28/2012

Silberg, Dr Barry	92 Land Rover RANGE ROVER LS
	Mileage in:125565 out:125565
	Lic: 3BKH816/CA 8Cyl 4.0
	Vin: SALHV1246NA618427 01/92
	Eq: AT AC PS FI 4W
	Last in 11/12/2021

Job01 Ignition Lock Replacement	Labor: \$264.00
---------------------------------	-----------------

After lubrication lock stuck again
 Remove trim (very fragile, had to glue again, but not available)
 Refit and sucure, comes with two new keys, swap door key onto key set

NTC9440	STEER LOCK (int.lock)-N	1.0 @	389.97 =\$	389.97	389.97
---------	-------------------------	-------	------------	--------	--------

Status: Completed

Job Subtotal: \$653.97

Job02 Locking, Alarm Fault	Labor: \$145.20
----------------------------	-----------------

Found wiring harness fault at connector from back up camera hook up
 Disconnect and re-route wiring hanress and secure connector
 Recheck operation, lube rear door latches

Status: Completed

Job Subtotal: \$145.20

PLEASE UPDATE MILEAGE

Tire Pressure: LF[] RF[] LR [] RR []

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	409.20
Parts	389.97
Discount	264.00
Subtotal	535.17
Tax	33.15
Total	\$568.32

1 07/25/12 568.32 On Acct
 --A/R Pmt Allocations--
 09/13/12 \$568.32
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 220518001

Order Date 05/18/12 08:18 am
 Closed 5/26/2012

3462

Job04 (B5) Replc R.Brk Pads/Rotrs(90- Labor: \$330.00

Raise vehicle and remove rear wheels. Remove brake caliper and pads and clean. Remove hub and remove brake rotor. Clean and install new rotor and remove bearings clean and repack, install new seals refit hub and brake caliper assembly. Install new pads and sensor, bleed out fluid/air. Refit road wheels and road test complete.

571752	GASKET AXLE FLANGE(rov-N	2.0 @	1.68 =\$	3.36	
FTC1381	R.BRAKE ROTOR (rov 90--N	2.0 @	110.91 =\$	221.82	
FTC4785	HUB SEAL ALL (rov)-N	2.0 @	9.76 =\$	19.52	
STC9189	R.BRAKE PAD (rov all)-N	1.0 @	134.86 =\$	134.86	
MPS-100	PARTS CLEANER-N	1.0 @	17.02 =\$	17.02	
217353	LOCK TAB AXLE BRG (rov-N	2.0 @	3.16 =\$	6.32	402.90

Status: Completed

Job Subtotal: \$732.90

Job05 (D5) Inner R.Axle Seals (w/abs)Ad Labor: \$356.40

With Wheels and brakes already removed
 Remove outer axle hub
 Install replacement inner axle seals and gaskets

FTC3650	GASKET JOINT (rov/abs)-N	2.0 @	5.15 =\$	10.30	
FTC5268	STUB AXL SEAL IN F&R(r-N	2.0 @	11.48 =\$	22.96	
MPS-100	PARTS CLEANER-N	1.0 @	17.02 =\$	17.02	50.28

Status: Completed

Job Subtotal: \$406.68

Job06 Right Side Rear Stop Bulb Labor: \$13.20

Remove lamp guard and lens
 Install replacement bulb Refit lens and guard

1156	BULB SINGLE CON 21W-N	1.0 @	3.65 =\$	3.65	3.65
------	-----------------------	-------	----------	------	------

Status: Completed

Job Subtotal: \$16.85

PLEASE UPDATE MILEAGE

Tire Pressure: h

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
220518001

Order Date 05/18/12 08:18 am
Closed 5/26/2012

3462

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	1270.80
Parts	648.56
Haz Waste	5.00
Subtotal	1924.36
Tax	55.13
Total	\$1979.49

1 05/22/12 1979.49 On Acct
--A/R Pmt Allocations--
06/05/12 \$1,979.49
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
211221003

Order Date 12/21/11 09:46 am
Closed 12/24/2011

3262

PLEASE UPDATE MILEAGE

Tire Pressure: declined

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	858.00
Parts	728.44
Subtotal	1586.44
Tax	61.92
Total	\$1648.36

1 12/23/11 1648.36 On Acct
--A/R Pmt Allocations--
01/23/12 \$1,648.36
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 210718003

Order Date 07/18/11 08:58 am
 Closed/Paid: 07/22/11 10:01 am

Silberg, Dr Barry
 1111 S...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:121608 out:121608
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 07/18/11 03:02pm 132.00
 Dr in person.

Front Windshield Insurance separate invoice
 last oil service january

Job01 Check Pass Seat switch Labor: \$0.00

go forward but not back
 Removed, cleaned and refit, still not working, turminals burnt, recommend
 replacement and installed

PRC8096	SEAT SWITCH L/S(rov)-N	1.0 @	149.32 =\$	149.32	149.32
---------	------------------------	-------	------------	--------	--------

Status: Completed Tech: Dr.

Job Subtotal: \$149.32

Job02 (5) Rover Oil, Lube Service Labor: \$15.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL CASTROL (pnt)-N	13.0 @	3.96 =\$	51.48	
ERR3340	OIL FILTER (rov)-N	1.0 @	21.62 =\$	21.62	
ETC7398	OIL DRAIN SEAL (disc/ro)-N	1.0 @	3.58 =\$	3.58	
00748	WASHER FLUID-N	1.0 @	3.07 =\$	3.07	79.75

Status: Completed

Job Subtotal: \$94.75

Recommendations: Steering Box Leaking

PLEASE UPDATE MILEAGE

Tire Pressure: LF[28] RF[28] LR [38] RR [38]

Payments to British European Motors Cost Summary

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
210718003

Order Date 07/18/11 08:58 am
Closed/Paid: 07/22/11 10:01 am

Payments to British European Motors

Cost Summary

Labor	15.00
Parts	229.07
Haz Waste	5.00
deductible	250.00
Subtotal	499.07
Tax	19.47
Total	\$518.54
Payments	518.54
Bal Due	0.00

Status: Closed Work Order

Payments: \$518.54

1 07/22/11 518.54 Visa

Thank you for choosing British European Motors

British European Motors
 606 Portal Street
 Cotati, CA 94931
 Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
 210720003

Order Date 07/20/11 09:21 am
 Closed 7/23/2011

WIND

<p>Salberg, Dr. Patty 12345 Main St Cotati, CA 94931 Phone: 707 792-1234</p>	<p>92 Land Rover RANGE ROVER LS Mileage in:121608 out:117966 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021</p>
---	---

auth ref # 598661
 USAA 614-602-2120 nett operations phone

Job01 Replace Front Windshield	Labor: \$152.00
--------------------------------	-----------------

Replacement windshield

FW00622GTNYCOM	WINDSHIELD HEATED-S	1.0 @	776.13 =\$	776.13
HAH000004	ADHESIVE-S	1.0 @	30.00 =\$	30.00
WBL576	WEATHSTRIP-S	1.0 @	198.53 =\$	198.53 1004.66

Status: Completed Tech: SL

Job Subtotal: \$1,156.66

Recommendations: Steering Box Leaking

PLEASE UPDATE MILEAGE

Tire Pressure: LF
 RF
 LR
 RR

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	152.00
Parts	1004.66
deductible	-250.00
Subtotal	906.66

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
210720003

Order Date 07/20/11 09:21 am
Closed 7/23/2011

WIND

Payments to British European Motors

Cost Summary

Tax	85.40
Total	\$992.06

1 07/22/11 992.06 On Acct
--A/R Pmt Allocations--
08/29/11 \$992.06
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 210426004

Order Date 04/26/11 11:49 am
 Closed/Paid: 05/02/11 03:20 pm

Silberg, Dr Barr	92 Land Rover RANGE ROVER LS	Quotes	
	Mileage in:117966 out:117966 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	1 05/02/11 03:19pm	54.45
		Dr in person.	

Job01 Install R/F Bumper End Cap	Labor: \$39.60
----------------------------------	----------------

Main mounting clip supplied @ no charge
 Retaining clips supplied

NTC7867	BUMPER RET CLIP-N	4.0 @	3.39 =\$	13.56	13.56
---------	-------------------	-------	----------	-------	-------

Status: Completed Tech: Dr.

Job Subtotal: \$53.16

Recommendations: Steering Box Leaking

PLEASE UPDATE MILEAGE

Tire Pressure:LF[] RF[] LR[] RR[]

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Status: Closed Work Order

Payments: \$54.45

1 05/02/11 54.45 Visa

Labor	39.60
Parts	13.56
Subtotal	53.16
Tax	1.29
Total	\$54.45
Payments	54.45
Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 210406004

Order Date 04/06/11 11:21 am
 Closed 4/9/2011

Silberg, Dr Barry	92 Land Rover RANGE ROVER LS Mileage in:117966 out:117966 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	Quotes 1 04/11/11 09:53am 84.40 Dr. Barry in person.
-------------------	--	--

Job01 Replace R/F Bumper End Cap Labor: \$13.20

RTC5695	END CAP R/F (rov)-N	1.0 @	65.02 =\$	65.02	65.02
---------	---------------------	-------	-----------	-------	-------

Status: Completed Tech: Dr.

Job Subtotal: \$78.22

Recommendations: Steering Box Leaking

PLEASE UPDATE MILEAGE

Tire Pressure:declined

Payments to British European Motors Cost Summary

Labor	13.20
Parts	65.02
Subtotal	78.22
Tax	6.18
Total	\$84.40

1 04/08/11 84.40 On Acct
 --A/R Pmt Allocations--
 05/02/11 \$84.40
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 210110010

Order Date 01/10/11 05:09 pm
 Closed/Paid: 01/12/11 04:11 pm

2777

Silberg, Dr Harry

92 Land Rover RANGE ROVER LS
 Mileage in:117966 out:117966
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 01/10/11 05:15pm 397.68
 Dr in person.

Job01 (5) Rover Oil, Lube Service Labor: \$30.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL CASTROL (pnt)-N	13.0 @	3.87 =\$	50.31
ERR3340	OIL FILTER (rov)-N	1.0 @	21.62 =\$	21.62
ZEP003801	PARTS CLEANER-N	0.5 @	17.02 =\$	8.51
ETC7398	OIL DRAIN SEAL (disc/ro)-N	1.0 @	3.58 =\$	3.58
564258	OIL FILLER CAP SEAL(rov)-N	1.0 @	3.03 =\$	3.03
00748	WASHER FLUID-N	1.0 @	3.07 =\$	3.07 90.12

Status: Completed Job Subtotal: \$120.12

Job02 Check Door Lock Fault Labor: \$250.80

Remove door panel and found linkage off
 Cleaned out latch and lubed all linkages and operating levers
 Repaired/adjusted linkage.
 Screw attach door pocket panel
 Refit panel and secure
 Recheck operation

Status: Completed Job Subtotal: \$250.80

Job03 Rear Window Repair Labor: \$79.20

for heated rear window

PRM21351	DEFOGGER TAB GLUE-S	1.0 @	19.69 =\$	19.69 19.69
----------	---------------------	-------	-----------	-------------

Status: Completed
 Scheduled for: 01/12/11 10:00 am

Job Subtotal: \$98.89

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
210110010

Order Date 01/10/11 05:09 pm
Closed/Paid: 01/12/11 04:11 pm

2777

Job04 Check C.Control No-op Labor: \$0.00

hold

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Job05 Rear Cargo Peg Labor: \$0.00

Peg - N/A,

057.6.30	METRIC BOLT 6X30-N	1.0 @	0.71 =\$	0.71	
317.6	METRIC NUT 6MM-N	2.0 @	0.18 =\$	0.36	
WASHER	WASHER (FLAT)-N	2.0 @	0.11 =\$	0.22	1.29

Status: Completed

Job Subtotal: \$1.29

Job06 Clean And Adjust Washer Jets Labor: \$0.00

Status: Completed

Job Subtotal: \$0.00

Job07 Refit Fan Shroud Labor: \$0.00

Status: Completed

Job Subtotal: \$0.00

Recommendations: Steering Box Leaking

PLEASE UPDATE MILEAGE

Tire Pressure:LF[28] RF[28] LR[41] RR[41]

Payments to British European Motors Cost Summary

Labor 360.00

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
210110010

Order Date 01/10/11 05:09 pm
Closed/Paid: 01/12/11 04:11 pm

2777

Payments to British European Motors

Cost Summary

Parts	111.10
Haz Waste	5.00
Subtotal	476.10
Tax	10.55
Total	\$486.65
Payments	486.65
Bal Due	0.00

Status: Closed Work Order

Payments: \$486.65

1 01/12/11 486.65 MCard

Thank you for choosing British European Motors

Invoice No.
 201220008

Order Date 12/20/10 04:40 pm
 Closed/Paid: 12/22/10 12:54 pm

2743

Silberg, Dr Barry

92 Land Rover RANGE ROVER LS
 Mileage in:117311 out:117311
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 12/20/10 04:51pm 915.42
 Dr.Barry in person.

2743

Job01 (E5) Replace Ignition Sw (int) Labor: \$237.60

Remove steering turn/wiper covers.
 Remove ignition switch and install replacement.
 Actuate switch and check correct operation
 Refit panels and recheck

NTC9440 STEER LOCK (int.lock)-N 1.0 @ 389.97 =\$ 389.97 389.97

Status: Completed Tech: Dr.

Scheduled for: 12/22/10 08:30 am

Job Subtotal: \$627.57

Job02 Cruise Control Non Op. Labor: \$0.00

Changed main feed hose from actuator to 't' piece, did not get to test,

Status: Completed Tech: Dr.

Scheduled for: 12/22/10 10:00 am

Job Subtotal: \$0.00

Job03 Rear Window Ellimnt/Lamp Loose Labor: \$0.00

Remove lamp cover and secure with replacement screw and one rivet
 Refit trim
 Will need elliment adhesive, will order and call when comes in

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Job04 Rear View Mirror-Loose Labor: \$0.00

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
201220008

Order Date 12/20/10 04:40 pm
Closed/Paid: 12/22/10 12:54 pm

2743

Job04 Rear View Mirror-Loose

Recheck at next service

Status: Completed

Job Subtotal: \$0.00

Job05 Repair Steering Cover Trim

Labor: \$66.00

Additional time to glue and refix trim around steering column and switches

Status: Completed Tech: Dr.

Job Subtotal: \$66.00

Recommendations: steering box leaking?

PLEASE UPDATE MILEAGE

Payments to British European Motors

Cost Summary

Status: Closed Work Order

Payments: \$730.62

1 12/22/10 730.62 Visa

Labor	303.60
Parts	389.97
Subtotal	693.57
Tax	37.05
Total	\$730.62
Payments	730.62
Bal Due	0.00

Thank you for choosing British European Motors

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
200616002

Order Date 06/16/10 08:45 am
Closed/Paid: 06/16/10 04:35 pm

Recommendations: steering box leaking, will change next month

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Status: Closed Work Order

Payments: \$789.45

1 06/16/10 400.00 Cash
2 06/16/10 389.45 AMEX

Labor	557.40
Parts	212.89
Subtotal	770.29
Tax	19.16
Total	\$789.45
Payments	789.45
Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 200715003

Order Date 07/15/10 04:01 pm
 Closed/Paid: 07/25/10 12:46 pm

Silberg, Dr Barry 1211...	92 Land Rover RANGE ROVER LS Mileage in:112756 out:112756 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021
--	--

Job01 Rplc Rear Lap Belt/Check Brake w Labor: \$37.80

Install and check brake waring light coming on
 Front pads and rotors

BEM54564	USED REAR LAP BELT-S	1.0 @	75.00 =\$	75.00	75.00
----------	----------------------	-------	-----------	-------	-------

Status: Completed Tech: Dr.

Scheduled for: 07/16/10 08:30 am

Job Subtotal: \$112.80

Job02 (B5) Replc F.Brk Pads/Rotrs(90- Labor: \$390.00

Raise vehicle and remove front wheels. Remove front axles and remove hub, rotor and brake caliper assembly. Check and clean all area, clean and inspect/replace hub bearings and repack Refit hub and rotor. Refit brake caliper and install new pads. Refit road wheels and road test complete.+

FTC4785	HUB SEAL ALL (rov)-N	2.0 @	9.76 =\$	19.52	
FTC902	F.BRAKE ROTOR/VENT 90--N	2.0 @	102.39 =\$	204.78	
571752	GASKET AXLE FLANGE(rov-N	2.0 @	1.68 =\$	3.36	
STC3765	F.BRAKE PAD (disco/rov-N	1.0 @	155.30 =\$	155.30	
ZEP003801	PARTS CLEANER-N	1.0 @	17.02 =\$	17.02	
BG860	ANTI-SQUEEL PAD TREATMNT-N	1.0 @	11.93 =\$	11.93	
217353	LOCK TAB AXLE BRG (rov-N	2.0 @	3.16 =\$	6.32	418.23

Status: Completed
 Scheduled for: 07/19/10 09:30 am

Job Subtotal: \$808.23

Recommendations: steering box leaking, will change next month

PLEASE UPDATE MILEAGE

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
200715003

Order Date 07/15/10 04:01 pm
Closed/Paid: 07/25/10 12:46 pm

Payments to British European Motors

Cost Summary

Status: Closed Work Order

Payments: \$970.42

1 07/25/10 970.42 Visa

Labor	427.80
Parts	493.23
S&H	5.00
Subtotal	926.03
Tax	44.39
Total	\$970.42
Payments	970.42
Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 200503004

Order Date 05/03/10 10:20 am
 Closed/Paid: 05/07/10 05:00 pm

2338

Silberg, Dr. Paul	92 Land Rover RANGE ROVER LS	Quotes
	Mileage in:111979 out:111979 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	1 05/03/10 05:04pm 0.00 Dr in person.
		2 05/05/10 09:08am 1084.86 Dr Silberg in person. Job #1-4

Job01 Headliner Materials-Panel R&R Labor: \$126.00

Materials for headliner replacement and labor time to remove and refit slider trim and glass panel

RE9843	MATERIALS-S	1.0 @	55.00 =\$	55.00	55.00
--------	-------------	-------	-----------	-------	-------

Status: Completed Tech: Dr.

Job Subtotal: \$181.00

Job02 Headliner Sublet: \$600.00

Remove healiner and old trim
 Install replacement and refit all

Job03 Rear Shock Bushings-LOWER Labor: \$189.00

Remove rear shocks and install replacement lower bushings
 Secure all, road test

552818	SHOCK BUSHINGS-N	4.0 @	4.98 =\$	19.92	19.92
--------	------------------	-------	----------	-------	-------

Status: Completed Tech: Dr.

Scheduled for: 05/07/10 08:30 am

Job Subtotal: \$208.92

Job04 Check Sunroof Drains/Correct Labor: \$88.20

Check with tilt panel out and confirm drains are ok
 Blow out and slide rioid through all drains, right side front badly blocked, ok now
 Flow water onto roof and confirm draining away

Status: Completed Job Subtotal: \$88.20

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
200503004

Order Date 05/03/10 10:20 am
Closed/Paid: 05/07/10 05:00 pm

2338

PLEASE UPDATE MILEAGE

Payments to British European Motors

Cost Summary

Status: Closed Work Order

Payments: \$1,084.86

1 05/07/10 1084.86 Visa

Labor	403.20
Parts	74.92
Sublet	600.00
Subtotal	1078.12
Tax	6.74
Total	\$1084.86
Payments	1084.86
Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 200329004

Order Date 03/29/10 02:22 pm
 Closed/Paid: 04/01/10 02:05 pm

2280/Door

Silberg, Dr Barry	92 Land Rover RANGE ROVER LS	<u>Quotes</u>	
	Mileage in:111577 out:111577 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	1 03/29/10 02:24pm	132.00
		Dr in person.	
		2 03/31/10 09:28am	874.69
		Dr. Barry in person.	

USAA -1800-531-8222
 0842937
 CHRIS 79308

Job01 Check Right Rear Door Lock Fault	Labor: \$132.00
--	-----------------

had window replaced.
 Removed door panel and traced fault down to broken door latch, recommend replacement.

Status: Completed Tech: Dr.

Job Subtotal: \$132.00

Job02 (K5) R/R Door Lock/Latch Assy	Labor: \$343.20
-------------------------------------	-----------------

Dissassemble door lock mechanism and remove
 Install replacement and secure/adjust all rods
 Check operation and refit/secure door panel

FQM100680	DOOR LOCK ACTUATR (R/R-N	1.0 @	366.50 =\$	366.50	366.50
-----------	--------------------------	-------	------------	--------	--------

Status: Completed

Job Subtotal: \$709.70

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	475.20
Parts	366.50
Subtotal	841.70
Tax	32.99
Total	\$874.69
Payments	874.69

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
200329004

Order Date 03/29/10 02:22 pm
Closed/Paid: 04/01/10 02:05 pm

2280/Door

Payments to British European Motors

Cost Summary

Bal Due 0.00

Status: Closed Work Order

Payments: \$874.69

1 04/01/10 874.69 Visa

Thank you for choosing British European Motors

Invoice No.
 200318006

Order Date 03/18/10 05:24 pm
 Closed 3/20/2010

2263

Silbers, Dr Barry	92 Land Rover RANGE ROVER LS	Quotes
	Mileage in:111474 out:111474 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	1 03/19/10 08:41am 144.00 Dr in person.
		2 03/19/10 10:43am 1141.29 Dr. Barry in person. Jobs 2-3

Job01 Check Engine Fault Diagnosis Labor: \$144.00

starts up, but hard time running.
 Hooked up fuel gauge ,Traced down to a bad fuel pump , recommend replacement fuel pump and recheck running fault.

Status: Completed
 Scheduled for: 03/19/10 10:30 am

Job Subtotal: \$144.00

Job02 (F5) Replace Fuel Pump (91-92) Labor: \$189.00

Remove carpet in rear compartment. Lift under insulation and remove fuel pump cover plate. Remove fuel pump and install replacement.
 Update wiring harness (if applicable) and install replacement crimp fittings.
 Refit cover and carpet. Replacement of fuel filter and relay if listed in parts area.

NTC5859	FUEL PUMP SEAL (rov)-N	1.0 @	22.84 =\$	22.84	
NRC9771	FUEL PUMP FITTING-N	2.0 @	2.68 =\$	5.36	
PRC9409	FUEL PUMP(rov)L91--N	1.0 @	480.02 =\$	480.02	
NRC9770	FUEL PUMP FITTING(rov)-N	2.0 @	6.74 =\$	13.48	
3481	FUEL FILTER (rov/jag)-N	1.0 @	26.18 =\$	26.18	547.88

Status: Completed Tech: Dr.

Job Subtotal: \$736.88

Job03 (5) Rover Oil, Lube Service Labor: \$30.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel leaks general inspection of complete vehicle

20/50	ENGINE OIL CASTROL (pnt)-N	13.0 @	3.72 =\$	48.36	
-------	----------------------------	--------	----------	-------	--

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors

606 Portal Street
 Cotati, CA 94931
 Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
 200318006

Order Date 03/18/10 05:24 pm
 Closed 3/20/2010

2263

Job03 (5) Rover Oil, Lube Service

ERR3340	OIL FILTER (rov)-N	1.0 @	21.62 =\$	21.62	
ZEP003801	PARTS CLEANER-N	0.5 @	17.02 =\$	8.51	
ETC7398	OIL DRAIN SEAL (disc/ro)-N	1.0 @	3.58 =\$	3.58	
564258	OIL FILLER CAP SEAL(rov)-N	1.0 @	3.03 =\$	3.03	
00748	WASHER FLUID-N	1.0 @	3.07 =\$	3.07	88.17

Status: Completed
 Scheduled for: 03/19/10 03:30 pm

Job Subtotal: \$118.17

Job04 Lube Ign Lock	Labor: \$0.00
---------------------	---------------

Status: Completed
 Scheduled for: 03/19/10 04:00 pm

Job Subtotal: \$0.00

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	363.00
Parts	636.05
Haz Waste	5.00
towing fee	80.00
Subtotal	1084.05
Tax	57.24
Total	\$1141.29

1 03/19/10 1141.29 On Acct
 --A/R Pmt Allocations--
 04/19/10 \$1,141.29
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 190220003

Order Date 02/20/09 10:10 am
 Closed/Paid: 02/27/09 01:00 pm

Detailing

Silberg, Dr Barry
 1011 1st St
 Cotati, CA 94931
 Phone: 707 792-2737
 Fax: 707 792-4454

92 Land Rover RANGE ROVER LS
 Mileage in:108402 out:108402
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 02/20/09 02:57pm 376.00
 Dr in person.

Job01 Additional Trim Panels Etc Labor: \$0.00

Switch panel supplied

54938	CLUSTER SWITCH PANEL-S	1.0 @	15.00 =\$	15.00	15.00
-------	------------------------	-------	-----------	-------	-------

Status: Completed Tech: SL

Job Subtotal: \$15.00

Job02 Repair Console Labor: \$289.80

Fabricate brackets and secure all areas around center console

Status: Completed

Job Subtotal: \$289.80

Job03 Polish & Wax Sublet: \$150.00

cut tops, buff and polish
 Hand Wax

PLEASE UPDATE MILEAGE

Payments to British European Motors Cost Summary

Labor	289.80
Parts	15.00
Sublet	150.00
Discount	555.96
Deductible	250.00
Subtotal	148.84

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
 606 Portal Street
 Cotati, CA 94931
 Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
 190515002

Order Date 05/15/09 12:57 pm
 Closed/Paid: 05/15/09 12:57 pm

BATT/WARR

Silberg, Dr Barry 1111 1st St Cotati, CA 94931 Phone: 707-792-2737 Fax: 707-792-4454	92 Land Rover RANGE ROVER LS Mileage in:108886 out: Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021
--	--

Job01 (E5) Replace Battery	Labor: N/C
----------------------------	------------

Remove and install replacement battery

MT-34	BATTERY (xj6/rov)-N	1.0 @	129.41 =\$	N/C
MT-34	BATTERY (xj6/rov)-N	-1.0 @	129.41 =\$	N/C

~~Status: Completed~~

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Status: Closed Work Order

Payments:

Labor	0.00
Parts	0.00
Subtotal	0.00
Total	\$0.00
Payments	0.00
Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 190211002

Order Date 02/11/09 10:17 am
 Closed/Paid: 02/27/09 05:00 pm

USSA

Silburt, Dr Barry
 10000
 10000
 10000
 10000

92 Land Rover RANGE ROVER LS
 Mileage in:108402 out:108402
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 02/26/09 03:30pm 3098.31
 BO by phone 800-531-8669

att Bo 805-898-2374

USSA-#842937
 FAX-1800-531-8669
 1-800-531-USAA (8722)

Job01 Check Blower/Heater Fault Labor: \$188.00

Diagnosis to trace fault and confirmed blower motor non operational, check blower resistor pack, only will allow full power to blower motor, still no operation of blower motor, a/c blower working, only blowing on high
 Systems separate blowers but has same resistor pack
 Resistor pack and disassembly of heater unit to determine heater blower motor non operation
 Remove interior and dash to access blower/heater assembly
 Removed and found insulation missing/chewed, heater box damage, rodent nest found inside blower, wires chewed through causing motor restriction and failure, overload of resistor pack and related circuits. box assembly not re-usable, Wiring also chewed, replacement assembly required

Status: Completed Job Subtotal: \$188.00

Job02 Heater Blower Motor Assembly Labor: \$963.60

Labor to remove and install replacement blower/heater assembly
 Install replacement heater core
 Temp hook up run system electrical to confirm no further damage to heater blower and associated system
 Re-assemble heater unit and install in vehicle
 Add coolant and run engine to operating temp
 (NO CHARGE-Add Wire shielding to air intake thus preventing further acces for rodents)

A/F	ANTIFREEZE/COOLANT(pnt-R	16.0 @	1.61 =\$	25.76
H/C	HOSE CLAMP-N	4.0 @	2.98 =\$	11.92
ZEP003801	PARTS CLEANER-N	1.0 @	16.01 =\$	16.01
BTR6485	BLOWER ASSY-S	1.0 @	618.28 =\$	618.28

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
 606 Portal Street
 Cotati, CA 94931
 Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
 190211002

Order Date 02/11/09 10:17 am
 Closed/Paid: 02/27/09 05:00 pm

USSA

Job02 Heater Blower Motor Assembly

STC250	HEATER CORE (fov 90-) -N	1.0 @	467.71 = \$	467.71	1139.68
Status: Completed					Job Subtotal: \$2,103.28

Job03 Blower Resistor-Replacement	Labor: \$844.80
-----------------------------------	-----------------

Loosen and remove wiper arms
 Mark, loosen and remove hood
 Loosen and remove front cowling
 Loosen and remove air intake to access resistor
 Remove resistor assembly and correct chewed wiring, update harness to match
 updated resistor assembly
 Secure all and test circuit
 Refit and secure cowling and air intake trim
 Re-attach hood and secure, check adjustment open and closing

PRC8010	BLOWER MOTOR RESISTER-N	1.0 @	71.37 = \$	71.37	71.37
Status: Completed					Job Subtotal: \$916.17

Job04 Coolant Flush/Mechanical	Labor: \$47.00
--------------------------------	----------------

Status: Completed Tech: Dr.

Job Subtotal: \$47.00

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	2043.40
Parts	1211.05
Deductible	-250.00
Subtotal	3004.45
Tax	93.86
Total	\$3098.31

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
190211002

Order Date 02/11/09 10:17 am
Closed/Paid: 02/27/09 05:00 pm

USSA

Payments to British European Motors

Cost Summary

Payments	3098.31
Bal Due	0.00

Status: Closed Work Order

Payments: \$3,098.31

1 02/27/09 3098.31 Check

Thank you for choosing British European Motors

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
190220003

Order Date 02/20/09 10:10 am
Closed/Paid: 02/27/09 01:00 pm

Detailing

Payments to British European Motors

Cost Summary

Tax	1.16
Total	\$150.00
Payments	150.00
Bal Due	0.00

Status: Closed Work Order

Payments: \$150.00

1 02/27/09 150.00 Visa

Thank you for choosing British European Motors

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
190107002

Order Date 01/07/09 11:18 am
Closed 1/10/2009

1553

Job07 Parts Only

HJA2132AALFJ	BLANKING PLUG-S	1.0 @	2.08 =\$	2.08	2.08
					Job Subtotal: \$2.08

Status: Completed

Recommendations:

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	486.00
Parts	567.88
Haz Waste	2.98
Discount	50.00
Subtotal	1006.86
Tax	40.14
Total	\$1047.00

1 01/09/09 1047.00 On Acct
--A/R Pmt Allocations--
01/30/09 \$1,047.00
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 1

Invoice No.
190127001

Order Date 01/27/09 08:38 am
Closed/Paid: 01/30/09 12:32 pm

1588

Silberg, Dr Barry

92 Land Rover RANGE ROVER LS
Mileage in:108279 out:108279
Lic: 3BKH816/CA 8Cyl 4.0
Vin: SALHV1246NA618427 01/92
Eq: AT AC PS FI 4W
Last in 11/12/2021

Quotes

1 01/27/09 10:49am 178.40
Dr in person.

Job01 Check Heater Blower Motor Fault

Labor: \$158.40

Remove trim around blower switch (trim is cracked, bulbholder broken)
Remove switch and check operation
Check power from switch to resistor pack and blower
circuits all ok at this time ,replacement blower motor assembly

Status: Completed Tech: Dr.

Job Subtotal: \$158.40

Recommendations: Replacement blower motor required/trim panel

PLEASE UPDATE MILEAGE

Payments to British European Motors

Cost Summary

Status: Closed Work Order

Payments: \$178.40

1 01/30/09 178.40 Visa

with last invc

Labor	158.40
Parts	0.00
SHIPPING	20.00
Subtotal	178.40
Total	\$178.40
Payments	178.40
Bal Due	0.00

Thank you for choosing British European Motors

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
180227002

Order Date 02/27/08 01:51 pm
Closed 3/1/2008

Job04 (G5) Flange Gasket Replace Both

REmove and lower front section of exhaust system
Remove old studs and clean manifold surfaces
Draw file flat exhaust downpipe flanges
Install replacement manifold flange studs
Install replacement flange gaskets and nuts
Refit section of exhaust and secure.

FN108041L	EX MANIFOLD NUT-N	6.0 @	2.39 =\$	14.34	
ETC4524	EXHAUST FLANGE GASKET-N	2.0 @	13.96 =\$	27.92	
ERR551L	EXHAUST STUD (disc)-N	6.0 @	3.90 =\$	23.40	65.66

Job Subtotal: \$490.66

Status: Completed

Recommendations: Recheck Rear Brakes & brake pulsation at Next Service

Right rear mud flap cracking (rubber getting old)

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	644.00
Parts	135.72
Haz Waste	5.00
Subtotal	784.72
Tax	10.52
Total	\$795.24

1 02/29/08 795.24 On Acct
--A/R Pmt Allocations--
02/20/18 \$795.24
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
180702002

Order Date 07/02/08 10:26 am
Closed 7/5/2008

Dr Barry
1245

92 Land Rover RANGE ROVER LS
lease in:106912 out:106912
C: 3BKH816/CA 8Cyl 4.0
VIN: SALHV1246NA618427 01/92
T: AT AC PS FI 4W
last in 11/12/2021

Quotes		
1	07/02/08 10:52am	250.00
DrBarry in person.		
2	07/03/08 09:52am	499.11
Dr. Barry by phone 707-528-09		
job # 3		

1245

Job01 Check Drivers Seat Switch Labor: \$137.50

Fault in seat switch, repair or replace
Remove switch and open
Clean contacts in switch and re-assemble
Refit in holder and check seat positions and operation
Secure trim

Job Subtotal: \$137.50

Status: Completed

Job02 ABS Pump Runs Long Time Labor: \$187.50

Pump has been running up to a couple of minutes in the morning, not all the time,
check operation of pump, switch and accumulator
All appears normal at time of testing, would recommend at least changing pump
relay
Disconnect and remove lower scuttle panel and install replacement relay
Check operation and refit lower scuttle panel

PRC9603	A.B.S. RELAY (rov)-N	1.0 @	33.98 =\$	33.98	33.98
---------	----------------------	-------	-----------	-------	-------

Status: Completed
Scheduled for: 07/03/08 07:30 am

Job Subtotal: \$221.48

Job03 Check Pass. Seat Switch Labor: \$137.50

Fault in seat switch, repair or replace
Remove switch and open
Clean contacts in switch and re-assemble
Refit in holder and check seat positions and operation
Secure trim

Status: Completed
Scheduled for: 07/03/08 09:30 am

Job Subtotal: \$137.50

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
180702002

Order Date 07/02/08 10:26 am
Closed 7/5/2008

Recommendations: Recheck Rear Brakes & brake pulsation at Next Service
Right rear mud flap cracking (rubber getting old)

PLEASE UPDATE MILEAGE

Payments to British European Motors

Cost Summary

Labor	462.50
Parts	33.98
Subtotal	496.48
Tax	2.63
Total	\$499.11

1 07/03/08 499.11 On Acct
--A/R Pmt Allocations--
07/21/08 \$499.11
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 180519004

Order Date 05/19/08 12:25 pm
 Closed 5/23/2008

Silberg, Dr Barry 1111 Spruce Ave Cotati, CA 94931 Phone: 707 792-2737	92 Land Rover RANGE ROVER LS Mileage in:106802 out:106802 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	Quotes 1 05/19/08 12:32pm 393.22 Dr Barry in person.
---	--	--

1173

Job01 Check A/c Fault **Labor: \$62.50**

Compressor activating, would recommend servicing the system and recheck

Status: Completed
 Scheduled for: 05/19/08 09:30 am Job Subtotal: \$62.50

Job02 ()Air Conditioning Service 134** **Labor: \$192.00**

Hook up A/C rec machine // Drain/evacuate//hold test//recharge including leak dye to man specs
 Test leaks ok

R-134A	FREON R-134A-N	48.0 @	1.29 =\$	61.92	
BG702	LEAK DYE/LUBRICANT(a/c)-N	1.0 @	16.00 =\$	16.00	
BG708	FRIGI FRESH (a/c fresh)-N	1.0 @	16.02 =\$	16.02	93.94

Status: Completed Tech: SL Job Subtotal: \$285.94

Job03 Clean Out Trapped Leaves **Labor: \$37.50**

Loosen and tilt back radiator and grill
 Blow and clean out draied leaves making contact with fans
 Refit mouting brackets and secure

Status: Completed Job Subtotal: \$37.50

Recommendations: Recheck Rear Brakes & brake pulsation at Next Service
 Right rear mud flap cracking (rubber getting old)

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
180519004

Order Date 05/19/08 12:25 pm
Closed 5/23/2008

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	292.00
Parts	93.94
Subtotal	385.94
Tax	7.28
Total	\$393.22

1 05/21/08 393.22 On Acct
--A/R Pmt Allocations--
07/03/08 \$393.22
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

British European Motors
 606 Portal Street
 Cotati, CA 94931
 Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
 171210003

Order Date 12/10/07 10:16 am
 Closed 12/15/2007

Silberg, Dr Barry
 11111111111111111111
 11111111111111111111
 11111111111111111111
 11111111111111111111
 11111111111111111111

92 Land Rover RANGE ROVER LS
 Mileage in:106213 out:106213
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes		
1	12/10/07 01:54pm	276.00
Dr in person.		
2	12/10/07 03:53pm	425.29
Dr Barry in person.		
job # 3		

1861

Job01 Check Dead Battery Diagnosis	Labor: \$138.00
------------------------------------	-----------------

Check charging system, battery and diagnose. charging 100 amps/13.8, Traced to battery testing bad

Status: Completed Job Subtotal: \$138.00

Job02 Check Dash Lights No-op	Labor: \$110.40
-------------------------------	-----------------

Dimmer Switch Connector Came Loose, Refit, and tested, ok at this time

Status: Completed Job Subtotal: \$110.40

Job03 (E5) Replace Battery	Labor: \$59.00
----------------------------	----------------

Remove and install replacement battery

MT-34	BATTERY (xj6/rov)-N	1.0 @	109.41 =\$	109.41	109.41
					Job Subtotal: \$168.41

Status: Completed

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	307.40
Parts	109.41
Subtotal	416.81
Tax	8.48

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
171210003

Order Date 12/10/07 10:16 am
Closed 12/15/2007

Payments to British European Motors

Cost Summary

Total \$425.29

1 12/13/07 425.29 On Acct
--A/R Pmt Allocations--
01/04/08 \$425.29
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 170927001

Order Date 09/27/07 09:53 am
 Closed 11/3/2007

Silberg, Dr Barry
 1111 S. ...
 ...
 ...
 ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:105144 out:105144
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 09/27/07 10:07am 138.00
 Dr in person.

1705 TAGS?

in park, -pick up at office

Job01 Check Shifting Sticking	Labor: \$96.60
-------------------------------	----------------

Check solenoid and wiring from switch and signal at shifter

Status: Completed Job Subtotal: \$96.60

Job02 (E5) Replace Brake Light Switch	Labor: \$153.40
---------------------------------------	-----------------

Remove lower panel and remove switch.
 Install replacement switch and adjust setting
 Check cruise cancel operation and A.B.S sensing function

AMR2010	BRAKE SWITCH (rov)-N	1.0 @	47.72 =\$	47.72	47.72
---------	----------------------	-------	-----------	-------	-------

Status: Completed Job Subtotal: \$201.12

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	250.00
Parts	47.72
Subtotal	297.72
Tax	3.70
Total	\$301.42

1 11/02/07 301.42 On Acct
 --A/R Pmt Allocations--
 12/11/07 \$301.42
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 170305006

Order Date 03/05/07 11:47 am
 Closed 3/10/2007

Silberg, Dr Barry
 1234

92 Land Rover RANGE ROVER LS
 Mileage in:105144 out:105144
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 03/05/07 11:49am 1350.80
 Dr in person.

1234

Job01 Check A/C Faults Labor: \$182.00

just had 134a swap, doest seem to get cold enough. Doesn't work on low and med,
 only on high.
 Traced fault to blower resistor behind front cowling
 Wiring loose, attempt to solder, not possible will need to replace
 Ran system again, hook up pressure guages, system has full pressure, flow is
 minimal? Low pressure pulling into vacuum, high pressure climbing, system hoses
 not getting cold, reduced flow possible expansion valve, will need to replace

Job Subtotal: \$182.00

Status: Completed

Job02 (H5) Replace Expansion Valve Labor: \$613.60

Evacuate system. Remove dash panels right side to gail entry to valve. Disconect
 lines and remove valve. Clean out filter and refit. Install new valve and refit
 lines. Check for clearance thru to engine compartment. Refit dash panels and
 connect all lines. (EVACUATION/HOLD/RECHARGE SEPERATE OPERATION)

RTC6143	EXPANSION VALVE (rov) -N	1.0 @	58.73 =\$	58.73	58.73
---------	--------------------------	-------	-----------	-------	-------

Job Subtotal: \$672.33

Status: Completed

Job03 (H5) Replace Receiver/Dryer Labor: \$259.60

check system evacuated and remove receiver/dryer lines
 Disconnect and remove dryer
 Install replacement with new seals and secure

BTR3717	REC/DRYER (rov) -N	1.0 @	190.89 =\$	190.89	190.89
---------	--------------------	-------	------------	--------	--------

Job Subtotal: \$450.49

Status: Completed

Job04 Replace Blower Resistor Labor: \$141.60

Install and wire in place, recheck all blower speeds

----->----->----->-----Continued on the next page----->----->----->----->

Invoice No.
 170305006

Order Date 03/05/07 11:47 am
 Closed 3/10/2007

Job04 Replace Blower Resistor

PRC8010	PRC8010-N	1.0 @	62.21 =\$	62.21	62.21
---------	-----------	-------	-----------	-------	-------

Job Subtotal: \$203.81

Status: Completed

Job05 (**)Air Conditioning Service 134	Labor:	N/C
--	--------	-----

Hook up A/C rec machine // Drain/evacuate//hold test//recharge including leak dye
 to man specs
 Test leaks ok

R-134A	FREON R-134A-N	48.0 @	1.29 =\$	N/C
BG702	LEAK DYE/LUBRICANT (a/c) -N	1.0 @	16.00 =\$	N/C

Status: Completed Tech: Dr.

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	1196.80
Parts	311.83
Discount	182.00
Subtotal	1326.63
Tax	24.17
Total	\$1350.80

1 03/08/07 1350.80 On Acct
 --A/R Pmt Allocations--
 03/16/07 \$1,350.80
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 170220001

Order Date 02/20/07 09:58 am
 Closed 2/24/2007

Silberg, Dr Barry	92 Land Rover RANGE ROVER LS	<u>Quotes</u>	
	Mileage in:105144 out:105144 Lic: 3BKH816/CA 8Cyl 4.0	1 02/20/07 10:04am	354.00
	Vin: SALHV1246NA618427 01/92	Dr in person.	
	Eq: AT AC PS FI 4W	2 02/20/07 04:42pm	871.35
	Last in 11/12/2021	Dr Barry in person.	
		Jobs 1-4	

Job01 Pass Front Door No-op Labor: \$118.00

From the outside
 **Ajusted Pass front door latch, and Clean.ok at this time, check a couple of time.

Status: Completed

Job Subtotal: \$118.00

Job02 Rear Defroster No-op Labor: \$224.20

Will have to Adhesive weld connector

765-2634	ADHESIVE, ELEC-S	1.0 @	17.98 =\$	17.98	17.98
----------	------------------	-------	-----------	-------	-------

Job Subtotal: \$242.18

Status: Completed

Job03 Check A/c No-op Diagnosis Labor: \$118.00

Rec switching to 134a and recheck for leaks

Status: Completed

Job Subtotal: \$118.00

Job04 (**)Air Conditinng CHANGE to-134 Labor: \$212.00

Hook up A/C rec machine // Drain/evacuate//hold test
 Add clean 134 oil to required amount
 Install correct replacement fittings
 Add clean recharge of 134 freon and check for leaks

R-134A	FREON R-134A-N	64.0 @	1.29 =\$	82.56
409901	A/C FITTING TO R12-134-N	1.0 @	12.03 =\$	12.03
409902	A/C FITTING R12-134-N	1.0 @	16.08 =\$	16.08
PMI-T4-1	A/C LEAK DYE (oz)-N	1.0 @	10.36 =\$	10.36
A/C OIL CHARGE	OIL CHARGE (UNIT)-N	10.0 @	2.98 =\$	29.80

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
170220001

Order Date 02/20/07 09:58 am
Closed 2/24/2007

Job04 (**)Air Conditinng CHANGE to-134

~~BG708 FRIGI FRESH (a/c fresh)-N 1.0 @ 16.02 =\$ 16.02 166.85~~
Status: Completed Tech: SL

Job Subtotal: \$378.85

PLEASE UPDATE MILEAGE

Payments to British European Motors

Cost Summary

Labor	672.20
Parts	184.83
Subtotal	857.03
Tax	14.32
Total	\$871.35

1 02/23/07 871.35 On Acct
--A/R Pmt Allocations--
02/20/18 \$871.35
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 170117003

Order Date 01/17/07 11:23 am
 Closed 1/18/2007

Silbano, Dr. Barry
 1142
 1142
 1142

92 Land Rover RANGE ROVER LS
 Mileage in:104786 out:104786
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 01/17/07 11:43am 164.18
 Dr in person.
 2 01/17/07 01:56pm 298.79
 Dr Barry in person.
 jobs 1-4

1142

Job01 (5) Rover Oil, Lube Service Labor: \$18.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL GTX (pnt)-N	13.0 @	2.41 =\$	31.33	
ERR3340	OIL FILTER (rov)-N	1.0 @	21.62 =\$	21.62	
ZEP003801	PARTS CLEANER-N	1.0 @	15.98 =\$	15.98	
ETC7398	OIL DRAIN SEAL (disc/ro)-N	1.0 @	3.38 =\$	3.38	
564258	OIL FILLER CAP SEAL(rov)-N	1.0 @	3.03 =\$	3.03	75.34

Status: Completed
 Scheduled for: 01/17/07 07:00 am

Job Subtotal: \$93.34

Job02 Right Front Door Fault No-op Labor: \$35.40

from out side,Clean and lubed ok at this time.

Job Subtotal: \$35.40

Status: Completed

Job03 (*5) Reset `service engine` Labor: \$65.00

Reset 'service engine' light

Status: Completed Tech: Dr.

Job Subtotal: \$65.00

Job04 Check Window Switchs Labor: \$59.00

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
170117003

Order Date 01/17/07 11:23 am
Closed 1/18/2007

Job04 Check Window Switchs

PRC5254	WINDOW SWITCH (rov/R)-N	1.0 @	32.68 =\$	32.68	32.68
---------	-------------------------	-------	-----------	-------	-------

Status: Completed Tech: Dr.

Job Subtotal: \$91.68

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	177.40
Parts	108.02
Haz Waste	5.00
Subtotal	290.42
Tax	8.37
Total	\$298.79

1 01/19/07 298.79 On Acct
--A/R Pmt Allocations--
01/29/07 \$298.79
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 161018002

Order Date 10/18/06 11:28 am
 Closed 10/28/2006

Silber, Dr. Barry	92 Land Rover RANGE ROVER LS	Quotes
	Mileage in:104102 out:103683 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	1 10/18/06 11:37am 130.00 Dr in person.
		2 10/18/06 03:31pm 783.88 Dr. Barry in person. job # 2

1659

Job01 Check Door Lock Fault	Labor: N/C
-----------------------------	------------

Rec job # 2 and recheck fault

Job02 Test Door Locking system	Labor: \$460.20
--------------------------------	-----------------

After removing door panel
 Remove actuator and test, tract from there to main e.c.u under dash
 Order and install replacement, refit door panel and retest

PRC7921	DOOR LOCK E.C.U-S	1.0 @	279.98 =\$	279.98	279.98
---------	-------------------	-------	------------	--------	--------

Job Subtotal: \$740.18

Status: Completed

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	460.20
Parts	279.98
shipping	22.00
Subtotal	762.18
Tax	21.70
Total	\$783.88

1 10/24/06 783.88 On Acct
 --A/R Pmt Allocations--
 10/30/06 \$783.88
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 160803004

Order Date 08/03/06 11:14 am
 Closed 8/19/2006

Silberg, Dr Barry
 1111 Sycamore Ave
 Cotati, CA 94931
 Phone: 707 792-2737
 Fax: 707 792-4454

92 Land Rover RANGE ROVER LS
 Mileage in:103683 out:103683
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes		
1	08/03/06 11:18am	240.00
Dr in person.		
2	08/10/06 11:01am	2044.66
Dr Barry in person.		
jobs 1-8		

1489

Job01 Check Battery Light	Labor: \$120.00
---------------------------	-----------------

off and on-Battery and alternator tested ok
 Low coolant light flashing, radiator has coolant leak

Status: Completed	Job Subtotal: \$120.00
-------------------	------------------------

Job02 Check Remote Door Locks	Labor: \$120.00
-------------------------------	-----------------

Remove door panel and inspected Fault
 Cleaned and check connection, inspected wire harness , and refit, ok at this time

Status: Completed	Job Subtotal: \$120.00
-------------------	------------------------

Job03 Radiator Repairs	Labor: \$280.00
------------------------	-----------------

Remove radiator and send out for repair

Status: Completed	Job Subtotal: \$280.00
-------------------	------------------------

Job04 Hood Stops	Labor: \$0.00
------------------	---------------

391287	BUMP STOP-N	2.0 @	4.90 =\$	9.80	9.80
					Job Subtotal: \$9.80

Status: Completed	Sublet: \$226.00
-------------------	------------------

Job05 Flush/Rod/Seal Radiator	Labor: \$226.00
-------------------------------	-----------------

Flow check
 Clean and rod out, reseal lower seam
 Reseal and re-test for leaks

Job06 (B5) Replc F.Brk Pads (90-)	Labor: \$123.20
-----------------------------------	-----------------

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
160803004

Order Date 08/03/06 11:14 am
Closed 8/19/2006

Payments to British European Motors

Cost Summary

Parts	581.59
Sublet	226.00
Subtotal	1999.59
Tax	45.07
Total	\$2044.66

1 08/17/06 2044.66 On Acct
--A/R Pmt Allocations--
10/30/06 \$2,044.66
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
151207004

Order Date 12/07/05 10:52 am
Closed 1/7/2006

Job10 Seat Repair, Sticking	Labor: \$25.00
-----------------------------	----------------

Drivers seat had to be repaired, stiching was coming apart at the lower seams.

Status: Completed

Job Subtotal: \$25.00

PLEASE UPDATE MILEAGE

We Are Currently Updating Our Databases In Order To Serve You Better. May We Take A Moment And Ask You For A Current E.Mail Address. We Will Only Use This To Inform You Of Any Maintenance Reminders Or Service Bullitens Applicable To Your Vehicle
e.mail : _____

Payments to British European Motors

Cost Summary

Labor	1763.00
Parts	1938.24
Subtotal	3701.24
Tax	150.21
Total	\$3851.45

1 01/06/06 3851.45 On Acct
--A/R Pmt Allocations--
03/13/08 \$2,064.76
01/23/12 \$504.69
03/07/12 \$133.91
11/16/15 \$206.75
01/01/16 \$104.58
02/20/18 \$836.76
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 150516004

Order Date 05/16/05 11:00 am
 Closed 5/21/2005

Silberg, Dr Barry	92 Land Rover RANGE ROVER LS	Quotes
	Mileage in:98591 out:98591 Lic: 3BKH816/CA 8Cyl 4.0	1 05/16/05 11:08am 86.94 Dr in person.
	Vin: SALHV1246NA618427 01/92	2 05/16/05 04:31pm 2109.60 Barry in person.
	Eq: AT AC PS FI 4W	Jobs 2-7
	Last in 11/12/2021	

8887

Job01 (5) Rover Oil, Lube Service Labor: \$18.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL GTX (pnt)-N	13.0 @	1.91 =\$	24.83
ERR3340	OIL FILTER (rov)-N	1.0 @	17.04 =\$	17.04
ZEP003801	PARTS CLEANER-N	1.0 @	10.98 =\$	10.98
ETC7398	OIL DRAIN SEAL (disc/ro)-N	1.0 @	3.46 =\$	3.46
564258	OIL FILLER CAP SEAL(rov)-N	1.0 @	3.03 =\$	3.03
				59.34
				Job Subtotal: \$77.34

Status: Completed

Job02 Check Window Washers Labor: \$0.00

Front windshield washer pump not working, replacement required

Job Subtotal: \$0.00

Status: Completed

Job03 Check Tires Labor: \$0.00

look low all 4

Job Subtotal: \$0.00

Status: Completed

Job04 (I5) Drag Link Tie Rod Ends ALL Labor: \$310.00

Remove drag link and tie rod assembly, loosen and free off adjustment, lubricate
 Install replacement tie rod ends as required.
 Check steering wheel straight adjust as required

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
 150516004

Order Date 05/16/05 11:00 am
 Closed 5/21/2005

Job04 (I5) Drag Link Tie Rod Ends ALL

RTC5869	TIE ROD END(r/h thread-N	3.0 @	57.92 =\$	173.76	
RTC5870	TIE ROD END(l/h)-N	1.0 @	56.68 =\$	56.68	230.44

Status: Completed
 Scheduled for: 05/17/05 08:30 am

Job Subtotal: \$540.44

Job05 Computerized F.Alignment

Sublet: \$103.32

Computerized front alignment

Job06 Replace Washer Pump

Labor: \$50.00

STC1454	W.SHIELD WASH PUMP(rov-N	1.0 @	67.46 =\$	67.46	
AMR3849	HARNESS UPDATE W.PUMP-N	1.0 @	19.60 =\$	19.60	87.06

Status: Completed
 Scheduled for: 05/17/05 11:30 am

Job Subtotal: \$137.06

Job07 (I5) Replace Power Steering Box

Labor: \$560.00

Drain fluid and disconnect arm. Remove hoses and drain.
 Disconnect and remove box. Install replacement assembly and refit other
 components. Add fluid and bleed/flush system.

ATF	TRANS FLUID (pnts)-N	3.0 @	2.89 =\$	8.67	
STC2845/RBLT	STEERING BOX (rov)-R	1.0 @	584.61 =\$	584.61	593.28

Status: Completed
 Scheduled for: 05/17/05 12:30 pm

Job Subtotal: \$1,153.28

Job08 Air Filter

Labor: \$0.00

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
150516004

Order Date 05/16/05 11:00 am
Closed 5/21/2005

Job08 Air Filter

RTC4683	AIR FILTER (rov)-N	1.0 @	16.68 =\$	16.68	16.68
---------	--------------------	-------	-----------	-------	-------

Status: Completed
Scheduled for: 05/17/05 12:00 pm

Job Subtotal: \$16.68

PLEASE UPDATE MILEAGE

We Are Currently Updating Our Databases In Order To Serve You Better. May We Take A Moment And Ask You For A Current E.Mail Address. We Will Only Use This To Inform You Of Any Maintenance Reminders Or Service Bullitens Applicable To Your Vehicle
e.mail : _____

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	938.00
Parts	986.80
Sublet	103.32
Haz Waste	5.00
Subtotal	2033.12
Tax	76.48
Total	\$2109.60

1 05/20/05 2109.60 On Acct
--A/R Pmt Allocations--
05/26/05 \$2,109.60
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 140824002

Order Date 08/24/04 09:40 am
 Closed 8/28/2004

Silber, Dr Barry
 1111 S. ...
 ...
 ...
 ...
 ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:95346 out:95346
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 08/24/04 09:59am 98.00
 Dr in person.

8270

Job01 Brake Check Labor: \$0.00

brakes making noise
 Rear pads and rotors reaching min thickness, replacements recommended

Status: Completed
 Scheduled for: 08/24/04 12:00 pm

Job Subtotal: \$0.00

Job02 Check Engine Labor: \$0.00

Follow up check on Engine install

Status: Completed

Job Subtotal: \$0.00

Job03 (B5) Replc R.Brak Pads/Rotrs(90- Labor: \$247.50

Raise vehicle and remove rear wheels. Remove brake caliper and pads and clean.
 Remove hub and remove brake rotor. Clean and install new rotor and remove bearings
 clean and repack, install new seals refit hub and brake caliper assembly. Install
 new pads and sensor, bleed out fluid/air. Refit road wheels and road test
 complete.

571752	GASKET AXLE FLANGE(rov-N	2.0 @	1.57 =\$	3.14
FTC1381	R.BRAKE ROTOR (rov 90-95-N	2.0 @	98.94 =\$	197.88
FTC4785	HUB SEAL ALL (rov)-N	2.0 @	9.48 =\$	18.96
STC9189	R.BRAKE PAD (rov all)-N	1.0 @	125.27 =\$	125.27
ZEP003801	PARTS CLEANER-N	1.0 @	10.32 =\$	10.32
217353	LOCK TAB AXLE BRG (rov-N	2.0 @	3.08 =\$	6.16 361.73

Job Subtotal: \$609.23

Status: Completed

Job04 (5) Rover Oil, Lube Service Labor: \$18.00

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
 140824002

Order Date 08/24/04 09:40 am
 Closed 8/28/2004

Job04 (5) Rover Oil, Lube Service

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL GTX (pnt)-N	13.0 @	1.61 =\$	20.93	
ERR3340	OIL FILTER (rov)-N	1.0 @	16.26 =\$	16.26	
ZEP003801	PARTS CLEANER-N	1.0 @	10.32 =\$	10.32	
ETC7398	OIL DRAIN SEAL (disc/ro)-N	1.0 @	3.46 =\$	3.46	
564258	OIL FILLER CAP SEAL(rov)-N	1.0 @	2.78 =\$	2.78	53.75

Job Subtotal: \$71.75

Status: Completed

Recommendations: RETURN EVERY 3000/3MONTHS FOR OIL SERVICE

PLEASE UPDATE MILEAGE

THANK YOU

If you have any questions - Please call 707-792-2737
 Complete satisfaction is our goal. We will be calling
 you in the next few days to follow up on this repair
 visit. WHAT WOULD BE THE BEST TIME TO REACH YOU?

AM PM HOME# WORK#

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	265.50
Parts	415.48
Haz Waste	5.00
Subtotal	685.98
Tax	31.16

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
140824002

Order Date 08/24/04 09:40 am
Closed 8/28/2004

Payments to British European Motors

Cost Summary

Total \$717.14

1 08/26/04 717.14 On Acct
--A/R Pmt Allocations--
03/16/07 \$630.06
03/13/08 \$87.08
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 140422005

Order Date 04/22/04 05:03 pm
 Closed/Paid: 04/22/04 05:03 pm

Silber, Dr Barry 1111 Grand Ave Suite 100 Cotati, CA 94931 Phone: 707 792-2737	92 Land Rover RANGE ROVER LS Mileage in:94060 out: Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021
--	---

USED ENGINE 'DISCOUNT' -\$750
 LABOR HOURS ON ENGINE EXCEEDED ORIGINAL ESTIMATE, KEPT AT ORIGINAL QUOTED
 PRICE, 'ADDITIONAL PARTS' LISTED REQUIRED/RECOMMENDED WHEN REPLACEMENT
 ENGINE INSTALLED

Job01 Engine Repairs	Labor: N/C
----------------------	------------

Remove engine and install replacement

76960	LONG BLOCK-cust sply-S	1.0 @	0.00 =\$	N/C
20/50	ENGINE OIL GTX (pnt)-N	14.0 @	0.00 =\$	N/C
ERR3340	OIL FILTER (rov)-N	1.0 @	0.00 =\$	N/C

Job02 Additional Parts	Labor: N/C
------------------------	------------

FN108041L	EX MANIFOLD NUT(rov)-N	6.0 @	2.39 =\$	N/C
564258	OIL FILLER CAP SEAL(ro-N	1.0 @	2.58 =\$	N/C
7041039	DRAIN PLUG-S	4.0 @	5.22 =\$	N/C
ERR4077	WATER PUMP GASKET (dis-N	1.0 @	11.22 =\$	N/C
STC483	WATER PUMP (rov)-N	1.0 @	227.45 =\$	N/C
RN14YC/405	SPARK PLUG-N	8.0 @	4.49 =\$	N/C
ERR6733	EX MAN GASKET(disc/rov-N	4.0 @	18.46 =\$	N/C
ETC4524	EXHAUST FLANGE GASKET-N	2.0 @	13.96 =\$	N/C
ERR2846	CRANK KEYWAY-S	1.0 @	18.84 =\$	N/C
ESR3297	TOP RAD HOSE(rov-95/DI-N	1.0 @	31.27 =\$	N/C
LYG101440	BOLT MANIFOLD (rov)-N	10.0 @	4.35 =\$	N/C
LYG101450	BOLT MANIFOLD (rov)-N	2.0 @	5.98 =\$	N/C
610289	CAM GEAR-S	1.0 @	45.30 =\$	N/C
ESR356	OIL COOLER HOSE-S	1.0 @	130.33 =\$	N/C
ESR355	OIL COOLER HOSE(rov)*-N	1.0 @	132.04 =\$	N/C
572312	RAD MOUNT BUSHING-S	1.0 @	3.80 =\$	N/C
ETC4276	OIL PUMP HOUSING-S	1.0 @	397.98 =\$	N/C

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
140422005

Order Date 04/22/04 05:03 pm
Closed/Paid: 04/22/04 05:03 pm

Recommendations

LEVELS

SHOULD RETURN EVERY 3000/3MONTHS FOR OIL SERVICE

PLEASE UPDATE MILEAGE

THANK YOU

If you have any questions - Please call 707-792-2737
Complete satisfaction is our goal. We will be calling
you in the next few days to follow up on this repair
visit. WHAT WOULD BE THE BEST TIME TO REACH YOU?

AM PM HOME# WORK#

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Status: Closed Work Order	Labor	0.00
	Parts	0.00
Payments:	Subtotal	0.00
	Total	\$0.00
	Payments	0.00
	Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 140121003

Order Date 01/21/04 09:15 am
 Closed 1/25/2004

Silberg, Dr Barry
 2111 Crown Ln
 Cotati, CA 94931
 Phone: 707 792-2737
 Fax: 707 792-4454

92 Land Rover RANGE ROVER LS
 Mileage in: 92980 out:
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 01/22/04 12:28pm 728.35
 Dr. Silberg in person.

819

Job01 (5) Rover Oil, Lube Service Labor: \$18.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL GTX (pnt)-N	13.0 @	1.51 =\$	19.63	
ERR3340	OIL FILTER (rov)-N	1.0 @	15.78 =\$	15.78	
ZEP003801	PARTS CLEANER-N	1.0 @	10.32 =\$	10.32	
ETC7398	OIL DRAIN SEAL (disc/ro)-N	1.0 @	3.46 =\$	3.46	49.19

Status: Completed
 Scheduled for: 01/22/04 08:30 am

Job Subtotal: \$67.19

Job02 Left Front Door Pocket Labor: \$96.00

Remove door panel and remove broken faseners and install replac

MXC1324SUA	DOOR POCKET-S	1.0 @	70.56 =\$	70.56	70.56
------------	---------------	-------	-----------	-------	-------

Status: Completed

Job Subtotal: \$166.56

Job03 (c5)R&r Update Vlve Covr Gskts Labor: \$336.00

Remove plenum chamber//remove valve cover gaskets// Install new
 gaskets//Refit/seal plenum chamber//Run Test leaks

25223	GSKT SEALER(rightstuff)-N	0.5 @	25.79 =\$	12.90	
LVC100260	VALVE COVER GSKT(rov)-N	2.0 @	13.84 =\$	27.68	40.58

Status: Completed
 Scheduled for: 01/22/04 05:00 pm

Job Subtotal: \$376.58

----->----->----->-----Continued on the next page----->----->----->----->

Invoice No.
 140121003

Order Date 01/21/04 09:15 am
 Closed 1/25/2004

Job04 Driving Lights	Labor: \$57.60
----------------------	----------------

Check relay, correct wiring, trace fault to bulbs, remove lenses and install replacement bulbs

H3/100W	FOG LAMP BULB(helogen)-N	2.0 @	14.32 =\$	28.64	28.64
---------	--------------------------	-------	-----------	-------	-------

Status: Completed Tech: Dr.

Job Subtotal: \$86.24

Job05 Radiator Bleed Hose	Labor: \$28.80
---------------------------	----------------

F5/16	5/16 HOSE/FOOT-N	8.0 @	2.98 =\$	23.84	
H/C	HOSE CLAMP-N	4.0 @	2.21 =\$	8.84	32.68

Status: Completed

Job Subtotal: \$61.48

PLEASE UPDATE MILEAGE

THANK YOU
 If you have any questions - Please call 707-792-2737
 Complete satisfaction is our goal. We will be calling
 you in the next few days to follow up on this repair
 visit. WHAT WOULD BE THE BEST TIME TO REACH YOU?

AM PM HOME# WORK#

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	536.40
Parts	221.65
Haz Waste	5.00
Shipping	5.00
Subtotal	768.05
Tax	16.62
Total	\$784.67

1 01/23/04 784.67 On Acct
 --A/R Pmt Allocations--
 02/11/04 \$784.67
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

British European Motors
 606 Portal Street
 Cotati, CA 94931
 Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
 130904006

Order Date 09/04/03 04:16 pm
 Closed 9/8/2003

Silberg, Dr Barry 1111 3rd St Cotati, CA 94931 Phone: 707-792-2737	92 Land Rover RANGE ROVER LS Mileage in:91004 out:91004 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	Quotes 1 09/04/03 04:20pm 172.80 Dr in person.
---	--	--

managed to have supplier of lock warranty part even though outside of 12 months since installed

Job01 (E5) Replace Ignition Sw (int)	Labor: \$172.80
--------------------------------------	-----------------

Remove steering turn/wiper covers.
 Remove ignition switch and install replacement.
 Actuate switch and check correct operation
 Refit panels and recheck

NTC9440	STEER LOCK (int.lock)-N	1.0 @	0.00 =\$	0.00	0.00
					Job Subtotal: \$172.80

Status: Completed

PLEASE UPDATE MILEAGE

THANK YOU
 If you have any questions - Please call 707-792-2737
 Complete satisfaction is our goal. We will be calling
 you in the next few days to follow up on this repair
 visit. WHAT WOULD BE THE BEST TIME TO REACH YOU?

AM PM HOME# WORK#

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	172.80
Parts	0.00
Subtotal	172.80
Total	\$172.80

1 09/05/03 172.80 On Acct
 --A/R Pmt Allocations--
 10/14/03 \$172.80
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 130610001

Order Date 06/10/03 09:54 am
 Closed/Paid: 06/16/03 04:45 pm

code 15665 Santa Rosa Ca 95405 Work Phone: Cell Phone:	92 Land Rover RANGE ROVER LS	Quotes
	Mileage in:88995 out:88995 Lic: 3BKH816/CA 8Cyl 4.0	1 06/10/03 09:54am 550.43
	Vin: SALHV1246NA618427 01/92	Dr in person.
	Eq: AT AC PS FI 4W	2 06/10/03 02:19pm 2000.02
	Last in 11/12/2021	Dr. Barry in person.
		Adding brakes and 90k service
		3 06/11/03 01:56pm 2298.97
		Dr. Barry by phone 528-0911
		adding job 08
		4 06/12/03 01:30pm 3087.55
		Dr. Barry by phone call-in
		add new rad job #8

Job01 (5) Rover 90-92 Major Srvce 90K Labor: \$592.00

Service list as recommended by Range Rover plus additional addatives highly recommended for longer life and durability

BG203	FUEL ADD DEPOSIT CONTROL-N	1.0 @	13.00 =\$	13.00
ETC4524	EXHAUST FLANGE GASKET-N	2.0 @	13.56 =\$	27.12
BG110	ENGINE OIL ADDATIVE-N	1.0 @	9.90 =\$	9.90
WURTH	W/SHIELD WASHER FLUID-N	1.0 @	3.91 =\$	3.91
NMD6091AB	FUEL FILTER (rov/jag)-N	1.0 @	25.19 =\$	25.19
LMA	BRAKE FLUID BY THE Oz-N	32.0 @	0.50 =\$	16.00
GR1	GREASE/LUBE-N	1.0 @	5.33 =\$	5.33
FK82716	TRANS SERVICE KIT(rov)-N	1.0 @	41.64 =\$	41.64
ERR3340	OIL FILTER (rov)-N	1.0 @	14.88 =\$	14.88
EBC9044	OIL DRAIN SEAL-N	1.0 @	3.80 =\$	3.80
DIFF-OIL	1/2 pint DIFF-OIL-N	26.0 @	2.04 =\$	53.04
ATF	TRANS FLUID (pnts)-N	9.0 @	2.39 =\$	21.51
A/F	ANTIFREEZE/COOLANT(pnts)-R	12.0 @	1.87 =\$	22.44
20/50	ENGINE OIL GTX (pnt)-N	14.0 @	1.40 =\$	19.60
FN108041L	EX MANIFOLD NUT(rov)-N	6.0 @	2.39 =\$	14.34
RTC4683	AIR FILTER (rov)-N	1.0 @	14.23 =\$	14.23
ZEP003801	PARTS CLEANER-N	1.0 @	7.80 =\$	7.80
				313.73

Job Subtotal: \$905.73

Status: Completed

Job02 Side mirror operation Labor: \$96.00

----->----->----->-----Continued on the next page----->----->----->----->

Invoice No.
130610001

Order Date 06/10/03 09:54 am
Closed/Paid: 06/16/03 04:45 pm

Job02 Side mirror operation

passanger side only has up and down movement and driver side works intermittenly
Remove control switch and transfer switch
Clean contact and recheck operation
Refit and check both side work fine

Status: Completed

Job Subtotal: \$96.00

Job03 Shaking when braking

Labor: \$0.00

Front brake rotors required

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Job04 Install handle inserts

Labor: \$0.00

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Job05 Dash Lights

Labor: \$96.00

Correct fault for heater control illumination

Status: Completed

Job Subtotal: \$96.00

Job06 Front parking light

Labor: \$96.00

Status: Completed Tech: Dr.

Job Subtotal: \$96.00

Job07 (B5) Replc F.Brk Pads/Rotrs(90-

Labor: \$374.40

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
 130610001

Order Date 06/10/03 09:54 am
 Closed/Paid: 06/16/03 04:45 pm

Job07 (B5) Replc F.Brk Pads/Rotrs(90-

Raise vehicle and remove front wheels. Remove front axles and remove hub, rotor and brake caliper assembly. Check and clean all area, clean and inspect/replace hub bearings and repack Refit hub and rotor. Refit brake caliper and install new pads. Refit road wheels and road test complete.+

FTC3179	LOCK TAB AXLE BRG (Lrov)-N	2.0 @	3.38 =\$	6.76	
FTC4785	HUB SEAL ALL (rov)-N	2.0 @	11.97 =\$	23.94	
FTC902	F.BRAKE ROTOR (rov 90--N	2.0 @	102.39 =\$	204.78	
571752	GASKET AXLE FLANGE(rov-N	2.0 @	1.43 =\$	2.86	
STC9190	F.BRAKE PAD (rov 90-94)-N	1.0 @	124.43 =\$	124.43	
ZEP003801	PARTS CLEANER-N	1.0 @	7.80 =\$	7.80	370.57

Job Subtotal: \$744.97

Status: Completed

Job08 (H5) Radiator Repairs (new)	Labor: \$105.60
-----------------------------------	-----------------

Drain and remove radiator.
 Send out for recore.
 Install replacement and add coolant as required.

H/C	HOSE CLAMP-N	2.0 @	2.21 =\$	4.42	
ERR4686	RADIATOR PLUG (lr)-N	1.0 @	4.13 =\$	4.13	
ERR4685	PLUG SEAL (rover)-N	1.0 @	1.89 =\$	1.89	
ESR74	RADIATOR (rov-93)-N	1.0 @	902.98 =\$	902.98	913.42

Job Subtotal: \$1,019.02

Status: Completed Tech: Dr.

PLEASE UPDATE MILEAGE

THANK YOU
 If you have any questions - Please call 707-792-2737
 Complete satisfaction is our goal. We will be calling
 you in the next few days to follow up on this repair
 visit. WHAT WOULD BE THE BEST TIME TO REACH YOU?

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
130610001

Order Date 06/10/03 09:54 am
Closed/Paid: 06/16/03 04:45 pm

AM PM HOME# WORK#

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Status: Closed Work Order
Payments: \$3,087.55
1 06/16/03 3087.55 Check

Labor	1360.00
Parts	1597.72
Haz Waste	10.00
Subtotal	2967.72
Tax	119.83
Total	\$3087.55
Payments	3087.55
Bal Due	0.00

Thank you for choosing British European Motors

British European Motors
 606 Portal Street
 Cotati, CA 94931
 Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
 130604003

Order Date 06/04/03 11:51 am
 Closed 6/9/2003

Silberg, Dr Harry
 1111 S. ...
 ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:86254 out:86254
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 06/04/03 11:53am 87.38
 Dr in person.

Job01 Supply/Install Door Pulls Labor: \$0.00

Supply/Install Door Pulls

MXC1306SUA	DOOR PULL-S	4.0 @	18.46 =\$	73.84	73.84
------------	-------------	-------	-----------	-------	-------

Status: Completed Tech: Dr.

Job Subtotal: \$73.84

Recommendations: *30K INTERVAL (major) SERVICE* *Lube, Oil and Filter*

PLEASE UPDATE MILEAGE

THANK YOU
 If you have any questions - Please call 707-792-2737
 Complete satisfaction is our goal. We will be calling
 you in the next few days to follow up on this repair
 visit. WHAT WOULD BE THE BEST TIME TO REACH YOU?

AM PM HOME# WORK#

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	0.00
Parts	73.84
FREIGHT	8.00
Subtotal	81.84
Tax	5.54
Total	\$87.38

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
130604003

Order Date 06/04/03 11:51 am
Closed 6/9/2003

Payments to British European Motors

Cost Summary

1 06/04/03 87.38 On Acct
--A/R Pmt Allocations--
06/16/03 \$87.38
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 121105003

Order Date 11/05/02 11:06 am
 Closed 11/7/2002

Silberg, Dr Harry 1111 Serrano Ave Cotati, CA 94931 Phone: 707-792-2737 Fax: 707-792-4454	? Land Rover RANGE ROVER LS Mileage in:86254 out:86254 C: 3BKH816/CA 8Cyl 4.0 VIN: SALHV1246NA618427 01/92 Dr: AT AC PS FI 4W Last in 11/12/2021
---	---

Job01 (5) Rover Oil, Lube Service	Labor: \$15.00
-----------------------------------	----------------

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL GTX (pnt)-N	13.0 @	1.39 =\$	18.07	
ERR3340	OIL FILTER (rov)-N	1.0 @	14.92 =\$	14.92	
UAM2857L	OIL DRAIN SEAL (rov4.0-)-N	1.0 @	2.81 =\$	2.81	
ZEP003801	PARTS CLEANER-N	1.0 @	10.61 =\$	10.61	
40718a	WIPER BLADE 18"-N	3.0 @	14.32 =\$	42.96	89.37

Status: Completed Job Subtotal: \$104.37

PLEASE UPDATE MILEAGE

THANK YOU
 If you have any questions - Please call 707-792-2737
 Complete satisfaction is our goal. We will be calling
 you in the next few days to follow up on this repair
 visit. WHAT WOULD BE THE BEST TIME TO REACH YOU?

AM PM HOME# WORK#

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	15.00
Parts	89.37
Haz Waste	5.00

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
121105003

Order Date 11/05/02 11:06 am
Closed 11/7/2002

Payments to British European Motors

Cost Summary

Subtotal	109.37
Tax	6.70
Total	\$116.07

1 11/05/02 116.07 On Acct
--A/R Pmt Allocations--
11/19/02 \$116.07
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 120605004

Order Date 06/05/02 02:42 pm
 Closed 6/23/2002

Silberg, Dr Barry
 1111 Sonoma Ave
 Cotati, CA 94931
 Phone: 707 792-2737

92 Land Rover RANGE ROVER LS
 Mileage in:84756 out:84756
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 06/17/02 11:16am 1313.70
 Dr in person.

had to re-glue steering shroud, some pices broken, ok now

Job01 (E5) Replace Ignition Sw (int) Labor: \$140.63

Remove steering turn/wiper covers.
 Remove electrical portion of switch and install replacement.
 Actuate switch and check correct operation
 Refit panels and recheck

STC932	IGN SWITCH(int/rov)-N	1.0 @	45.79 =\$	45.79	
NTC9440	STEER LOCK (int.lock)-N	1.0 @	341.24 =\$	341.24	387.03

Status: Completed Job Subtotal: \$527.66

Job02 Brake Warning Lamp On Labor: \$0.00

Status: Completed Tech: Dr. Job Subtotal: \$0.00

Job03 (B5) Replc R.Brk Pads/Rotrs(90- Labor: \$210.00

Raise vehicle and remove rear wheels. Remove brake caliper and pads and clean.
 Remove hub and remove brake rotor.Clean and install new rotor and remove bearings
 clean and repack,install new seals refit hub and brake caliper assembly. Install
 new pads and sensor, bleed out fluid/air. Refit road wheels and road test
 complete.

571752	GASKET AXLE FLANGE(rov-N	2.0 @	1.43 =\$	2.86	
FTC1381	R.BRAKE ROTOR (rov 90-95-N	2.0 @	98.94 =\$	197.88	
FTC4785	HUB SEAL ALL (rov)-N	2.0 @	11.97 =\$	23.94	
ZEP009601	PARTS CLEANER-N	1.0 @	10.61 =\$	10.61	
FTC3179	LOCK TAB AXLE BRG (Lrov)-N	2.0 @	3.38 =\$	6.76	
STC9189	R.BRAKE PAD (rov all)-N	1.0 @	119.64 =\$	119.64	361.69

Status: Completed Job Subtotal: \$571.69

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
120605004

Order Date 06/05/02 02:42 pm
Closed 6/23/2002

PLEASE UPDATE MILEAGE

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	350.63
Parts	748.72
Subtotal	1099.35
Tax	56.15
Total	\$1155.50

1 06/18/02 1155.50 On Acct
--A/R Pmt Allocations--
01/07/02 \$1,109.58
01/07/02 (\$1,277.79)
04/29/02 \$168.21
07/17/02 \$1,155.50
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 120404002

Order Date 04/04/02 09:36 am
 Closed 4/7/2002

Silberg, Dr Barry
 1000 ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:83668 out:83668
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 04/04/02 12:42pm 163.21
 Dr in person.

Job01 (5) Rover Oil, Lube Service Labor: \$15.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL GTX (pnt)-N	15.0 @	1.36 =\$	20.40	
EBC9044	OIL DRAIN SEAL-N	1.0 @	4.50 =\$	4.50	
ERR3340	OIL FILTER (rov)-N	1.0 @	14.92 =\$	14.92	
ZEP009601	PARTS CLEANER-N	1.0 @	10.61 =\$	10.61	50.43

Status: Completed Job Subtotal: \$65.43

Job02 Check Oil Leak Labor: \$89.00

Found Slight seapeage from valve cover gaskets very minor
 Want to do oil consumption test. DRIVE FOR 1000 MILES DO NOT ADD OIL UNLESS OIL
 LEAVES DIP STICK.

Status: Completed Job Subtotal: \$89.00

PLEASE UPDATE MILEAGE

Payments to British European Motors Cost Summary

Labor	104.00
Parts	50.43
Haz Waste	5.00
Fuel	5.00
Subtotal	164.43

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
120404002

Order Date 04/04/02 09:36 am
Closed 4/7/2002

Payments to British European Motors

Cost Summary

Tax	3.78
Total	\$168.21

1 04/05/02 168.21 On Acct
--A/R Pmt Allocations--
01/07/02 \$168.21
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 111204007

Order Date 12/04/01 11:37 am
 Closed 12/13/2001

Silberg, Dr Barry	92 Land Rover RANGE ROVER LS	Quotes
	Mileage in:81867 out:81867 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	1 12/04/01 11:38am 110.00 Dr in person.
		2 12/04/01 12:41pm 742.19 Dr Barry by phone call-in job 1-2

Job01 (*K4)Test Book `check engine` Labor: \$75.00

Hook up test book run procedure for 'check engine' diagnosis
 Remove code, stepper motor, cleaned and refit-recheck operation no code set

Status: Completed

Job Subtotal: \$75.00

Job02 check coolant level Labor: \$0.00

Intake manifold seepage

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Job03 (C5) Intake Manifold Gasket Labor: \$453.90

Drain coolant and disconnect electrical and coolant connections.
 Remove intake manifold and clean off area.
 Install replacement gasket and refit manifold.
 Torque and secure.
 Refit all aux equipment and add coolant.
 Run and check for no leaks.
 Top off coolant as required.

A/F	ANTIFREEZE/COOLANT (pnts) -R	10.0 @	1.87 =\$	18.70	
ERR7283	INTAKE MAN SEAL (rov) -N	2.0 @	13.92 =\$	27.84	
ERR7306	INTAKE MANIFOLD GASKET -N	1.0 @	41.98 =\$	41.98	
ZEP009601	PARTS CLEANER -N	1.0 @	10.61 =\$	10.61	
ERR7282	VALLEY END BRACKET (rov) -N	2.0 @	16.36 =\$	32.72	
LYG101440	BOLT MANIFOLD (rov) -N	10.0 @	4.99 =\$	49.90	
LYG101450	BOLT MANIFOLD (rov) -N	2.0 @	6.23 =\$	12.46	194.21

Status: Completed

Job Subtotal: \$648.11

Job04 Adjust D.Door Handle Labor: \$44.50

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
111204007

Order Date 12/04/01 11:37 am
Closed 12/13/2001

Job04 Adjust D.Door Handle

Adjust outer door handle to open easier

Status: Completed

Job Subtotal: \$44.50

HAPPY HOLIDAYS FROM EVERYBODY HERE AT BRITISH EUROPEAN

Payments to British European Motors

Cost Summary

Labor	573.40
Parts	194.21
Haz Waste	5.00
Subtotal	772.61
Tax	14.08
Total	\$786.69

1 12/05/01 786.69 On Acct
--A/R Pmt Allocations--
12/19/01 \$786.69
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 111127002

Order Date 11/27/01 10:23 am
 Closed 12/3/2001

Silberg, Dr Barry 111 Portal Street Cotati, CA 94931 Phone: 707 792-2737 Fax: 707 792-4454	92 Land Rover RANGE ROVER LS Mileage in:81743 out:81743 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	<p style="text-align: center;">Quotes</p> <hr/> 1 11/27/01 10:26am 491.10 Dr.Silberg in person.
--	--	--

Job01 Redefroster not working	Labor: \$89.00
-------------------------------	----------------

Wire off on rear tail gate, comes off when lifting, refit and secure slide harnes to ensure no movement of wires when opening tail gate

Status: Completed	Job Subtotal: \$89.00
-------------------	-----------------------

Job02 Driverside seat heater not work	Labor: \$300.00
---------------------------------------	-----------------

Remove seat pads, install replacement elliments as required
 Refit seat and secure, recheck operation

MXC5228	SEAT ELLIMENT-S	1.0 @	75.98 =\$	75.98	
BTR1216	BACK SEAT ELL-S	1.0 @	102.20 =\$	102.20	178.18

Status: Completed	Job Subtotal: \$478.18
-------------------	------------------------

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	389.00
Parts	178.18
Discount	89.00
Subtotal	478.18
Tax	12.92
Total	\$491.10

1 11/29/01 491.10 On Acct
 --A/R Pmt Allocations--
 12/19/01 \$491.10
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 111113002

Order Date 11/13/01 09:42 am
 Closed 11/25/2001

Silberg, Dr Barry
 111113002
 11/13/01

92 Land Rover RANGE ROVER LS
 Mileage in:81217 out:81217
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 11/13/01 10:49am 780.49
 Dr Barry in person.

Job01 (H5) Replace Thermostat/Gasket Labor: \$111.25

Drain coolant // Remove thermostat chk and Fit new
 Refit housing and new gasket // Add coolant run bleed test opening temp

ETC4765	THERMOSTAT (rov)-N	1.0 @	18.36 =\$	18.36	
ERR2429	THERMOSTAT GASKET(rov)-N	1.0 @	6.84 =\$	6.84	
A/F	ANTIFREEZE/COOLANT(pnts)-R	16.0 @	1.87 =\$	29.92	
ZEP009601	PARTS CLEANER-N	1.0 @	10.61 =\$	10.61	65.73

Status: Completed Job Subtotal: \$176.98

Job02 Driver Seat Heater Elliment? Labor: \$320.00

Was replaced, has stopped working
 Tracing fault to both front seat heaters and rear window defrost elliment, all three have power delivery through switches, however relays for each individual item to not trigger when activated
 When ground signal is applied to all three at the grounding relay all three individual relays then activate.
 Trace wiring circuit to power distribution at on all vehicles excluding the 92 goes to MFU control unit, on the 92 these are triggered by a voltage sensitive relay
 Traced and found mounted behind steering column
 Remove and tested, replacement required
 Refit access panels except under steering column and await arrival of voltage relay

Status: Completed Job Subtotal: \$320.00

Job03 Lock On Latch Lock Not Unlock Labor: \$53.40

Rear latch will lock with key from drivers door but will not unlock
 Adjust actuator, if fails again will require replacement

Status: Completed Job Subtotal: \$53.40

----->----->----->---Continued on the next page--->----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
111113002

Order Date 11/13/01 09:42 am
Closed 11/25/2001

Job04 Install Voltage Control Relay	Labor: \$22.25
-------------------------------------	----------------

Install voltage relay and refit steering panel
Test circuits by shting off engine and watching voltage drop
Start engine and wait for relays to activate, all operational

PRC4427	RELAY VOLTAGE-N	1.0 @	184.70 =\$	184.70	184.70
---------	-----------------	-------	------------	--------	--------

Status: Completed

Job Subtotal: \$206.95

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	506.90
Parts	250.43
Haz Waste	5.00
Subtotal	762.33
Tax	18.16
Total	\$780.49

1 11/20/01 780.49 On Acct
--A/R Pmt Allocations--
12/05/01 \$780.49
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 110820004

Order Date 08/20/01 10:23 am
 Closed 8/26/2001

Silberg, Dr Barry
 1111...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:80236 out:80236
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1	08/20/01 10:24am	84.00
Dr in person.		
2	08/21/01 08:39am	1067.12
Dr. Silberg by phone call in		
Additional work Jobs03,04		
3	08/21/01 12:32pm	1088.47
mark in person.		
remote repair		

Job01 Tail gate latch not working Labor: \$243.60

not locking, trace fault to lock actuator wiring fault and actuator arm linkage.
 Repair wiring and secure.
 Repair actuator linkage

Status: Completed Job Subtotal: \$243.60

Job02 smog Labor: \$0.00

Status: Completed Tech: Dr. Job Subtotal: \$0.00

Job03 (5) Rover Oil, Lube Service Labor: \$15.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL GTX (pnt)-N	15.0 @	1.36 =\$	20.40
EBC9044	OIL DRAIN SEAL-N	1.0 @	4.50 =\$	4.50
ERR3340	OIL FILTER (rov)-N	1.0 @	14.92 =\$	14.92
ZEP009601	PARTS CLEANER-N	1.0 @	10.61 =\$	10.61
				50.43

Status: Completed Job Subtotal: \$65.43

Job04 (B5) Replc F.Brk Pads/Rotrs(90- Labor: \$304.20

Raise vehicle and remove front wheels. Remove front axles and remove hub, rotor
 and brake caliper assembly. Check and clean all area, clean and inspect/replace

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
 110820004

Order Date 08/20/01 10:23 am
 Closed 8/26/2001

Job04 (B5) Replc F.Brk Pads/Rotrs(90-

area, clean and inspect/replace hub bearings and repack Refit hub and rotor. Refit brake caliper and install new pads. Refit road

FTC4785	HUB SEAL ALL (rov)-N	2.0 @	11.97 =\$	23.94	
FTC902	F.BRAKE ROTOR (rov 90--N	2.0 @	123.31 =\$	246.62	
ZEP009601	PARTS CLEANER-N	1.0 @	10.61 =\$	10.61	
571752	GASKET AXLE FLANGE(rov-N	2.0 @	1.39 =\$	2.78	
STC9190	F.BRAKE PAD (rov 90-94)-N	1.0 @	124.43 =\$	124.43	
217353	LOCK TAB AXLE BRG (rov-N	2.0 @	3.54 =\$	7.08	415.46

Job Subtotal: \$719.66

Status: Completed

Job05 Remote Reapir/test Battery	Labor: \$21.00
----------------------------------	----------------

Open remote and refit, clean contact on printed board, secure program chip (was loose)
 Test battery voltage good
 Refit and tested great

Status: Completed Tech: Dr.

Job Subtotal: \$21.00

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	583.80
Parts	465.89
Haz Waste	5.00
Subtotal	1054.69
Tax	33.78
Total	\$1088.47

1 08/21/01 1088.47 On Acct
 --A/R Pmt Allocations--
 08/27/01 \$1,088.47
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 110410005

Order Date 04/10/01 02:57 pm
 Closed 4/22/2001

Silberg, Dr Barry
 1111 Serrano Ave
 Santa Rosa, CA 95405
 Home Phone: 707-541-3700
 Cell Phone: 307-210-1290

92 Land Rover RANGE ROVER LS
 Mileage in:78346 out:78346
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 04/11/01 08:33am 635.92
 Dr in person.

brakes front pads 7mm (min 3mm) rotors 23
 rear brakes pads 5mm (min3mm) rotors 11mm,bellow man recommended)

Job01 (5) Rover Oil, Lube and Filter Labor: \$15.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL GTX (pnt)-N	15.0 @	1.31 =\$	19.65	
EBC9044	OIL DRAIN SEAL-N	1.0 @	4.50 =\$	4.50	
ERR3340	OIL FILTER (rov)-N	1.0 @	14.92 =\$	14.92	
ZEP009601	PARTS CLEANER-N	1.0 @	10.61 =\$	10.61	49.68

Status: Completed

Job Subtotal: \$64.68

Job02 L.F. seat not heating Labor: \$0.00

Will require complete seat strip and replacement elliment installed

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Job03 Rear latch to working Labor: \$92.40

Clean out and adjust mechanism
 Lubricate latch mechanism and pivots

Status: Completed

Job Subtotal: \$92.40

Job04 Bezel around handle missing Labor: \$0.00

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
110410005

Order Date 04/10/01 02:57 pm
Closed 4/22/2001

Job04 Bezel around handle missing

Install replacement part

MWC2480	HANDLE FINISHER (rov)-N	1.0 @	7.36 =\$	7.36	7.36
---------	-------------------------	-------	----------	------	------

Status: Completed Tech: Dr.

Job Subtotal: \$7.36

Job05 Dent on L.R Panel Labor: \$85.00

Have Dent Dynamics remove

Could not remove the dent frome L. R. Panel but were able to remove some others

Status: Completed Tech: Dr.

Job Subtotal: \$85.00

Job06 Air Conditioning Service Labor: \$42.00

Hook up A/C rec machine // Drain/evacuate//hold test//recharge test leaks ok
pressure readings
low side 15
high side 195

RF12	FREON rf-12-N	30.0 @	2.67 =\$	80.10	
59346	SCHRADDER VALVE-N	2.0 @	3.39 =\$	6.78	86.88

Status: Completed

Job Subtotal: \$128.88

Job07 Check Engine Light Labor: \$126.00

Check engine code "48"
Retreive and clear code, adjust base idle setting and clean throttle plate

Status: Completed

Job Subtotal: \$126.00

Job08 Washer Fluid Labor: \$0.00

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
110410005

Order Date 04/10/01 02:57 pm
Closed 4/22/2001

Job08 Washer Fluid

After servicing the vehicle the washer jets plugged again, so drained and refin completely the reservoir

WURTH	W/SHIELD WASHER FLUID-N	2.0 @	3.91 =\$	7.82	7.82
-------	-------------------------	-------	----------	------	------

Status: Completed Tech: Dr.

Job Subtotal: \$7.82

Recommendations: Some 'pulsing' from brake pedal, allow pads to wear to minimum and then replacemnt pads and rotors

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	360.40
Parts	151.74
Haz Waste	5.00
Subtotal	517.14
Tax	11.00
Total	\$528.14

1 04/19/01 528.14 On Acct
--A/R Pmt Allocations--
04/27/01 \$528.14
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 101115005

Order Date 11/15/00 05:04 pm
 Closed 11/25/2000

[Faded text, likely a signature or stamp]

92 Land Rover RANGE ROVER LS
 Mileage in:75979 out:75979
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 11/16/00 11:28am 2042.27
 Dr in person.

Job01 (5) Rover 90-94 Major Servce 60K Labor: \$480.00

OIL CHANGE DONE ON SEPERATE INVOICE LAST WEEK
 Service list as recommended by Range Rover plus additional addtatives highly
 recommended for longer life and durability

A/F	ANTIFREEZE/COOLANT (pnts)-R	12.0 @	1.87 =\$	22.44	
ATF	TRANS FLUID (pnts)-N	9.0 @	2.39 =\$	21.51	
BG110	ENGINE OIL ADDATIVE-N	1.0 @	12.98 =\$	12.98	
BG203	FUEL ADD DEPOSIT CONTROL-N	1.0 @	12.98 =\$	12.98	
ETC4524	EXHAUST FLANGE GASKET-N	2.0 @	14.31 =\$	28.62	
FK82716	TRANS SERVICE KIT(rov)-N	1.0 @	57.21 =\$	57.21	
FN108041L	EX MANIFOLD NUT(rov)-N	6.0 @	2.32 =\$	13.92	
GFE1104	AIR FILTER (rov)-N	1.0 @	14.51 =\$	14.51	
GRI	GREASE/LUBE-N	1.0 @	5.71 =\$	5.71	
LMA	BRAKE FLUID BY THE Oz-N	32.0 @	0.77 =\$	24.64	
NMD6091AB	FUEL FILTER (rov/jag)-N	1.0 @	25.19 =\$	25.19	
RN14YC	SPARK PLUG-N	8.0 @	4.97 =\$	39.76	
WURTH	W/SHIELD WASHER FLUID-N	1.0 @	3.91 =\$	3.91	283.38

Status: Completed Job Subtotal: \$763.38

Job02 (I5) Replace Power Steering Box Labor: \$459.20

Drain fluid and disconect arm. Remove hoses and drain.
 Disconect and remove box. Install relpacement assembly and refit other
 components. Add fluid and bleed/flush system.

ATF	TRANS FLUID (pnts)-N	3.0 @	2.39 =\$	7.17	
STC2845/RBLT	STEERING BOX (rov)-N	1.0 @	490.20 =\$	490.20	497.37

Status: Completed Job Subtotal: \$956.57

Job03 (G5) Rear Exhaust Muffler Labor: \$75.00

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
101115005

Order Date 11/15/00 05:04 pm
Closed 11/25/2000

Job03 (G5) Rear Exhaust Muffler

Remove and install replacement muffler box in the rear

ESR1053B	R.EXHAUST BOX (rov)-N	1.0 @	175.59 =\$	175.59	175.59
----------	-----------------------	-------	------------	--------	--------

Status: Completed

Job Subtotal: \$250.59

Recommendations: *Air Conditioning Service*

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	1014.20
Parts	956.34
Subtotal	1970.54
Tax	71.73
Total	\$2042.27

1 11/17/00 2042.27 On Acct
--A/R Pmt Allocations--
12/19/01 \$2,042.27
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 101026003

Order Date 10/26/00 11:30 am
 Closed 11/4/2000

[Faded text, likely a stamp or signature]

92 Land Rover RANGE ROVER LS
 Mileage in:75850 out:75850
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 10/26/00 11:30am 127.68
 Dr in person.

Job01 (5) Rover Oil, Lube and Filter Labor: \$45.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL GTX (pnt)-N	15.0 @	1.29 =\$	19.35	
EBC9044	OIL DRAIN SEAL-N	1.0 @	4.50 =\$	4.50	
ERR3340	OIL FILTER (rov)-N	1.0 @	14.92 =\$	14.92	
ZEP009601	PARTS CLEANER-N	1.0 @	10.61 =\$	10.61	49.38

Status: Completed Job Subtotal: \$94.38

Job02 Check battery in remote Labor: \$0.00

Remote working fine numerous tries

Status: Completed Tech: Dr. Job Subtotal: \$0.00

Job03 Missfire?? Labor: \$24.60

Check over vehicle and found plug wire loose secured on cap

Status: Completed Job Subtotal: \$24.60

Recommendations: *30K INTERVAL (major) SERVICE* *Air Conditioning Service*
 REAR MUFFFLER REQUIRED NOW
 POWER STEERING BOX LEAKING

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
101026003

Order Date 10/26/00 11:30 am
Closed 11/4/2000

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	69.60
Parts	49.38
Haz Waste	5.00
Subtotal	123.98
Tax	3.70
Total	\$127.68

1 10/26/00 127.68 On Acct
--A/R Pmt Allocations--
12/19/01 \$127.68
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 100601002

Order Date 06/01/00 08:27 am
 Closed 6/4/2000

Silberg, Dr Barry
 111 Santa Fe Valley
 #1541
 Santa Fe Valley
 Santa Fe Valley

92 Land Rover RANGE ROVER LS
 Mileage in:73603 out:73603
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 06/01/00 08:28am 836.44
 Dr.Barry in person.

Job01 ABS Diagonsis Labor: \$180.40

Trace fault using scan tool and blink codes
 Correct relay fault

PRC9603	A.B.S. RELAY (rov)-N	2.0 @	50.38 =\$	100.76	100.76
---------	----------------------	-------	-----------	--------	--------

Status: Completed Tech: Dr.

Job Subtotal: \$281.16

Job02 (5) Rover Oil, Lube and Filter Labor: \$45.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL GTX (pnt)-N	15.0 @	1.09 =\$	16.35	
EBC9044	OIL DRAIN SEAL-N	1.0 @	4.50 =\$	4.50	
ERR3340	OIL FILTER (rov)-N	1.0 @	14.92 =\$	14.92	
ZEP009601	BRAKE/PARTS CLEANER-N	1.0 @	10.61 =\$	10.61	
gfe1104	AIR FILTER (rov)-N	1.0 @	14.51 =\$	14.51	60.89

Status: Completed

Job Subtotal: \$105.89

Job03 (I5) Replace L.Pwr Steer Hose Labor: \$129.00

Remove low pressure feed hose from res to pump

H/C	HOSE CLAMP-N	2.0 @	1.86 =\$	3.72	
ANR4245	PWR STEER HOSE-S	1.0 @	22.39 =\$	22.39	26.11

Status: Completed

Job Subtotal: \$155.11

Job04 Power wash Steering/eng Area Labor: \$41.00

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
100601002

Order Date 06/01/00 08:27 am
Closed 6/4/2000

Job04 Power wash Steering/eng Area

Clean and wash area around steering box leak and engine compartment

Status: Completed

Job Subtotal: \$41.00

Job05 (rov) Replace Vacuum T/hose

Labor: \$25.80

Remove cracked or brittle vacuum "T" and breather hose as required/listed

ERR4762	P.C.V HOSE (rov)-N	1.0 @	25.42 =\$	25.42	
ERR4763	HOSE PLENUM-"T" FITTING-N	1.0 @	15.54 =\$	15.54	
ERR4764	HOSE, P.C.V LINE-N	1.0 @	14.78 =\$	14.78	
ERR4765	AIR HOSE `T`-N	1.0 @	44.14 =\$	44.14	99.88

Status: Completed Tech: Dr.

Job Subtotal: \$125.68

Job06 Coolant Level Probe

Labor: \$0.00

Change coolant level probe

PRC7925	SENSOR/CAP-S	1.0 @	93.98 =\$	93.98	93.98
---------	--------------	-------	-----------	-------	-------

Status: Completed Tech: Dr.

Job Subtotal: \$93.98

Recommendations: Rear muffler starting to corrode from inside, loose particals can be heard rattling when banging on side of it
Recheck rear brake pads and rotors at next oil service

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors

Cost Summary

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
100601002

Order Date 06/01/00 08:27 am
Closed 6/4/2000

Payments to British European Motors

Cost Summary

Labor	421.20
Parts	381.62
Haz Waste	5.00
Subtotal	807.82
Tax	28.62
Total	\$836.44

1 06/04/00 836.44 On Acct
--A/R Pmt Allocations--
07/20/00 \$836.44
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 100124003

Order Date 01/24/00 09:32 am
 Closed 1/30/2000

Job05 (rov) Replce All Drv Blts 90-92	Labor: \$37.50
---------------------------------------	----------------

Slacken off belts and remove. Install all new belts and adjust

611612	BELT FAN (rov)-N	2.0 @	23.59 =\$	47.18	
ERC675	POWER STEER BELT(rov)-N	1.0 @	26.56 =\$	26.56	
ERR2073	ALT BELT (rov)-N	1.0 @	14.76 =\$	14.76	88.50

Status: Completed

Job Subtotal: \$126.00

Recommendations: *30K INTERVAL (major) SERVICE* *Lube, Oil and Filter* Rear muffler starting to corrode from inside, loose particalls can be heard rattling when banging on side of it
 Recheck rear brake pads and rotors at next oil service 11/6/99

HAPPY NEW YEAR !!!!

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	491.60
Parts	621.75
Subtotal	1113.35
Tax	46.63
Total	\$1159.98

1 01/26/00 1159.98 On Acct
 --A/R Pmt Allocations--
 03/15/00 \$1,159.98
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 090831006

Order Date 08/31/99 11:55 am
 Closed 9/5/1999

Silberg, Dr Barry
 1121...
 ...
 ...
 ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:70537 out:70537
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes		
1	08/31/99 12:02pm	93.75
Dr in person.		
2	08/31/99 05:04pm	1383.83
Dr.Silberg by phone 528-0911		
parts/labor		

Job01 (rov) A/C Hoses Labor: \$93.75

Remove and install replacement hoses from rec/dryer to condensor and condensor to compressor

BTR3710	A/C HOSE-S	1.0 @	239.64 =\$	239.64	
BTR2564	A/C HOSE-S	1.0 @	148.89 =\$	148.89	
46909015	A/C O-RING-N	2.0 @	1.01 =\$	2.02	
46909013	A/C O-RING-N	2.0 @	1.01 =\$	2.02	392.57

Status: Completed Job Subtotal: \$486.32

Job02 (rov) Replace Receiver/Dryer Labor: \$195.00

check system evacuated and remove receiver/dryer lines
 Disconnect and remove dryer
 Install replacement with new seals and secure

BTR3717	REC/DRYER (rov)-N	1.0 @	202.39 =\$	202.39	
46909011	A/C O-RING-N	2.0 @	1.12 =\$	2.24	204.63

Status: Completed Job Subtotal: \$399.63

Job03 Evacuate/Recylce/Hold/Recharge Labor: \$58.00

Hook up recycle machine run full operation

BG702	LEAK DYE/LUBRICANT(a/c)-N	1.0 @	14.92 =\$	14.92	
RF12	FREON rf-12-N	48.0 @	2.39 =\$	114.72	129.64

Status: Completed Tech: Dr. Job Subtotal: \$187.64

Job04 (rov) A/c Compressor,O-rings Labor: \$86.00

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
090831006

Order Date 08/31/99 11:55 am
Closed 9/5/1999

Job04 (rov) A/c Compressor,O-rings

Remove lines and install replacement o-ring seals
Secure hoses and recheck for leaks

STC3192	COMP O-RING SEALS(rov)-N	2.0 @	3.23 =\$	6.46	6.46
---------	--------------------------	-------	----------	------	------

Status: Completed

Job Subtotal: \$92.46

Job05 Third Brake light Cover Labor: \$0.00

Cover trim to be secured on rear brake lamp in rear.

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Job21 Check A/C Not Cold Labor: \$75.00

Hook up recycle machine and test system
Trace fault to system low.
Add small amount of freon and check for leaks
Leaks around hoses and dryer

Status: Completed

Job Subtotal: \$75.00

Job22 Exhaust Leak??? Labor: \$0.00

Secure manifold bolts

Status: Completed Tech: Dr.

Job Subtotal: \$0.00

Recommendations: *30K INTERVAL (major) SERVICE* Recheck rear brake pads and rotors at next oil service 11/6/99

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
090831006

Order Date 08/31/99 11:55 am
Closed 9/5/1999

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	507.75
Parts	733.30
Subtotal	1241.05
Tax	55.00
Total	\$1296.05

1 09/06/99 1296.05 On Acct
--A/R Pmt Allocations--
11/27/00 \$395.14
12/19/01 \$900.91
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 090802001

Order Date 08/02/99 10:42 am
 Closed 8/8/1999

Silberg, Dr Barry
 1111 1st St
 Cotati, CA 94931
 Phone: 707 792-2737

92 Land Rover RANGE ROVER LS
 Mileage in:69888 out:69888
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 08/02/99 10:42am 226.96
 Dr Silberg in person.

Job01 (rov) Oil Lube and Filter Labor: \$33.00

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check
 all levels // Inspect all other levels, brakes belts lights, oil leaks, fuel
 leaks general inspection of complete vehicle

20/50	ENGINE OIL GTX (pnts)-N	15.0 @	1.38 =\$	20.70	
EBC9044	OIL DRAIN SEAL-N	1.0 @	5.16 =\$	5.16	
ERR3340	OIL FILTER (rov)-N	1.0 @	14.92 =\$	14.92	
ZEP009601	BRAKE/PARTS CLEANER-N	1.0 @	10.61 =\$	10.61	51.39

Status: Completed Job Subtotal: \$84.39

Job02 (rov) Replace Alternator Belt Labor: \$77.40

Replace alternator belt

ERR2073	ALT BELT (rov)-N	1.0 @	12.39 =\$	12.39	12.39
---------	------------------	-------	-----------	-------	-------

Status: Completed Job Subtotal: \$89.79

Recommendations: Recheck rear brake pads and rotors at next oil service

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors Cost Summary

Labor	110.40
Parts	63.78
Haz Waste	5.00

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
090802001

Order Date 08/02/99 10:42 am
Closed 8/8/1999

Payments to British European Motors

Cost Summary

SMOG	43.00
Subtotal	222.18
Tax	4.78
Total	\$226.96

1 08/03/99 226.96 On Acct
--A/R Pmt Allocations--
11/27/00 \$226.96
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 090310001

Order Date 03/10/99 07:39 am
 Closed 3/21/1999

Silberg, Dr Barry
 1111 Ocean Ave
 Santa Rosa, CA 95405
 707 538-1111

92 Land Rover RANGE ROVER LS
 Mileage in:67725 out:67725
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 03/10/99 07:38am 200.87
 Dr in person.

Job01 Supply Parts Labor: \$0.00

STC335	PEG PARCEL SHELF-S	1.0 @	15.71 =\$	15.71	
RRNACLIP	CARPET RETAINING CLIP-N	1.0 @	4.12 =\$	4.12	
MXC3352RUN	PANEL-S	1.0 @	46.21 =\$	46.21	66.04

Status: Completed Tech: Dr.

Job Subtotal: \$66.04

Job02 Go out and Jump Start Labor: \$75.00

Jump start and then charge battery when vehicle at shop

Status: Completed

Job Subtotal: \$75.00

Job03 Check For Power Draw Labor: \$46.88

Check battery for power draw
 Pass front lock stuck in down position
 Move and lube linkage
 Battery test good

Status: Completed

Job Subtotal: \$46.88

Recommendations: *Lube, Oil and Filter* SEAT BELT BUCKLE \$99.15 +TAX CAN BE
 HERE IN ONE DAY

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors Cost Summary

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
090310001

Order Date 03/10/99 07:39 am
Closed 3/21/1999

Payments to British European Motors

Cost Summary

Labor	121.88
Parts	66.04
Shipping	8.00
Subtotal	195.92
Tax	4.95
Total	\$200.87

1 03/22/99 200.87 On Acct
--A/R Pmt Allocations--
11/27/00 \$200.87
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 081203004

Order Date 12/03/98 03:02 pm
 Closed 12/6/1998

Silberg, Dr Harry
 1111 S. ...
 ...
 ...
 ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:67725 out:67725
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 12/03/98 03:01pm 1128.40
 Dr Silberg by phone call-in

added wiper blades parts only

Job01 (rov) 7,500 Interval Service Labor: \$283.80

Renew engine oil and filter..Check condition drive belts-adj if required.Check top up cooling system.Check HT leads and wiring for fraying/chaffing/deteriation.Check engine idle speed .Scoipe check engine and Aux equipment.Check fuel lines for leakage/damage and security.Check operation of electronic control unit/systems.Check top up transfer box oil/front axle oil/rear axle oil/. Check top up power steering fluid/chk for leaks/security.Check top up swivel housing oil levels.Check top up transmission oil leve/check for leaks and operation.Check top up brake fluid/check for leaks and deteriation.Check for oil leakson suspension struts and wear on bushings/arms/steering components.Check foot brake and handbrake operation.Check steering box free play adjust as required.Check crnakcase ventilation system/clean filter(breathers) as required.Check clean air filter dump valve if required.Check throttle linkage and transmission cable.Check condition/security of seats,seat belts/mouldingsand buckles.Check tightness of propeller shaft coupling bolts. check exhaust system for leaks and security. Check cruise control operation. Check tires and pressures/comply with manufactures specs.check for cuts/damage/uneven wear depth and road wheels for damage.Check headlamp alignment/security.check operation of all instruments,fuel and temp gauges,warning indicators,lamps,horns and audio warning unit.check operation of front and rear windshield washers/wipers.Check sunroof drain tubes. check operation of doors,hood,tailgate locksand window controls.Lubricate door locks,hinges.Check operation of heater,a/c syatems.Inspect brake pads/rotors for wearand leaks.Add Techron/washer fluid .Lubricate all points required/Report any items required.

20/50	ENGINE OIL GTX (pnts)-N	13.0 @	1.38 =\$	17.94	
BG110	ENGINE OIL ADDATIVE-N	1.0 @	10.29 =\$	10.29	
BG203	FUEL ADD DEPOSIT CONTROL-N	1.0 @	11.38 =\$	11.38	
EBC9044	OIL DRAIN SEAL-N	1.0 @	5.16 =\$	5.16	
ERR3340	OIL FILTER (rov)-N	1.0 @	14.63 =\$	14.63	
WURTH	W/SHIELD WASHER FLUID-N	1.0 @	3.91 =\$	3.91	63.31

Status: Completed

Job Subtotal: \$347.11

Job02 (rov) Replc F.Brk Pads (90-) Labor: \$94.60

Raise vehicle and remove front wheels. Check and clean all area, and install new pads. Refit road wheels and road test complete.

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
 081203004

Order Date 12/03/98 03:02 pm
 Closed 12/6/1998

Job02 (rov) Replc F.Brk Pads (90-)

RTC6781	F.BRAKE PAD (rov 90-)-N	1.0 @	120.57 =\$	120.57	
ZEP009601	BRAKE/PARTS CLEANER-N	1.0 @	6.91 =\$	6.91	
BG68	STOP SQUEEL-N	1.0 @	16.14 =\$	16.14	143.62

Status: Completed Job Subtotal: \$238.22

Job03 (rov) Dist. Vacuum Advance Unit) Labor: \$189.20

Remove distributor
 Remove center rotor and check mechanical advance weights.
 Free off and lube as required.
 Install replacement vacuum advance unit.
 Refit distributor into engine and set ignition timing and confirm vacuum advance operation.

54420300	DISTRIBUTOR RETAINER-N	1.0 @	5.31 =\$	5.31	
RTC5022	VACUUM ADV UNIT (rov)-N	1.0 @	145.76 =\$	145.76	
DDB176	DIST CAP (rov)-N	1.0 @	46.68 =\$	46.68	
DRB195	DIST ROTOR (rov)-N	1.0 @	20.56 =\$	20.56	
RTC6551	PLUG WIRE SET-N	1.0 @	67.82 =\$	67.82	286.13

Status: Completed Job Subtotal: \$475.33

Job04 Replace Fog Lamp Bulbs Labor: \$0.00

Right side non operational
 Upgraded left and right side

H3	FOG LAMP BULB(helogen)-N	2.0 @	11.98 =\$	23.96	23.96
----	--------------------------	-------	-----------	-------	-------

Status: Completed Job Subtotal: \$23.96

Job05 F.Wiper Blades Labor: \$0.00

40918	WIPER BLADE-N	2.0 @	14.32 =\$	28.64	28.64
-------	---------------	-------	-----------	-------	-------

Status: Completed Tech: Dr. Job Subtotal: \$28.64

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 3

Invoice No.
081203004

Order Date 12/03/98 03:02 pm
Closed 12/6/1998

Recommendations: SEAT BELT BUCKLE \$99.15 +TAX CAN BE HERE IN ONE DAY

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	567.60
Parts	545.66
Haz Waste	5.00
Subtotal	1118.26
Tax	40.92
Total	\$1159.18

1 12/07/98 1159.18 On Acct
--A/R Pmt Allocations--
11/27/00 \$1,159.18
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

British European Motors
 606 Portal Street
 Cotati, CA 94931
 Phone: 707 792-2737 FAX: 707 792-4454

Invoice No.
 081122001

Order Date 11/22/98 08:24 am
 Closed 11/21/1998

Silberg, Dr Sarry
 111 S. ...
 ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:00000 out:
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 11/22/98 08:25am 187.80
 Dr in person.

Job01 Go Out Check Battery Labor: \$92.51

Install temp battery and return to shop for charge and test
 Charged battery and load test.No Good

MT34	BATTERY (xj6/rov)-N	1.0 @	88.64 =\$	88.64	88.64
------	---------------------	-------	-----------	-------	-------

Status: Completed Job Subtotal: \$181.15

Recommendations: *Lube, Oil and Filter*

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors Cost Summary

Labor	92.51
Parts	88.64
Subtotal	181.15
Tax	6.65
Total	\$187.80

1 11/22/98 187.80 On Acct
 --A/R Pmt Allocations--
 11/27/00 \$187.80
 *Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 080326004

Order Date 03/26/98 10:21 am
 Closed 3/28/1998

Silberg, Dr Barry
 1111...
 1000...
 Santa Rosa...
 707...
 707...

92 Land Rover RANGE ROVER LS
 Mileage in:65472 out:65472
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 03/26/98 10:20am 1180.21
 Dr in person.

Job01 Remove/refit drivers Seat Labor: \$64.76

Remove and refit drivers seat for elliment replacement

RTD4343	SEAT ELLIMENT-S	1.0 @	93.32 =\$	93.32	
TRFD4343	SEAT ELLIMENT BOTTOM-S	1.0 @	68.72 =\$	68.72	162.04

Status: Completed Job Subtotal: \$226.80

Job02 (rov) Replace Valve Cover Gaskets Labor: \$277.53

Remove plenum chamber//remove valve cover gaskets// Install new gaskets//Refit/seal plenum chamber//Run Test leaks

25223	GSKT SEALER-N	0.5 @	20.69 =\$	10.35	
ERR7288	VALVE COVER GSKT(rov)-N	2.0 @	15.94 =\$	31.88	42.23

Status: Completed Job Subtotal: \$319.76

Job03 (rov) Hub Swivel Seal (w/abs) Labor: \$283.80

Raise vehicle and remove wheel. Remove/disconnect front hub assembly. Remove seals as required and fit new.
 Drain oil and update to Land Rover aproved swivel housing grease.
 Refit assembly and road wheel.Road test complete.

FRC2349	SWIVEL HUB GASKET iner-N	1.0 @	3.43 =\$	3.43	
FRC2889	HUB SWIVEL SEAL(rov9.mm)-N	1.0 @	28.71 =\$	28.71	
FTC1376	A.B.S SENSR SEAL (rov)-N	1.0 @	14.93 =\$	14.93	
FTC2783	HUB SEAL ALL (rov)-N	1.0 @	11.24 =\$	11.24	
STC3435	ONE SHOT SWIVEL GREASE-N	1.0 @	13.18 =\$	13.18	71.49

Status: Completed Job Subtotal: \$355.29

Job04 Seat Heat Elliment Sublet: \$188.00

Remove seat cover and padding

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
080326004

Order Date 03/26/98 10:21 am
Closed 3/28/1998

Job04 Seat Heat Elliment

Remove heater elliment and install replacement

Job05 Update Swivel Housing Grease	Labor: \$55.51
------------------------------------	----------------

Drain swivel housing oil and install updated grease on left side housing

STC3435	ONE SHOT SWIVEL GREASE-N	1.0 @	13.18 =\$	13.18	13.18
---------	--------------------------	-------	-----------	-------	-------

Status: Completed

Job Subtotal: \$68.69

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	681.60
Parts	288.94
Sublet	188.00
Subtotal	1158.54
Tax	21.67
Total	\$1180.21

1 03/29/98 1180.21 On Acct
--A/R Pmt Allocations--
04/26/98 \$1,180.21
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
080319002

Order Date 03/19/98 11:27 am
Closed 3/21/1998

Recommendations: Valve cover gaskets seeping oil (update to new style required.

Seat heater pads required.

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors

Cost Summary

Labor	283.80
Parts	62.42
Haz Waste	5.00
Subtotal	351.22
Tax	4.68
Total	\$355.90

1 03/22/98 355.90 On Acct
--A/R Pmt Allocations--
04/26/98 \$355.90
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 071104002

Order Date 11/04/97 09:30 am
 Closed 11/8/1997

Silberg, Dr Barry
 1111 1st Ave S.W.
 Lido 1
 Santa Monica, CA 90405
 Tel: 310 318 1111

92 Land Rover RANGE ROVER LS
 Mileage in:62312 out:62312
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 11/04/97 09:29am 142.01
 Dr Barry in person.

Discount replacement brake parts on rear

Job01 Brake Squeel Labor: \$88.80

Check noise from front or rear.
 Remove rear pads and install replacements.

RTC4518	F.BRAKE PAD (rov-90)-N	1.0 @	105.76 =\$	105.76	
STOP 68	SQUEEL PREVENTER-N	1.0 @	6.79 =\$	6.79	112.55

Status: Completed Job Subtotal: \$201.35

Job02 D.Seat Eliment Hotter?? Labor: \$0.00

Seat will have to be dis-assembled and possibly replacement pads installed.
 Colud be vey costly????!?!?

Status: Completed Tech: Dr. Job Subtotal: \$0.00

Job03 Oil Leaks???? Smelling Labor: \$0.00

Secure valve cover bolts and clean off.
 Road test and recheck.

Status: Completed Job Subtotal: \$0.00

Job04 Right Catalytic Convtr Sublet: \$123.32

Remove right side front convertor and install replacement.

Job05 Cat Convertor Parts Labor: \$0.00

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
071104002

Order Date 11/04/97 09:30 am
Closed 11/8/1997

Job05 Cat Convertor Parts

Right side cat convertor and gaskets parts

RTC55456	R.CAT CONVERTOR-S	1.0 @	303.39 =\$	303.39	303.39
----------	-------------------	-------	------------	--------	--------

Status: Completed Tech: Dr.

Job Subtotal: \$303.39

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors

Cost Summary

Labor	88.80
Parts	415.94
Sublet	123.32
Discount	112.55
Subtotal	515.51
Tax	22.76
Total	\$538.27

1 11/08/97 538.27 On Acct
--A/R Pmt Allocations--
12/15/97 \$538.27
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 070916002

Order Date 09/16/97 10:57 am
 Closed 9/20/1997

Silberg, Dr Barry
 1111 Progress Ave
 Cotati, CA 94931
 Phone: 707-792-4454

92 Land Rover RANGE ROVER LS
 Mileage in:59903 out:59903
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 09/16/97 10:58am 0.00
 Dr in person.

Job01 (rov) Replace all Coolant Hoses Labor: \$192.40

Remove all coolant hoses and install new with new clamps and re-add coolant (changed at 60k service)to correct percentage.

BTR216	HOSE HEATER INLET-N	1.0 @	31.16 =\$	31.16	
BTR217	HOSE HEATER OUTLET-N	1.0 @	27.31 =\$	27.31	
ESR1052	TOP HOSE-N	1.0 @	27.35 =\$	27.35	
ETC6889	HOSE HEATER RETURN-N	1.0 @	18.24 =\$	18.24	
ETC6890	HOSE HEATER-N	1.0 @	21.46 =\$	21.46	
H/C	HOSE CLAMP-N	15.0 @	1.56 =\$	23.40	
NTC5632	LOWER RADIATOR HOSE-N	1.0 @	65.75 =\$	65.75	
F5/16	HOSE/FOOT-N	4.0 @	2.37 =\$	9.48	
81242 MMV-9	HOSE 9MM-N	3.0 @	3.18 =\$	9.54	233.69

Status: Completed Job Subtotal: \$426.09

Job02 Front Anti-Roll Bar Labor: \$88.80

Refit roll bar with replacement bushings and right side mounting pin.

NTC8202	MOUNTING PIN-S	1.0 @	14.64 =\$	14.64	
264024	WASHER-S	1.0 @	2.52 =\$	2.52	
552819	BUSHING ROLL BAR-S	4.0 @	4.07 =\$	16.28	
NV116041	LOCKING NUT-S	1.0 @	1.64 =\$	1.64	35.08

Status: Completed Job Subtotal: \$123.88

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors Cost Summary

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
070916002

Order Date 09/16/97 10:57 am
Closed 9/20/1997

Payments to British European Motors

Cost Summary

Labor	281.20
Parts	268.77
Subtotal	549.97
Tax	20.16
Total	\$570.13

1 09/18/97 570.13 On Acct
--A/R Pmt Allocations--
10/28/97 \$570.13
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 070911002

Order Date 09/11/97 09:31 am
 Closed 9/13/1997

Silberg, Dr. Harry
 1111 1st St
 2nd Floor
 San Francisco, CA 94107
 Phone: 415 774 1111

92 Land Rover RANGE ROVER LS
 Mileage in:59903 out:59903
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 09/11/97 09:29am 914.60
 Dr in person.

Job01 (rov) 60K Interval Service 90- Labor: \$547.60

Service list as recommended by Range Rover plus additional additives highly recommended for longer life and durability

20/50	ENGINE OIL GTX (pnts)-N	14.0 @	1.38 =\$	19.32	
A/F	ANTIFREEZE/COOLANT (pnts)-R	12.0 @	1.87 =\$	22.44	
ATF	TRANS FLUID (pnts)-N	9.0 @	1.97 =\$	17.73	
DIFF-OIL	1/2 pint DIFF-OIL-N	26.0 @	0.72 =\$	18.72	
EBC9044	OIL DRAIN SEAL-N	1.0 @	4.98 =\$	4.98	
ERR3340	OIL FILTER (rov)-N	1.0 @	13.21 =\$	13.21	
ETC4524	EXHAUST FLANGE GASKET-N	2.0 @	17.39 =\$	34.78	
FK82716	TRANS SERVICE KIT(rov)-N	1.0 @	60.71 =\$	60.71	
FN108041L	EX MANIFOLD NUT(rov)-N	6.0 @	1.96 =\$	11.76	
GFE1104	AIR FILTER (rov)-N	1.0 @	14.51 =\$	14.51	
GR1	GREASE/LUBE-N	1.0 @	4.91 =\$	4.91	
LMA	BRAKE FLUID BY THE Oz-N	32.0 @	0.66 =\$	21.12	
M.I.3000	FUEL ADD DEPOSIT CONTROL-N	1.0 @	9.98 =\$	9.98	
M.O.A	MOTOR OIL ADDATIVE-N	1.0 @	15.43 =\$	15.43	
NMD6091AB	FUEL FILTER (rov/jag)-N	1.0 @	23.49 =\$	23.49	
RN14YC	SPARK PLUG-N	8.0 @	4.97 =\$	39.76	
WURTH	W/SHIELD WASHER FLUID-N	1.0 @	3.91 =\$	3.91	336.76

Status: Completed

Job Subtotal: \$884.36

Recommendations: RADIATOR HOSES HAVE BEEN LEAKING

SWAY BAR ON FRONT RIGHT SIDE MISSING BUSHINGS AND SECURING BOLT.

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors Cost Summary

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
070911002

Order Date 09/11/97 09:31 am
Closed 9/13/1997

Payments to British European Motors

Cost Summary

Labor	547.60
Parts	336.76
Haz Waste	5.00
Subtotal	889.36
Tax	25.26
Total	\$914.62

1 09/14/97 914.62 On Acct
--A/R Pmt Allocations--
10/28/97 \$914.62
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 070725001

Order Date 07/25/97 08:42 am
 Closed/Paid: 07/27/97 09:09 am

Sullivan, Dr. Barry
 1015 S. ...
 ...

92 Land Rover RANGE ROVER LS
 Mileage in:57433 out:57433
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 07/25/97 08:39am 1642.96
 Dr in person.

Job01 (rov) Install 4 Tires Labor: \$80.00

Sublet dismount/mount new and balance

205/80R16XPC	TIRE ROVER-N	4.0 @	215.61 =\$	862.44	862.44
--------------	--------------	-------	------------	--------	--------

Status: Completed Tech: Dr.

Job Subtotal: \$942.44

Job02 (rov) Install Shocks Fnt & Rear Labor: \$185.00

Remove and install to upgrade shocks with bilstein

B46-0243	FRONT SHOCK(rov)-N	2.0 @	106.37 =\$	212.74	
B46-0253	REAR SHOCK (rov)-N	2.0 @	103.32 =\$	206.64	419.38

Status: Completed

Job Subtotal: \$604.38

EPA#CAL000157651/BAR#AG190042

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Status: Closed Work Order
 Payments: \$1,642.96
 1 07/27/97 1642.96 Check

Labor	265.00
Parts	1281.82
Subtotal	1546.82
Tax	96.14
Total	\$1642.96
Payments	1642.96
Bal Due	0.00

Thank you for choosing British European Motors

Invoice No.
 070717004

Order Date 07/17/97 12:19 pm
 Closed 7/19/1997

Silbery, Dr Harry
 1111 Serrano Ave
 Cotati, CA 94931
 Phone: 707 792-2737

92 Land Rover RANGE ROVER LS
 Mileage in:57176 out:57176
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes
 1 07/16/97 08:50am 500.03
 Dr in person.

Job01 (rov) Replace Steering Lock(int) Labor: \$111.00

Remove steering turn/wiper covers. Free off and remove shear bolts from ignition lock. Check ignition lock for fault and replace as required

NTC9440	STEER LOCK (int.lock)-N	1.0 @	341.24 =\$	341.24	341.24
---------	-------------------------	-------	------------	--------	--------

Status: Completed

Job Subtotal: \$452.24

Job02 (rov) Oil Lube and Filter Labor: \$44.40

Raise vehicle // Drain oil and remove filter
 Install new filter // add oil run check leaks // Lube fittings as required check all levels // Inspect

20/50	ENGINE OIL GTX (pnts)-N	15.0 @	1.38 =\$	20.70	
EBC9044	OIL DRAIN SEAL-N	1.0 @	4.98 =\$	4.98	
ERR3340	OIL FILTER (rov)-N	1.0 @	13.21 =\$	13.21	38.89

Status: Completed

Job Subtotal: \$83.29

Recommendations: ***** ALL TIRES REQUIRED *****

EPA#CAL000157651/BAR#AG190042

come visit us on the web WWW.BRITISHEUROPEAN.COM

Payments to British European Motors Cost Summary

Labor 155.40
 Parts 380.13

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
070717004

Order Date 07/17/97 12:19 pm
Closed 7/19/1997

Payments to British European Motors

Cost Summary

Haz Waste	5.00
Discount	341.24
Subtotal	199.29
Tax	2.92
Total	\$202.21

1 07/17/97 202.21 On Acct
--A/R Pmt Allocations--
10/28/97 \$202.21
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 070310002

Order Date 03/10/97 09:49 am
 Closed 3/15/1997

	92 Land Rover RANGE ROVER LS Mileage in:53029 out:53029 Lic: 3BKH816/CA 8Cyl 4.0 Vin: SALHV1246NA618427 01/92 Eq: AT AC PS FI 4W Last in 11/12/2021	<p style="text-align: right;">Quotes</p> <hr/> 1 03/04/97 08:58pm 677.79 Dr in person.
--	--	---

WE HAVE TO RECHECK POWER STEERING LEAKS AND CARRY OUT BRAKE WORK REQUIRED

Job01 (rov)Replc R.Brk Rotor/Pads (90-	Labor: \$244.20
--	-----------------

Raise vehicle and remove rear wheels. Remove brake caliper and pads and clean. Remove hub and remove brake rotor. Clean and install new rotor and remove bearings clean and repack, install new seals refit hub and brake caliper assembly. Install new pads and sensor, bleed out fluid/air. Refit road wheels and road test complete.

028701	BRAKE/PARTS CLEANER-N	1.0 @	6.68 =\$	6.68	
571752	GASKET AXLE FLANGE(rov-N	2.0 @	0.98 =\$	1.96	
FTC1381	R.BRAKE ROTOR (rov 90--N	2.0 @	133.23 =\$	266.46	
FTC2783	HUB SEAL ALL (rov)-N	2.0 @	11.24 =\$	22.48	
RTC4518	R.BRAKE PAD (rov all)-N	1.0 @	105.76 =\$	105.76	403.34

Status: Completed

Job Subtotal: \$647.54

Recommendations: *Lube, Oil and Filter* *Rear Brakes* REAR BRAKE PADS AND ROTORS

STEERING BOX STARTING TO LEAK FLUID

EPA#CAL000157651/BAR#AG190042

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	244.20
Parts	403.34
Subtotal	647.54
Tax	30.25

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
070310002

Order Date 03/10/97 09:49 am
Closed 3/15/1997

Payments to British European Motors

Cost Summary

Total \$677.79

1 03/16/97 677.79 On Acct
--A/R Pmt Allocations--
10/28/97 \$677.79
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 070227002

Order Date 02/27/97 04:21 pm
 Closed 3/1/1997

92 Land Rover RANGE ROVER LS
 Mileage in: out:46231
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Quotes

1 02/27/97 11:25am 340.74
 Dr in person.

Job01 (rov) 7,500 Interval Service

Labor: \$244.20

Renew engine oil and filter..Check condition drive belts-adj if required.Check top up cooling system.Check HT leads and wiring for fraying/chaffing/deteriation.Check engine idle speed .Scoipe check engine and Aux equipment.Check fuel lines for leakage/damage and security.Check operation of electronic control unit/systems.Check top up transfer box oil/front axle oil/rear axle oil/. Check top up power steering fluid/chk for leaks/security.Check top up swivel housing oil levels.Check top up transmission oil leve/check for leaks and operation.Check top up brake fluid/check for leaks and deterioration.Check for oil leakson suspension struts and wear on bushings/arms/steering components.Check foot brake and handbrake operation.Check steering box free play adjust as required.Check crnakcase ventilation system/clean filter(breathers) as required.Check clean air filter dump valve if required.Check throttle linkage and transmission cable.Check condition/security of seats,seat belts/mouldingsand buckles.Check tightness of propeller shaft coupling bolts. check exhaust system for leaks and security. Check cruise control operation. Check tires and pressures/comply with manufactures specs.check for cuts/damage/uneven wear depth and road wheels for damage.Check headlamp alignment/security.check operation of all instruments,fuel and temp gauges,warning indicators,lamps,horns and audio warning unit.check operation of front and rear windshield washers/wipers.Check sunroof drain tubes. check operation of doors,hood,tailgate locksand window controls.Lubricate door locks,hinges.Check operation of heater,a/c syatems.Inspect brake pads/rotors for wearand leaks.Add Techron/washer fluid .Lubricate all points required/Report any items required.

20/50	ENGINE OIL GTX (pnts)-N	13.0 @	1.38 =\$	17.94	
EBC9044	OIL DRAIN SEAL-N	1.0 @	4.98 =\$	4.98	
ERR3340	OIL FILTER (rov)-N	1.0 @	13.21 =\$	13.21	
M.I.3000	FUEL ADD DEPOSIT CONTROL-N	1.0 @	9.98 =\$	9.98	
M.O.A	MOTOR OIL ADDATIVE-N	1.0 @	15.43 =\$	15.43	
WURTH	W/SHIELD WASHER FLUID-N	1.0 @	3.91 =\$	3.91	65.45

Status: Completed

Job Subtotal: \$309.65

Recommendations: *Rear Brakes* REAR BRAKE PADS AND ROTORS

STEERING BOX STARTING TO LEAK FLUID

EPA#CAL000157651/BAR#AG190042

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
070227002

Order Date 02/27/97 04:21 pm
Closed 3/1/1997

Payments to British European Motors	Cost Summary
-------------------------------------	--------------

Labor	244.20
Parts	65.45
Haz Waste	5.00
Subtotal	314.65
Tax	4.91
Total	\$319.56

1 03/02/97 319.56 On Acct
--A/R Pmt Allocations--
10/28/97 \$319.56
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 060820005

Order Date 08/20/96 11:55 am
 Closed 8/24/1996

92 Land Rover RANGE ROVER LS
 Mileage in:46231 out:46231
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

detail dents oil warning faults
 CHECK REMOTE ENTRY LOCKING SYSTEM
 canuber wax??
 CHECK A.B.S ON START UP AFTER WORK WAS CAVITATING.
 HANDS FREE PHONE KIT FUSE BLOWN.

Job01 (rov) Replc F.Brk Pads/Rotrs(90- Labor: \$237.60

Raise vehicle and remove front wheels. Remove front axles and remove hub, rotor and brake caliper assembly. Check and clean all area, clean and inspect/replace hub bearings and repack Refit hub and rotor. Refit brake caliper and install new pads. Refit road wheels and road test complete.

028701	BRAKE WASH(PARTS CLEAN-N	1.0 @	6.68 =\$	6.68	
FTC2783	HUB SEAL ALL (rov)-N	2.0 @	10.62 =\$	21.24	
FTC902	F.BRAKE ROTOR (rov 90--N	1.0 @	152.21 =\$	152.21	
LP599	F.BRAKE PAD (rov 90-)-N	1.0 @	65.71 =\$	65.71	245.84

Status: Completed Tech: Unknown

Job Subtotal: \$483.44

Job02 Replace L.Side Head gasket Labor: \$640.80

Remove intake amnifold and r.side exhaust manifold. Remove valve cover and remove rockers. Loosen head bolts and remove cylinder head. Surface head and clean off block. Install replacement head gasket and install head. Refit rockers and intake manifold etc..Run and road test. Change oil and filter. Top up coolant to strength and level.

STC1641	HEAD GASKET SET (rov)-N	1.0 @	135.91 =\$	135.91	135.91
---------	-------------------------	-------	------------	--------	--------

Status: Completed Tech: Unknown

Job Subtotal: \$776.71

Job03 SURFACE CYLINDER HEAD Sublet: \$110.00

PRESSURE TEST AND SURFACE CYLINDER HEAD. INSPECT FOR WEAR AND REPORT

----->----->----->---Continued on the next page--->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
060820005

Order Date 08/20/96 11:55 am
Closed 8/24/1996

Job03 SURFACE CYLINDER HEAD

Job04 Diagnose Remote Entry Non Op. Labor: \$158.40

Check for loose E.C.U chip loose or fallen out. Run thru diagnostic tree for faults. Found wiring at control unit right side phone hook up loose. Secured with new terminals and retest all function good.

Status: Completed Tech: Unknown

Job Subtotal: \$158.40

Recommendations: OIL WARNING SYSTEM FUNCTIONING OK AT THIS TIME

EPA#CAL000157651/BAR#AG190042

Payments to British European Motors Cost Summary

Labor	1036.80
Parts	381.75
Sublet	110.00
Discount	1557.16
Subtotal	-28.61
Tax	28.63
Total	\$0.02

1 08/25/96 0.02 On Acct trade total less
--A/R Pmt Allocations--
10/28/97 \$0.02
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 060521005

Order Date 05/21/96 04:13 pm
 Closed 5/24/1996

92 Land Rover RANGE ROVER LS
 Mileage in:43293 out:43293
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Job01 (rov) Replace F.Swivel Seal Labor: \$237.60

Raise vehicle and remove road wheel. Disconnect front hub assembly and lower from vehicle. Disemble hub swivel and remove gasket and seal. Install new swivel seal and A.B.S sensor seal (as reqd.) Refit all components and top off fluid. Refit wheel and lower vehicle. Road test complete.

FRC2889	HUB SWIVEL SEAL(abs)RO-N	1.0 @	28.71 =\$	28.71	
FTC1376	OIL SEAL (abs snsr rov-N	1.0 @	13.55 =\$	13.55	
FRC2349	SWIVEL HUB GASKET iner-N	1.0 @	3.43 =\$	3.43	45.69

Status: Completed Tech: Unknown

Job Subtotal: \$283.29

Job02 (rov) Replace Valve Cover Gaskets Labor: \$223.20

Remove plenum chamber//remove valve cover gaskets// Install new gaskets//Refit/seal plenum chamber//Run Test leaks

602512	VALVE COVER GASKET-N	2.0 @	8.12 =\$	16.24	16.24
--------	----------------------	-------	----------	-------	-------

Status: Completed Tech: Unknown

Job Subtotal: \$239.44

Recommendations: RIGHT SIDE FRONT HUB SEAL(SWIVEL) LEAKING. VALVE COVER GASKETS LEAKING OIL DRIPS AT REAR OF ENGINE. OIL PUMP VALVE BODY LEAKING OIL (minor)
 CYLINDER HEADS HAVE COOLANT RESIDUE AROUND GASKET WHERE CYLINDER HEADS JOIN BLOCK LEFT AND RIGHT.

Payments to British European Motors Cost Summary

----->----->----->-----Continued on the next page----->----->----->----->

British European Motors
606 Portal Street
Cotati, CA 94931
Phone: 707 792-2737 FAX: 707 792-4454

Page 2

Invoice No.
060521005

Order Date 05/21/96 04:13 pm
Closed 5/24/1996

Payments to British European Motors

Cost Summary

Labor	460.80
Parts	61.93
Subtotal	522.73
Tax	4.65
Total	\$527.38

1 05/22/96 527.38 On Acct
--A/R Pmt Allocations--
04/28/97 \$241.85
07/29/97 \$202.21
10/28/97 \$83.32
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors

Invoice No.
 060514003

Order Date 05/14/96 01:44 pm
 Closed 5/19/1996

92 Land Rover RANGE ROVER LS
 Mileage in:43011 out:43011
 Lic: 3BKH816/CA 8Cyl 4.0
 Vin: SALHV1246NA618427 01/92
 Eq: AT AC PS FI 4W
 Last in 11/12/2021

Job01 (rov) 7,500 Interval Service

Labor: \$237.60

Renew engine oil and filter..Check condition drive belts-adj if required.Check top up cooling system.Check HT leads and wiring for fraying/chaffing/deteriation.Check engine idle speed .Scoipe check engine and Aux equipment.Check fuel lines for leakage/damage and security.Check operation of electronic control unit/systems.Check top up transfer box oil/front axle oil/rear axle oil/. Check top up power steering fluid/chk for leaks/security.Check top up swivel housing oil levels.Check top up transmission oil leve/check for leaks and operation.Check top up brake fluid/check for leaks and deterioration.Check for oil leakson suspension struts and wear on bushings/arms/steering components.Check foot brake and handbrake operation.Check steering box free play adjust as required.Check crnakcase ventilation system/clean filter(breathers) as required.Check clean air filter dump valve if required.Check throttle linkage and transmission cable.Check condition/security of seats,seat belts/mouldingsand buckles.Check tightness of propeller shaft coupling bolts. check exhaust system for leaks and security. Check cruise control operation. Check tires and pressures/comply with manufactures specs.check for cuts/damage/uneven wear depth and road wheels for damage.Check headlamp alignment/security.check operation of all instruments,fuel and temp gauges,warning indicators,lamps,horns and audio warning unit.check operation of front and rear windshield washers/wipers.Check sunroof drain tubes. check operation of doors,hood,tailgate locksand window controls.Lubricate door locks,hinges.Check operation of heater,a/c syatems.Inspect brake pads/rotors for wearand leaks.Add Techron/washer fluid .Lubricate all points required/Report any items required.

20/50	PINTS GTX ENG OIL-N	13.0 @	1.38 =\$	17.94	
EBC9044	OIL DRAIN SEAL-N	1.0 @	4.98 =\$	4.98	
ERR3340	OIL FILTER-N	1.0 @	12.98 =\$	12.98	
M.I.3000	FUEL ADD DEPOSIT CONTROL-N	1.0 @	9.98 =\$	9.98	
M.O.A	MOTOR OIL ADDATIVE-N	1.0 @	15.43 =\$	15.43	
WURTH	W/SHIELD WASHER FLUID-N	1.0 @	3.91 =\$	3.91	65.22

Status: Completed Tech: Unknown

Job Subtotal: \$302.82

Job02 (rov) Replace Steering Lock

Labor: \$108.00

Remove steering turn/wiper covers. Free off and remove shear bolts from ignition

----->----->----->---Continued on the next page--->----->----->----->

Invoice No.
060514003

Order Date 05/14/96 01:44 pm
Closed 5/19/1996

Job02 (rov) Replace Steering Lock

from ignition lock. Check ignition lock for fault and replace as

NTC9440	STEER LOCK (int.lock)-N	1.0 @	312.36 =\$	312.36	312.36
---------	-------------------------	-------	------------	--------	--------

Status: Completed Tech: Unknown

Job Subtotal: \$420.36

Recommendations: RIGHT SIDE FRONT HUB SEAL(SWIVEL) LEAKING. VALVE COVER GASKETS LEAKING OIL DRIPS AT REAR OF ENGINE. OIL PUMP VALVE BODY LEAKING OIL (minor)
CYLINDER HEADS HAVE COOLANT RESIDUE AROUND GASKET WHERE CYLINDER HEADS JOIN BLOCK LEFT AND RIGHT.

Payments to British European Motors

Cost Summary

Labor	345.60
Parts	377.58
Haz Waste	5.00
Subtotal	728.18
Tax	28.32
Total	\$756.50

1 05/19/96 756.50 On Acct
--A/R Pmt Allocations--
10/07/96 \$1.00
03/27/97 \$677.79
04/28/97 \$77.71
*Unpaid Bal: \$0.00

Thank you for choosing British European Motors