

2001 PORSCHE BOXSTER

Service History & Documentation Portfolio

This vehicle is accompanied by a comprehensive collection of original documentation intended to provide complete transparency regarding its history, maintenance, and care.

Included in this binder:

- CARFAX Vehicle History Report
- Original Hammond Autowerks repair orders (2024–2025)
- Lifetime maintenance summary
- Supporting service documentation

The accompanying records document dealer servicing during the car's early years, long-term California ownership, and extensive recent maintenance by Hammond Autowerks, including preventative inspections, transmission service, battery and window regulator replacement, Porsche PCCM+ infotainment installation, and an engine oil inspection showing no metallic debris during the June 2025 service.

With just over 62,000 original miles, this Boxster represents a carefully maintained example with unusually complete documentation for its age. Prospective buyers are encouraged to review the enclosed records in conjunction with their own inspection and test drive.

Prepared for the sale of this vehicle

All service records included in chronological order.

2001 Porsche Boxster (VIN WP0CA29851U623039)

Lifetime Maintenance Summary

Overall: This 2001 Porsche Boxster has accumulated just 62,115 miles and benefits from a well-documented service history from new through June 2025. The records show consistent dealer and specialist maintenance, long-term ownership, and approximately \$5,700 invested by the current owner during late 2024–2025.

2001–2005 (Florida): Dealer serviced at Braman Porsche of Palm Beach. Documented work includes warranty servicing, front brake replacement, battery replacement, cooling system service, A/C recharge, brake light switch replacement, front strut bearing replacement, throttle housing replacement, 30,000-mile service, oil filler tube replacement, steering lock replacement, brake fluid flushes, and tire service.

2005–2024 (California): Long-term California ownership with exceptionally low annual mileage. Regular smog inspections and documented maintenance include oil services, air and cabin filters, serpentine belt replacement, A/C service and recharge, brake master cylinder repair, front brake hoses, brake fluid flush, and headlight bulbs. A minor 2006 accident (stationary object, no airbag deployment) is reported on CARFAX with no subsequent structural, salvage, or title issues.

2024–2025 (Hammond Autowerks): Initial inspection and baseline service included engine oil and filter, battery replacement, passenger window regulator replacement, diagnostic scan, and comprehensive inspection. A genuine Porsche PCCM+ infotainment system was installed. The battery was later replaced under warranty. Cosmetic upgrades included Coco Mats and Porsche crest center caps. June 2025 service included engine oil and filter, automatic transmission fluid and filter service, hood strut replacement, and an inspection of drained engine oil specifically for IMS bearing debris; no metallic contamination was found.



Report

2001 Porsche Boxster

62,115 mi | VIN: WPOCA29851U623039 |

Convertible | 2.7L H6 F | Gasoline | Rear wheel drive



ACCIDENT



Accident Reported

CARFAX VALUE \$13,930



25 Service History Records



At Least 1 Open Recall



4 Previous Owners



Personal Vehicle



Last Owned in California

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/10/26 at 1:40:30 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

12/01/2006

Accident reported

- Vehicle involved in crash
- It hit a stationary object
- Airbags did not deploy



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	06/17/2025

This car has been recently serviced. That's a good thing!



History-Based Value Report

\$13,930

CARFAX Retail Value

History events affecting this vehicle's value

-  Service History
-  Personal Vehicle
-  Accident Reported
-  Open Recall



Additional History

Not all accidents / issues are reported to CARFAX

	 Owners 1-2	 Owner 3	 Owner 4
Total Loss No total loss reported to CARFAX.	 No Issues Reported	 No Issues Reported	 No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	 No Issues Reported	 No Issues Reported	 No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	 No Issues Reported	 No Issues Reported	 No Issues Reported
Odometer Check No indication of an odometer rollback.	 No Issues Indicated	 No Issues Indicated	 No Issues Indicated
Accident / Damage Accident reported: 12/01/2006.	 No Issues Reported	Accident Reported	No New Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.	 No Recalls Reported	Recall Reported	No New Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired



Title History

	 Owners 1-2	 Owner 3	 Owner 4
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	No Problem	No Problem	No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	No Problem	No Problem	No Problem



Ownership History

The number of owners is estimated

	 Owners 1-2	 Owner 3	 Owner 4
Year purchased	2002	2005	2024
Type of owner	Personal	Personal	Personal
Estimated length of ownership	3 years	1 yr. 8 mo.	1 yr. 7 mo.
Owned in the following states/provinces	Florida, Florida	California	California
Estimated miles driven per year	See Details	4,513/yr	---
Last reported odometer reading	44,900	61,808	62,115



Detailed History



Owner 1

Purchased: 2002

Personal Vehicle

Date	Mileage	Source		Comments
08/18/2001		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews	✕	Vehicle serviced Engine cleaned Front brakes replaced Horn replaced
03/07/2002		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews	✕	Vehicle serviced Battery/charging system checked Battery charged Battery replaced CD player replaced Throttle valve/housing replaced
06/29/2002		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews	✕	Vehicle serviced Recommended maintenance performed Cooling system serviced Engine cleaned Front brakes replaced Horn replaced Lug nut(s)/bolt(s) replaced
07/08/2002		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews	✕	Vehicle serviced Emblem replaced One tire balanced One tire mounted Two tires balanced Two tires mounted
07/30/2002		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews	✕	Vehicle serviced Pre-delivery inspection completed A/C refrigerant recharged Brake light switch replaced Cooling system bled Front strut bearing(s) replaced Safety inspection performed Steering/suspension checked
08/17/2002		Florida Motor Vehicle Dept. Lake Worth, FL		First owner reported Titled or registered as personal vehicle
09/07/2002		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews	✕	Vehicle serviced Brake light switch replaced
10/11/2002		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews	✕	Vehicle serviced
08/19/2003		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews	✕	Vehicle serviced Oil and filter changed
09/25/2003		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews	✕	Vehicle serviced Pre-delivery inspection completed Brake fluid flushed/changed Front door trim panel replaced/repared Hood latch replaced Tire(s) balanced Two tires balanced Two tires mounted Vehicle washed/detailed



Owner 2
Purchased: 2003

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
12,863 mi/yr

Date	Mileage	Source	Comments
------	---------	--------	----------

09/27/2003	20,251	Florida Motor Vehicle Dept. North Palm Beach, FL		Odometer reading reported
10/07/2003		Florida Motor Vehicle Dept. North Palm Beach, FL		Title issued or updated New owner reported Loan or lien reported
01/13/2004	23,968	Service Facility		Vehicle serviced
02/11/2004		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews		Vehicle serviced Anti-theft/keyless remote(s) replaced Interior light bulb(s) replaced
02/12/2004		Florida Motor Vehicle Dept. North Palm Beach, FL		Registration issued or renewed Titled or registered as personal vehicle Loan or lien reported Vehicle color noted as Black
07/16/2004		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews		Vehicle serviced Recommended maintenance performed 30,000 mile service performed Engine cleaned Left sunvisor replaced Oil filler tube replaced Two tires balanced Two tires mounted
12/31/2004		Braman Motorcars of Palm Beach West Palm Beach, FL 561-684-6666 ★ 4.3 / 5.0 76 Verified Reviews		Vehicle serviced Steering lock replaced
01/28/2005		Florida Motor Vehicle Dept. North Palm Beach, FL		Registration issued or renewed Titled or registered as personal vehicle Loan or lien reported Vehicle color noted as Black
08/25/2005	44,850	Auto Auction		Listed as a dealer vehicle Vehicle sold
Millions of used vehicles are bought and sold at auction every year.				
08/30/2005	44,900	Dealer Inventory		Vehicle offered for sale
10/18/2005		Warrantech Automotive, Inc. Walnut Grove, CA		Service contract issued



Owner 3
Purchased: 2005

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
4,513 mi/yr

Date	Mileage	Source		Comments
10/28/2005		California Motor Vehicle Dept. Walnut Grove, CA		Title issued or updated New owner reported
11/14/2005	46,046	California Inspection Station		Passed emissions inspection
02/23/2006	46,128	California Motor Vehicle Dept. Walnut Grove, CA		Title issued or updated Registration updated when owner moved the vehicle to a new location
12/01/2006		Damage Report		Accident reported Vehicle involved in crash It hit a stationary object Airbags did not deploy

04/20/2007	52,647	Porsche Rocklin Rocklin, CA 916-625-8300 ★ 4.8 / 5.0 323 Verified Reviews ♥ 3,268 Customer Favorites		Vehicle serviced
05/03/2007	52,661	Porsche Rocklin Rocklin, CA 916-625-8300 ★ 4.8 / 5.0 323 Verified Reviews ♥ 3,268 Customer Favorites		Vehicle serviced
06/28/2007		Dealer Inventory		Vehicle sold
11/16/2007	54,247	California Inspection Station		Passed emissions inspection
11/02/2009	56,238	California Inspection Station Walnut Grove, CA		Passed emissions inspection
11/12/2011	56,914	California Inspection Station Elk Grove, CA		Passed emissions inspection
11/12/2013	57,186	California Inspection Station Sacramento, CA		Passed emissions inspection
11/07/2015	57,512	California Inspection Station		Passed emissions inspection
10/27/2017	58,594	California Inspection Station		Passed emissions inspection
11/06/2019	59,456	California Inspection Station		Passed emissions inspection
10/29/2021	59,707	California Inspection Station		Passed emissions inspection
08/17/2022	59,757	Morris Motors Walnut Grove, CA 916-776-2600 ★ 5.0 / 5.0 40 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced Recommended maintenance performed Air filter replaced Cabin air filter replaced/cleaned Drive belt(s) replaced Oil and filter changed Serpentine belt replaced Windshield washer checked
08/25/2022		Porsche Cars North America		Manufacturer Safety recall issued Recall #ANB4 RETROFIT SEALING CAP ON FRONT LEFT AND RIGHT MAIN HEADLAMP Click here or call 1-800-PORSCHE to locate an authorized Porsche dealer near you.  Learn more about this recall

Description: On the affected vehicles, it is possible that a sealing cap, which prevents the horizontal adjustment of the main headlights, was not fitted during vehicle assembly. If this is the case, certain legal requirements in the USA and Canada markets are not met. In order to bring the main headlights into compliance with the legal requirements, the installation of the sealing cap must be checked and, if necessary, a sealing cap must be retrofitted to the adjusting screw for the horizontal adjustment of the headlights.

It is possible that a sealing cap, which prevents the horizontal adjustment of the main headlights, was not fitted during vehicle assembly.

Remedy: The installation of the sealing cap must be checked and, if necessary, a sealing cap must be retrofitted to the adjusting screw for the horizontal adjustment of the headlights.

08/26/2022		Morris Motors Walnut Grove, CA 916-776-2600 ★ 5.0 / 5.0 40 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced A/C system checked A/C refrigerant recharged A/C service valves replaced
09/20/2022	59,957	Morris Motors Walnut Grove, CA 916-776-2600 ★ 5.0 / 5.0 40 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced Brake fluid flushed/changed Brake master cylinder replaced/repaired Front brake hose(s) replaced Headlight bulb(s) replaced
10/20/2023	61,471	Morris Motors Walnut Grove, CA 916-776-2600 ★ 5.0 / 5.0 40 Verified Reviews ♥ 7 Customer Favorites		Vehicle serviced
06/06/2024	61,628	California Inspection Station		Passed emissions inspection
06/11/2024	61,633	Future Ford Lincoln of Roseville Roseville, CA 916-786-3673 ★ 4.7 / 5.0 1,459 Verified Reviews ♥ 966 Customer Favorites		Vehicle serviced Brakes checked Emissions inspection performed Oil and filter changed Safety inspection performed
06/20/2024	61,690	Online Listing		Vehicle offered for sale
07/11/2024		Auto Auction		Vehicle sold
09/16/2024	61,808	California Inspection Station		Passed emissions inspection



Owner 4
Purchased: 2024

Personal Vehicle

Date	Mileage	Source	Comments
09/16/2024	61,810	California Motor Vehicle Dept. Santa Rosa, CA	Odometer reading reported
10/01/2024		California Motor Vehicle Dept. Santa Rosa, CA	Title issued or updated New owner reported
11/13/2024	61,944	Hammond Autowerks Santa Rosa, CA 707-538-4325 ★ 5.0 / 5.0 76 Verified Reviews ♥ 22 Customer Favorites	 Vehicle serviced Battery/charging system checked Battery replaced Brakes checked Oil and filter changed Right airbag assembly replaced Tire condition and pressure checked Window regulator(s) replaced
12/19/2024	61,962	Hammond Autowerks Santa Rosa, CA 707-538-4325 ★ 5.0 / 5.0 76 Verified Reviews ♥ 22 Customer Favorites	 Vehicle serviced Radio removed Tire condition and pressure checked
01/13/2025	61,963	Hammond Autowerks Santa Rosa, CA 707-538-4325 ★ 5.0 / 5.0 76 Verified Reviews ♥ 22 Customer Favorites	 Vehicle serviced Battery replaced

02/05/2025

Hammond Autowerks
Santa Rosa, CA
707-538-4325



Vehicle serviced

★ 5.0 / 5.0 76 Verified Reviews
♥ 22 Customer Favorites

06/17/2025

62,115

Hammond Autowerks
Santa Rosa, CA
707-538-4325



Vehicle serviced

★ 5.0 / 5.0 76 Verified Reviews
♥ 22 Customer Favorites

Air filter checked
Battery/charging system checked
Brakes serviced
Hood adjusted
Oil and filter changed
Tire condition and pressure checked
Transmission filter replaced
Transmission fluid changed

Have Questions? Please visit our Help Center at www.carfax.com.



Glossary

Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/10/26 at 1:40:30 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: facebook.com/CARFAX [@CARFAXinc](https://twitter.com/CARFAXinc) [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
5/10/26 1:40:30 PM (CDT)

Hammond Autowerks

4349 B Montgomery Drive

Santa Rosa, CA. 95405

Phone: (707)-538-4325

hammondautowerks.com | hammondautowerks@sonic.net

Invoice # 035153

Original Est # 76179

BAR #ARD00258579

EPA #CAL000405349

Invoice

Paid Balance Due: \$0.00

Santa Rosa, CA 95409

Cellular:

Home:

2001 Porsche - Boxster

2.7L, H6 (164CI) VIN(A)

VIN: WP0CA2985 1U623039

Odometer: In 61,694

License Plate: 5ZQA297 CA

Color: Black

Unit: 986

Work Complete: 02/05/2025

Service Advisor: Sam Hammond

Customer ID: 6671

Printed Date: 05/11/2026

Type	Description	Qty/Hr	Sale	Total
Job Title				\$693.28
Part	Coco Mats - Driver and Passenger - Black Natural	1.00	\$353.21	\$353.21
Part	Hub Cap for Alloy Wheel (Concave Plastic Type) Silver w/Colored Crest	4.00	\$69.62	\$278.48
Parts: \$631.69		Labor: \$0.00	Tax: \$61.59	Total: \$693.28

Thank you for allowing us to service your vehicle. We appreciate your patronage.
Warranty on parts and labor is one year or 12,000 miles whichever comes first, unless noted otherwise.
Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Incidental costs incurred (hotel, towing, rental, etc. will not be covered.

Labor	\$0.00
Parts	\$631.69
Subtotal	\$631.69
Taxes	\$61.59
Order Total:	\$693.28

Payment

Check Paid \$693.28 on 2/5/2025 Transaction: 5675

Signature _____

Date _____

Time _____

Hammond Autowerks

4349 B Montgomery Drive

Santa Rosa, CA. 95405

Phone: (707)-538-4325

hammondautowerks.com | hammondautowerks@sonic.net

Invoice # 036121

Original Est # 77329

BAR #ARD00258579

EPA #CAL000405349

Invoice**Paid Balance Due: \$0.00**

Santa Rosa, CA 95409

Cellular: _____

Home: _____

2001 Porsche - Boxster

2.7L, H6 (164CI) VIN()

VIN: WP0CA2985 1U623039

Odometer: In 62,115

License Plate: 5ZQA297 CA

Color: Black

Unit: 986

Work Complete: 06/16/2025

Service Advisor: Marc Brady

Customer ID: 6671

Printed Date: 05/11/2026

Type	Description	Qty/Hr	Sale	Total
Perform Basic Service *				\$221.92
Labor	Perform Basic Service * All lights work properly. Wipers streak. Battery tested 'Good Recharge'(936/760CCA). Air Filter is marginal. Brake Fluid moisture tested 1.3%. Drive Belt has no visible cracks or wear. Tires: Front 7mm(with 6mm inner tread) Rear 6mm(with 5.5mm inner tread). Brake Pad wear Front 7mm Rear 6mm. Rear Right Outer Axle boot is leaking grease. Engine Oil Pan gasket seeping. Rear Left Inner Axle boot is leaking grease. All shocks are weak. **NOTE-front under panel is broken.	0.50 hr		\$100.00
Note	* Includes: Oil and filter change, basic brake inspection and fluid testing (rotor measuring may be extra), lamp inspection and bulb replacement (most vehicles), suspension inspection, basic battery inspection and testing, top off washer fluid, check all fluids (if applicable), check wiper blades, check tire wear, check and adjust spare tire pressure, check engine air and cabin filters (on most vehicles), check for leaks, check drive belt.			
Labor	Set Tire Pressures to specifications Tire pressures have been set to specifications: 29 psi Front, 36 psi Rear	0.00 hr		\$0.00
Labor	Scan car for codes Scanned vehicle and saved report. No faults in engine module. No warning slight son at this time.	0.00 hr		\$0.00
Labor	If possible - check spare tire Vehicle is not equipped with spare tire.	0.00 hr		\$0.00
Part	Oil Filter Kit	1.00	\$27.23	\$27.23
Part	Engine Oil	9.30	\$8.99	\$83.61

Parts: \$110.84

Labor: \$100.00

Tax: \$11.08

Total: \$221.92

Per customer, inspect motor oil for any metallic residue for peace of mind regarding IMS bearing; Ch **\$0.00**

Labor	Per customer, inspect motor oil for any metallic residue for peace of mind regarding IMS bearing; Check and advise; Took small sample of engine oil, during service, inspected for metallic residue, found engine oil dirty, but no signs of metallic debris.	0.00 hr		\$0.00
-------	---	---------	--	--------

Parts: \$0.00

Labor: \$0.00

Tax: \$0.00

Total: \$0.00

TRANSMISSION OIL FILTER - Remove & Replace **\$799.54**

Labor	TRANSMISSION OIL FILTER - Remove & Replace Raised vehicle and removed under panel. Drained transmission fluid. Removed rear sway bar. Removed transmission pan, placed pan in parts washer to be cleaned at this time. Removed and replaced transmission oil filter. Using new gasket, re-installed transmission pan, and torqued to specification. Filled transmission fluid, started vehicle, let transmission get to operating temperature, and set oil level. Test drove vehicle.	3.00 hr		\$600.00
Part	AT Filter	1.00	\$57.31	\$57.31
Part	AT Pan Gasket	1.00	\$37.57	\$37.57
Part	Phillips 66 - Versatrans LV - ATF	6.00	\$12.82	\$76.92

Type	Description	Qty/Hr	Sale	Total
TRANSMISSION OIL FILTER - Remove & Replace [Continued]				\$799.54
Part	Brake cleaner	1.00	\$9.60	\$9.60
Parts:	\$181.40	Labor: \$600.00	Tax: \$18.14	Total: \$799.54
HOOD SHOCKS OR STRUTS - Remove & Replace - Both				\$86.04
Labor	HOOD SHOCKS OR STRUTS - Remove & Replace - Both Removed and replaced front hood struts.	0.50 hr		\$0.00
Part	Hood Strut	2.00	\$39.11	\$78.22
Parts:	\$78.22	Labor: \$0.00	Tax: \$7.82	Total: \$86.04
Per customer, Odometer screen is illegible; check and advise				\$0.00
Labor	Per customer, Odometer screen is illegible; check and advise Verified odometer screen is illegible, screen is pixleated.	0.20 hr		\$0.00
Parts:	\$0.00	Labor: \$0.00	Tax: \$0.00	Total: \$0.00
Order				\$5.00
Misc	Hazardous Materials			\$5.00
Total:	\$5.00	Tax: \$0.00		

Thank you for allowing us to service your vehicle. We appreciate your patronage.
 Warranty on parts and labor is one year or 12,000 miles whichever comes first, unless noted otherwise.
 Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Incidental costs incurred (hotel, towing, rental, etc. will not be covered.

Labor	\$700.00
Parts	\$370.46
Hazardous Materia	\$5.00
Subtotal	\$1,075.46
Taxes	\$37.05
Order Total:	\$1,112.51

Payment

Check Paid \$1112.51 on 6/17/2025 Transaction: 5810

Signature _____ Date _____ Time _____

Hammond Autowerks

4349 B Montgomery Drive

Santa Rosa, CA. 95405

Phone: (707)-538-4325

hammondautowerks.com | hammondautowerks@sonic.net

Invoice # 035152

Original Est # 76157

BAR #ARD00258579

EPA #CAL000405349

Invoice**Paid** Balance Due: **\$0.00**

Santa Rosa, CA 95409

Cellular:

Home:

2001 Porsche - Boxster

2.7L, H6 (164CI) VIN(A)

VIN: WP0CA2985 1U623039

Odometer: In 61,963

License Plate: 5ZQA297 CA

Color: Black

Unit: 986

Work Complete: 01/13/2025

Service Advisor: Sam Hammond

Customer ID: 6671

Printed Date: 05/11/2026

Type	Description	Qty/Hr	Sale	Total
Job Title				\$0.00
Labor	BATTERY - Remove & Replace - WARRANTY Customer having starting issues, car has been being driven regularly. Removed and replaced battery under warranty, previous battery was testing to replace.	0.60 hr		\$0.00
Part	Battery - WARRANTY Size: 9.5L 6.75W 7.5H	1.00	\$0.00	\$0.00
Parts: \$0.00		Labor: \$0.00		Tax: \$0.00
		Total: \$0.00		

Thank you for allowing us to service your vehicle. We appreciate your patronage.
Warranty on parts and labor is one year or 12,000 miles whichever comes first, unless noted otherwise.
Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Incidental costs incurred (hotel, towing, rental, etc. will not be covered.

Labor	\$0.00
Parts	\$0.00
Subtotal	\$0.00
Taxes	\$0.00
Order Total:	\$0.00

Signature _____

Date _____

Time _____

Hammond Autowerks

4349 B Montgomery Drive

Santa Rosa, CA. 95405

Phone: (707)-538-4325

hammondautowerks.com | hammondautowerks@sonic.net

Invoice # 034820

Original Est # 75784

BAR #ARD00258579

EPA #CAL000405349

Invoice**Paid Balance Due: \$0.00**

Santa Rosa, CA 95409

Cellular

Home:

2001 Porsche - Boxster

2.7L, H6 (164CI) VIN(A)

VIN: WP0CA2985 1U623039

Odometer: In 61,962

License Plate: 5ZQA297 CA

Color: Black

Unit: 986

Work Complete: 12/19/2024

Service Advisor: Sam Hammond

Customer ID: 6671

Printed Date: 05/11/2026

Type	Description	Qty/Hr	Sale	Total
Job Title				\$2,350.50
Labor	RADIO CHASSIS - Remove & Install for Repair Original radio removed from vehicle, dash brackets, frame, and other components replaced to fit new double DIN stereo, new stereo installed and tested.	0.50 hr		\$100.00
Labor	Install additional stereo components USB, Phone, and Bluetooth peripheral for new stereo installed in cubby under stereo.	0.50 hr		\$100.00
Part	PCCM+ Stereo - Porsche	1.00	\$1,475.01	\$1,475.01
Part	Frame - Black	1.00	\$8.33	\$8.33
Part	Frame	1.00	\$250.63	\$250.63
Part	Cubby	1.00	\$79.50	\$79.50
Part	Metal Retaining Frame	1.00	\$79.49	\$79.49
Part	Button Bezel - Left and Right	1.00	\$66.49	\$66.49
Labor	Set Tire Pressures to specifications Tire pressures have been set to specifications:	0.00 hr		\$0.00
	29 psi Front, 36 psi Rear			
Note	Note: Found Power steering reservoir empty, saw signs of leak between upper and lower PS reservoir, suggest replacing soon.			

Parts: \$1,959.45 Labor: \$200.00 Tax: \$191.05 Total: \$2,350.50

Thank you for allowing us to service your vehicle. We appreciate your patronage.
Warranty on parts and labor is one year or 12,000 miles whichever comes first, unless noted otherwise.
Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Incidental costs incurred (hotel, towing, rental, etc. will not be covered.

Labor	\$200.00
Parts	\$1,959.45
Subtotal	\$2,159.45
Taxes	\$191.05
Order Total:	\$2,350.50

Payment

Check Paid \$2350.50 on 12/19/2024 Transaction: 5769

Signature _____

Date _____

Time _____

Hammond Autowerks

4349 B Montgomery Drive

Santa Rosa, CA. 95405

Phone: (707)-538-4325

hammondautowerks.com | hammondautowerks@sonic.net

Invoice # 034774

Original Est # 75719

BAR #ARD00258579

EPA #CAL000405349

Invoice**Paid Balance Due: \$0.00**

Santa Rosa, CA 95409
 Cellular
 Home: 707

2001 Porsche - Boxster
 2.7L, H6 (164CI) VIN(A)
 VIN: WP0CA2985 1U623039
 Odometer: In 61,944

License Plate: 5ZQA297 CA
 Color: Black
 Unit: 986

Work Complete: 11/12/2024
 Service Advisor: Sam Hammond
 Customer ID: 6671
 Printed Date: 05/11/2026

Type	Description	Qty/Hr	Sale	Total
Job Title				\$1,721.44
Labor	Perform Basic Service *	0.50 hr		\$100.00
	Tire tread depth: LF 7mm with 6 mm edges. RF 6mm. LR & RR 6mm with 5mm edges. Front & rear brake pads are at 6mm. Brake fluid measures 1% moisture content. Battery test suggests replacing battery. Battery tested at 12.28v and measured 373cca out of 730cca. Front trunk struts are weak. Oil pan seeps. Rear inner axle seal are moist. Belt is ok. Windshield wiper blades are OK.			
Note	* Includes: Oil and filter change, basic brake inspection and fluid testing (rotor measuring may be extra), lamp inspection and bulb replacement (most vehicles), suspension inspection, basic battery inspection and testing, top off washer fluid, check all fluids (if applicable), check wiper blades, check tire wear, check and adjust spare tire pressure, check engine air and cabin filters (on most vehicles), check for leaks, check drive belt.			
Labor	Set Tire Pressures to specifications	0.00 hr		\$0.00
	Tire pressures have been set to specifications:			
	29 psi Front, 36 psi Rear			
Labor	Scan car for codes	0.00 hr		\$0.00
	Codes have been scanned and sent to email.			
Labor	If possible - check spare tire	0.00 hr		\$0.00
	Spare tire has been set to 60 psi.			
Part	Oil Filter Kit	1.00	\$27.23	\$27.23
Part	Engine Oil	9.30	\$8.99	\$83.61
Labor	Per customer, passenger window is stuck down; check and advise	1.00 hr		\$200.00
	Window lifter has failed, new lifter is needed			
Labor	BATTERY - Remove & Replace - [Includes: Test.]	0.60 hr		\$120.00
	Removed and replaced battery. Using Autologic, scanned vehicle, and cleared all related faults.			
Part	Battery Size: 9.5L 6.75W 7.5H	1.00	\$284.95	\$284.95
Labor	WINDOW REGULATOR - Remove & Replace - One	2.20 hr		\$440.00
	Removed passenger side door panel. Removed passenger side airbag assembly. Removed passenger side speaker. Removed dust cover. Removed passenger side window regulator. Removed window motor from old regulator and installed in new window regulator. Installed new window regulator, adjusted window as needed. Re-assembled in reverse order. Using Autologic, scanned vehicle, and cleared related faults.			
Part	Window Regulator-Front Right	1.00	\$389.12	\$389.12

Parts: \$784.91 Labor: \$860.00 Tax: \$76.53 Total: \$1,721.44

Order **-\$195.00**

Misc Hazardous Materials \$5.00
 Disc ***Discount*** -\$200.00
 \$200.00 off labor

Total: -\$195.00 Tax: \$0.00

Thank you for allowing us to service your vehicle. We appreciate your patronage.
Warranty on parts and labor is one year or 12,000 miles whichever comes first, unless noted otherwise.
Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Incidental costs incurred (hotel, towing, rental, etc. will not be covered.

Labor	\$860.00
Parts	\$784.91
Discount	-\$200.00
Hazardous Materia	\$5.00
Subtotal	\$1,449.91
Taxes	\$76.53
Order Total:	\$1,526.44

Payment

Check Paid \$1526.44 on 11/13/2024 Transaction: 5753

Signature _____ Date _____ Time _____
Copyright © Mitchell Repair Information Company LB1124I 2/2



Hammond Autowerks
4349 B Montgomery Drive
Santa Rosa, CA. 95405
Phone: 707-538-4325

INVOICE

34774

Org. Est. # 075719
BAR #ARD00258579
EPA #CAL000405349

INVOICE

Printed Date: 11/13/2024

Work Completed: 11/12/2024

5
Santa Rosa, CA 95409
Home Cell

2001 Porsche - Boxster - 2.7L, H6 (164CI) VIN(A)

Lic # : 5ZQA297

Odometer In : 61944

VIN # : WP0CA2985 1U623039

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Oil Filter Kit 996 107 225 60	1.00	27.23	27.23	Perform Basic Service *	100.00
Engine Oil M5w40	9.30	8.99	83.61	Tire tread depth: LF 7mm with 6 mm edges. RF 6mm. LR & RR 6mm with 5mm edges. Front & rear brake pads are at 6mm. Brake fluid measures 1% moisture content. Battery test suggests replacing battery. Battery tested at 12.28v and measured 373cca out of 730cca. Front trunk struts are weak. Oil pan seeps. Rear inner axle seal are moist. Belt is ok. Windshield wiper blades are OK.	
Battery Size: 9.5L 6.75W 7.5H MTX-48/H6	1.00	284.95	284.95	* Includes: Oil and filter change, basic brake inspection and fluid testing (rotor measuring may be extra), lamp inspection and bulb replacement (most vehicles), suspension inspection, basic battery inspection and testing, top off washer fluid, check all fluids (if applicable), check wiper blades, check tire wear, check and adjust spare tire pressure, check engine air and cabin filters (on most vehicles), check for leaks, check drive belt.	
Window Regulator-Front Right 996 542 076 05	1.00	389.12	389.12	Set Tire Pressures to specifications Tire pressures have been set to specifications: 29 psi Front, 36 psi Rear Scan car for codes Codes have been scanned and sent to email. If possible - check spare tire Spare tire has been set to 60 psi. Per customer, passenger window is stuck down; check and advise Window lifter has failed, new lifter is needed	n/c n/c n/c 200.00
				BATTERY - Remove & Replace - [Includes: Test.] Removed and replaced battery. Using Autologic, scanned vehicle, and cleared all related faults.	120.00
				WINDOW REGULATOR - Remove & Replace - One Removed passenger side door panel. Removed passenger side airbag assembly. Removed passenger side speaker. Removed dust cover. Removed passenger side window regulator. Removed window motor from old regulator and installed in new window regulator. Installed new window regulator, adjusted window as needed. Re-assembled in reverse order. Using Autologic, scanned vehicle, and cleared related faults.	440.00
				[Discount] \$200.00 off labor	
				Hazardous Materials	5.00



Hammond Autowerks
4349 B Montgomery Drive
Santa Rosa, CA. 95405
Phone: 707-538-4325

INVOICE

34774

Org. Est. # 075719
BAR #ARD00258579
EPA #CAL000405349

INVOICE

Printed Date: 11/13/2024

Work Completed: 11/12/2024

Santa Rosa, CA 95409
Home

2001 Porsche - Boxster - 2.7L, H6 (164CI) VIN(A)

Lic # : 5ZQA297

Odometer In : 61944

VIN # : WPOCA2985 1U623039

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----

Org. Estimate 440.18 Revisions 1,350.42 Current Estimate 1,790.60

Revision # 1, Previous Estimate Amount: 440.18, Additional Cost: 1350.42, Revised Estimate: 1790.60, Parts: \$674.07 Labor: \$560.00 Sublet: \$0.00
Taxes & Fees: \$116.35 Authorized by - Allen, Michael Date - 11/11/2024 Time - 6:02 PM, Initiated By - Shop, Written By - Hammond, Sam

Labor:	860.00
Parts:	784.91
HazMat:	5.00
Discount:	-200.00
SubTotal:	1,449.91
Tax:	76.53
Total:	1,526.44
Bal Due:	\$0.00

[Payments - Check (#5753) - \$1,526.44]

Vehicle Received: 11/11/2024

Customer Number : 6671

Thank you for allowing us to service your vehicle. We appreciate your patronage.

Warranty on parts and labor is one years or 12,000 miles whichever comes first, unless noted otherwise. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Incidental costs incurred (hotel, towing, rental, etc. will not be covered.

Signature _____ Date _____

Visit us on the web: www.hammondautowerks.com

Email Address: hammondautowerks@sonic.net

Service Advisor: Hammond, Sam, Tech: Please Select, Technician: Hammond, C

Page 2 of 2

Copyright (c) 2024 Mitchell Repair Information Company, LLC invhrs 5.12.21kr