


This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/12/19 at 7:37:25 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History The number of owners is estimated	🚨 Owner 1	a Owner 2	A Owner 3
Year purchased	2013	2016	2019
Type of owner	Personal lease	Personal	Personal
Estimated length of ownership	2 yrs. 2 mo.	2 yrs. 9 mo.	2 months
Owned in the following states/provinces	California	California	California
Estimated miles driven per year	6,630/yr	6,512/yr	
Last reported odometer reading	14,352	31,089	33,000

CARFAX guarantees the information in this section	🍰 Owner 1	🍰 Owner 2	Sowner 3
Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	Guaranteed	Guaranteed	Guaranteed
	No Problem	No Problem	No Problem
Not Actual Mileage   Exceeds Mechanical Limits	Guaranteed	Guaranteed	Guaranteed
	No Problem	No Problem	No Problem



CARFAX Additional History  Not all accidents / issues are reported to CARFAX	🚨 Owner 1	Cwner 2	Cwner 3
Total Loss  No total loss reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported

4/12/2019, 5:37 PM 1 of 4

Structural Damage  No structural damage reported to CARFAX.	No Issues	No Issues	No Issues
	Reported	Reported	Reported
Airbag Deployment  No airbag deployment reported to CARFAX.	No Issues	No Issues	No Issues
	Reported	Reported	Reported
Odometer Check  No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated	No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	No Issues	No Issues	No Issues
	Reported	Reported	Reported
Manufacturer Recall  At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.	No Recalls Reported	Recall Reported	No New Recalls Reported
Basic Warranty Original warranty estimated to have expired. Interested in an extended warranty?	Warranty	Warranty	Warranty
	Expired	Expired	Expired

California

# CARFAX Detailed History

Glossary

ı	Sowner 1		Date:	Mileage:	Source:
	Purchased: Type: Where: Est. miles/year:	2013 Personal lease California 6,630/yr	11/23/2013	20	California Motor Vehicle I Glendale, CA
	Est. length owned:	11/23/13 - 2/10/16 (2 yrs. 2 mo.)	12/12/2013		California Motor Vehicle I Glendale, CA
	Low mileage!				

Comments: Odometer reading reported Dept. Title issued or updated Dept. First owner reported Titled or registered as personal lease vehicle Loan or lien reported 02/10/2016 14,352 Mercedes-Benz Vehicle sold at auction **Financial Services** 





Millions of used vehicles are bought and sold at auction every year.

Owner 2	
Purchased:	2016
Type:	Personal
Where:	California
Est. miles/year:	6,512/yr
Est. length owned:	3/24/16 -
	1/22/19
	(2 yrs. 9 m

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

less than the

industry average

of 15,000 miles per year.



Date:	Mileage:	Source:	Comments:
03/24/2016	14,370	California Motor Vehicle Dept. Vallejo, CA	Odometer reading reported
04/08/2016		California Motor Vehicle Dept. Vallejo, CA	Title issued or updated New owner reported
10/15/2016	15,071	Mercedes Benz Fairfield Fairfield, CA 707-430-0101 mercedesfairfield.co m 4.8  29 Verified Reviews	Maintenance inspection completed 10,000 mile service performed Vehicle washed/detailed Tire condition and pressure checked
01/18/2018		Mercedes-Benz USA LLC	Manufacturer Safety recall issued NHTSA #17V627 Recall #2017120024 Model 207. Model Years 2014 - 2017. Steering Column Module SCM

4/12/2019, 5:37 PM

(Ground). Electric s Status: Remedy Available

Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall

- Learn more about this recall

Description: Daimler AG (DAG), the manufacturer of Mercedes-Benz vehicles, has determined that certain MY12-17 C-Class, E-Class, E-Class Coupe vehicles (204, 207, 212 platform) have insufficient electrical grounding in the steering column components. In rare instances, if the steering column module is exposed to an electrostatic discharge, and if the steering column module clock spring is broken (due to wear), this could lead to an inadvertent deployment of the driver airbag. An inadvertent driver airbag deployment may cause a risk of injury to the driver and might increase the risk of a potential crash. A broken clock spring will illuminate the SRS warning light as well as display a warning message in the instrument cluster. An authorized Mercedes-Benz Dealer will install a sufficient ground to the steering column, and a protective ring to the steering column module.

An inadvertent driver airbag deployment may cause a risk of injury to the driver and might increase the risk of a potential crash.

Remedy: As a precautionary measure an authorized Mercedes-Benz dealer, will add sufficient grounding to the steering components on the affected vehicles.

10/17/2018	31,089	Pep Boys Vallejo, CA 707-648-1032 pepboys.com 4.0	Tire(s) balanced Tire pressure monitoring system serviced Alignment performed
01/18/2019		Mercedes-Benz USA LLC	Manufacturer Safety recall issued NHTSA #19V010 Recall #2019010001 PND TAK PSAB PHASE 4 Status: Remedy Not Yet Available  Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall
			- Learn more about this recall

Description: Mercedes-Benz USA is recalling certain MY 2010-2017 C-Class, GLK-Class, SLS-Class and E-Class Coupe Mercedes-Benz vehicles equipped with passenger-side frontal airbags affected by the defect decision of TK Holdings, Inc. ( Takata ). Under certain circumstances during a crash that necessitates frontal airbag deployment, the defect in your passenger-side frontal airbag inflator may cause the inflator to explode. A passenger-side inflator explosion during deployment could result in metal fragments striking the front passenger or other occupants, possibly causing serious injury or death.

According to Takata, in the event of an inflator explosion, metal fragments could pass through the air bag cushion material, which may result in injury or death to vehicle occupants.

Remedy: An authorized Mercedes-Benz dealer will replace the passenger-side airbag.

Owner 3	
Purchased:	2019
Type:	Persona
Where:	Californi

Date:	Mileage:	Source:	Comments:
01/22/2019	33,000	California Motor Vehicle Dept. Oakland, CA	Odometer reading reported

4/12/2019, 5:37 PM

	Est. length owned:	1/22/19 - present (2 months)	02/26/2019	California Motor Vehicle Dept. Oakland, CA	Title issued or updated New owner reported	
ı						

Have Questions? Please visit our Help Center at www.carfax.com.



View Full Glossary

### **First Owner**

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### **Manufacturer Recall**

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

## **New Owner Reported**

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

# **Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: facebook.com/CARFAX @CarfaxReports

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2019 CARFAX, Inc., a unit of IHS Markit. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838. 4/12/19 7:37:25 PM (CDT)

4 of 4 4/12/2019, 5:37 PM