



Vehicle History Report™

US \$39.99

1990 MAZDA MX-5 MIATA VIN: JM1NA3514L0111743 CONVERTIBLE 1.6L I4 F DOHC GASOLINE REAR WHEEL DRIVE		No accidents or damage reported to CARFAX	
		7 Service history records	
		26 Detailed records available	
		115,240 Last reported odometer reading	






This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 11/24/21 at 2:49:32 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Title History CARFAX guarantees the information in this section		Summary
Salvage Junk Rebuilt Fire Flood Hail Lemon		Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits		Guaranteed No Problem
GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. Register View Terms View Certificate		

Additional History Not all accidents / issues are reported to CARFAX		Summary
Total Loss No total loss reported to CARFAX.		No Issues Reported
Structural Damage No structural damage reported to CARFAX.		No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.		No Issues Reported
Odometer Check No indication of an odometer rollback.		No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.		No Issues Reported
Manufacturer Recall Check with an authorized Mazda dealer for any open recalls.		No Recalls Reported
Basic Warranty No data reported to CARFAX.		No Data Reported

Detailed History				
Date	Mileage	Source	Comments	

06/29/1989		NICB		Vehicle manufactured and shipped to original dealer
08/19/1991	43,424	California Inspection Station Los Altos, CA		Passed emissions inspection
08/26/1993	82,559	California Inspection Station Ben Lomond, CA		Failed emissions inspection - Passed emissions inspection
08/26/1997	106,985	California Inspection Station Ben Lomond, CA		Passed emissions inspection
09/03/1999	111,022	Service Facility Santa Rosa, CA		Vehicle serviced
09/03/1999		California Inspection Station Santa Rosa, CA		Passed emissions inspection
09/17/1999		California Motor Vehicle Dept. Sonoma, CA		Title issued or updated
08/27/2001	111,804	Service Facility Santa Rosa, CA		Vehicle serviced
08/27/2001		California Inspection Station Santa Rosa, CA		Passed emissions inspection
07/23/2003	112,327	Service Facility Santa Rosa, CA		Vehicle serviced
07/23/2003		California Inspection Station Santa Rosa, CA		Passed emissions inspection
08/25/2005	112,915	California Inspection Station		Passed emissions inspection
08/21/2007	113,112	California Inspection Station		Passed emissions inspection
08/24/2009	113,348	California Inspection Station Sonoma, CA		Passed emissions inspection
08/25/2011	114,022	California Inspection Station Sonoma, CA		Passed emissions inspection
08/21/2013	114,301	California Inspection Station Sonoma, CA		Failed emissions inspection
08/22/2013		Vehicle Repair Center Sonoma, CA		Vehicle serviced - Computer system repaired
08/22/2013	114,307	California Inspection Station Sonoma, CA		Passed emissions inspection
08/26/2015	114,527	Marin Subaru San Rafael, CA 415-454-9240 marinsubaru.net ★ 4.7 / 5.0 45 Verified Reviews   99 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Tire condition and pressure checked - Fluids checked
08/27/2015	114,576	California Inspection Station Sonoma, CA		Passed emissions inspection
08/23/2017	115,090	California Inspection Station		Failed emissions inspection

08/24/2017		Sonoma, CA Vehicle Repair Center Sonoma, CA	 Vehicle serviced - Computer system repaired
08/24/2017		California Inspection Station Sonoma, CA	Passed emissions inspection
08/14/2019	115,133	California Inspection Station Sonoma, CA	Passed emissions inspection
08/18/2021	115,240	Silveira Chevrolet Sonoma, CA 707-832-4474 silveirachevy.com  4.6 / 5.0 17 Verified Reviews   566 Customer Favorites	 Vehicle serviced - Tire condition and pressure checked
08/18/2021		California Inspection Station Sonoma, CA	Passed emissions inspection

Have Questions? Please visit our Help Center at www.carfax.com.



Glossary

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://www.facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2021 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved.
11/24/21 2:49:32 PM (CST)